Submit 3 Copies to Appropriate District Office

CONDITIONS OF APPROVAL, IF ANY was to see the second of th

State of New Mexico Energy, Minerals and Natural Resources Department

OΠ.	CONSER	VATI	OND	IVISION
W	COLIDIA	1177	· · · ·	

451	
Form C-103 Revised 1-1-89	

DISTRICT P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088			WELL API NO.
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico	5. Indicate Type of Lease STATE XX FEE	
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	6. State Oil & Gas Lease No. LG 7990		
(DO NOT USE THIS FORM FOR PR	ICES AND REPORTS ON WE OPOSALS TO DRILL OR TO DEEPER PROOR. USE "APPLICATION FOR PEC-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name Wolf AHF State	
1. Type of Well:			WOII AIR State
OIL WELL X 2. Name of Operator	OTHER		8. Well No.
YATES PETROLEUM CORE	PORATION $\sqrt{(505)}$ 7	48-1471	9. Pool name or Wildcat
3. Address of Operator	· · · · · · · · · · · · · · · · · · ·	3210	Wildcat Precambrian
105 South 4th St., A	Artesia, New Mexico 88	7210	
Unit Letter A: 66	O Feet From The north	Line and66	60 Feet From The east Line
		07-	NMPM Chaves County
Section 13	Township 9S //////// 10. Elevation (Show whether	Range Z/e er DF, RKB, RT, GR, etc.)	V/////////////////////////////////////
<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>	/////// 3874 '	GR	
Check	Appropriate Box to Indicate	Nature of Notice, F	Report, or Other Data
	NTENTION TO:	SUE	BSEQUENT REPORT OF:
	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK	CHANGE PLANS	COMMENCE DRILLIN	NG OPNS. X PLUG AND ABANDONMENT
TEMPORARILY ABANDON	CHANGE PDANS	CASING TEST AND C	
PULL OR ALTER CASING	_	n 1	CEMENT GOS C
OTHER:		OTHER:	
12. Describe Proposed or Completed Op	erations (Clearly state all pertinent details	, and give pertinent dates, inc	cluding estimated date of starting any proposed
Spudded 11: 45 AM 2-Rollins, NMOCD, Arte Ran 30 joints 8-5/8" set 1167'. Cemented CaC12, (yield 1.98, PD 10:45 PM 3-3-90.	sia, NM, of spud. Rest 24# J-55 ST&C casing s w/750 sx Pacesetter L: wt 12.4). Tail in w/20 Bumped plug to 800 ps	set 1208'. Guid ite w/5#/sx Gils 00 sx Class C w/ i, float held ok	conductor. Notfified Betty Lt" hole 11:00 PM 3-2-90. He shoe set 1208', insert float sonite, 1/2#/sx Celloseal + 3% /2% CaCl2 (yield 1.32, wt 14.8). Cay. Circulated 100 sx to pit. Lested to 1200 psi for 30 mins, OK. Informed they would not observe
SKNATTORE LANGE Juanita)	e and belief. THE Production	TELEPHONE NO. 505/748-14
MI	KE WILLIAMS IPERVISOR, DISTRI CT II	. TITLE	MAR 2 1 1990