

c/sf

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		3a. Area Code & Phone No. 505/748-1471		5. LEASE DESIGNATION AND SERIAL NO. NM 3051	
2. NAME OF OPERATOR YATES PETROLEUM CORPORATION		8. FARM OR LEASE NAME Hewitt IM Federal		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR 105 South 4th St., Artesia, NM 88210		9. WELL NO. 3		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FSL & 660' FWL, Sec. 21-T6S-R25E		10. FIELD AND POOL, OR WILDCAT Pecos Slope Abo		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Unit L, Sec. 21-6S-25E	
14. PERMIT NO. 30-005-62782		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3738' GR		12. COUNTY OR PARISH Chaves	
				13. STATE NM	

AUG -1 '90

A.C.D. ARTESIA, OFFICE

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) Surface; Intermediate Casing

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Spudded 17 1/2" hole 11:15 AM 6-16-90 with Frank's Rathole. Notified BLM, Roswell, NM of spud. Ran 19 joints 13-3/8" J-55 54.5# casing set 805'. Guide shoe set 805', insert float set 760'. Cemented w/650 sx Pacesetter Lite w/1/4# Celloseal + 5# Gilsonite, 2% CaCl2 (yield 1.98, wt. 12.4). Tailed in w/200 sx Class C w/2% CaCl2 (yield 1.32, wt 14.8). PD 8:44 AM 6-21-90. Bumped plug to 550 psi, float held okay. Circulated 67 sx to pit. WOC. Drilled out 2:45 AM 6-22-90. WOC 18 hrs. Cut off and weld on flow nipple. Note: Not witnessed by BLM - Roswell, verbal approval to cement obtained from Mr. James Brasfield, BLM, Roswell, NM. Ran 34 joints 8-5/8" 24# J-55 casing set 1497'. Guide shoe set 1497', insert float set 1452'. Cemented w/425 sx 65/35 Poz C w/6% Bentonite + 1/4#/sx Flocele, 5#/sx Gilsonite, 3% CaCl2 (yield 1.92, wt 12.7). Tailed in w/200 sx Class C w/2% CaCl2 (yield 1.32, wt 14.8). PR 1:18 PM 6-23-90. Bumped plug to 900 psi, float held okay. Circulated 73 sacks cement. WOC. Drilled out 7:30 AM 6-24-90. WOC 18 hrs and 12 mins. NU and tested to 1000 psi for 30 minutes, OK. Reduced hole to 7-7/8" and resumed drilling. NOTE: Notified Armando, BLM, Roswell, NM - did not witness.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature]

TITLE Production Supvr.

DATE 6-26-90

(This space for Federal or State office use)

APPROVED BY _____

TITLE _____

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD
PETER W. CHESTER
DATE _____

JUL 30 1990

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA

*See Instructions on Reverse Side