	$C1^{2}$
Submit 3 Copies To Appropriate District  State of New Mexico	Form C-103
Office District I 1625 N. French Dr. Hobbs NM 8890	es Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 8830	WELL API NO. 30-005-62794
District II 1301 W. Grand Avenue, Artesia, 1888210CD ARTE CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1000 Pio Proper Pd. Artes NM 9348	STATE FEE
District IV Sainta Fe, INVI 6/303	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 8 505	L-794
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name:
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Hanlad State
PROPOSALS.)  1. Type of Well:	
Oil Well Gas Well Other Salt Water Disposal	
2. Name of Operator HANSON OPERATING COMPANY, INC.	8. Well No. #1 - SWD
2 Address of Onesastav	0 Pool name or Wildoot
P. O. Box 1515, Roswell, NW 88202-1515	Diablo Fussleman
4. Well Location	
Unit Letter_K : 1980 feet from the South line at	nd 2310 feet from the West line
Section 16 Township 10S Range 27E  10. Elevation (Show whether DR, RKB, RT,	NMPM Chaves County
3889' GR	Un, etc.)
11. Check Appropriate Box to Indicate Nature of No.	otice, Report or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL	L WORK ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMEN	CE DRILLING OPNS. PLUG AND
DULL OR ALTER CASING MULTIPLE CASING T	ABANDONMENT -
PULL OR ALTER CASING MULTIPLE CASING T	EST AND
COMPLETION CEMENT	EST AND SOB
OTHER: COMPLETION CEMENT.	EST AND JOB  Pit Closure
COMPLETION CEMENT	Pit Closure  ails, and give pertinent dates, including estimated date
OTHER:  COMPLETION  CEMENT  OTHER:  OTHER:  CEMENT  OTHER:	Pit Closure  ails, and give pertinent dates, including estimated date
OTHER:  OTHER:	Pit Closure  ails, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion  ndy Marley.
OTHER:  OTHER:	Pit Closure  ails, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion  ndy Marley.
OTHER:  OTHER:	Pit Closure  ails, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion  ndy Marley.
OTHER:  OTHER:	Pit Closure  ails, and give pertinent dates, including estimated dates. Attach wellbore diagram of proposed completion andy Marley.  20' X 3' pit and disposed at Gandy Marley.
OTHER:  OTHER:  OTHER:  OTHER:  12. Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompilation.  03/07/2002: Removed 95 barrels BS&W from pit and disposed at Ga 04/01/2002: Removed 20 mill liner and contaminated soil from 15' X Covered pit and leveled area.  06/27/2002: Notified OCD of soil samplings scheduled for 7/1/2002.  07/01/2002: Samples were taken from bottom of pit area as indicated analysis was forwarded to your attention.	Pit Closure  ails, and give pertinent dates, including estimated dates. Attach wellbore diagram of proposed completion and Marley.  20' X 3' pit and disposed at Gandy Marley.  d on the attached diagram. The sampling
OTHER:  OTHER:  OTHER:  OTHER:  12. Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompilation.  03/07/2002: Removed 95 barrels BS&W from pit and disposed at Ga 04/01/2002: Removed 20 mill liner and contaminated soil from 15' X Covered pit and leveled area.  06/27/2002: Notified OCD of soil samplings scheduled for 7/1/2002.  07/01/2002: Samples were taken from bottom of pit area as indicated analysis was forwarded to your attention.  The area ground water level is 400'. A windmill which has not pumper.	Pit Closure  Pit C
OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  12. Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompilation.  03/07/2002: Removed 95 barrels BS&W from pit and disposed at Ga 04/01/2002: Removed 20 mill liner and contaminated soil from 15' X Covered pit and leveled area.  06/27/2002: Notified OCD of soil samplings scheduled for 7/1/2002.  07/01/2002: Samples were taken from bottom of pit area as indicated analysis was forwarded to your attention.	Pit Closure  Pit C
OTHER:  OTHER:  OTHER:  OTHER:  12. Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompilation.  03/07/2002: Removed 95 barrels BS&W from pit and disposed at Ga 04/01/2002: Removed 20 mill liner and contaminated soil from 15' X Covered pit and leveled area.  06/27/2002: Notified OCD of soil samplings scheduled for 7/1/2002.  07/01/2002: Samples were taken from bottom of pit area as indicated analysis was forwarded to your attention.  The area ground water level is 400'. A windmill which has not pumped due east of the location. A dirt tank which only fills with rain water is leading to the location.	Pit Closure  Pit C
OTHER:  OTHER:  OTHER:  OTHER:  12. Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompilation.  03/07/2002: Removed 95 barrels BS&W from pit and disposed at Ga 04/01/2002: Removed 20 mill liner and contaminated soil from 15' X Covered pit and leveled area.  06/27/2002: Notified OCD of soil samplings scheduled for 7/1/2002.  07/01/2002: Samples were taken from bottom of pit area as indicated analysis was forwarded to your attention.  The area ground water level is 400'. A windmill which has not pumped due east of the location. A dirt tank which only fills with rain water is leading to the location.	Pit Closure  Pit C
OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  12. Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompilation.  03/07/2002: Removed 95 barrels BS&W from pit and disposed at Ga 04/01/2002: Removed 20 mill liner and contaminated soil from 15' X Covered pit and leveled area.  06/27/2002: Notified OCD of soil samplings scheduled for 7/1/2002.  07/01/2002: Samples were taken from bottom of pit area as indicated analysis was forwarded to your attention.  The area ground water level is 400'. A windmill which has not pumped due east of the location. A dirt tank which only fills with rain water is leading to the location.	Pit Closure  Pit C
OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  12. Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompilation.  03/07/2002: Removed 95 barrels BS&W from pit and disposed at Ga 04/01/2002: Removed 20 mill liner and contaminated soil from 15' X Covered pit and leveled area.  06/27/2002: Notified OCD of soil samplings scheduled for 7/1/2002.  07/01/2002: Samples were taken from bottom of pit area as indicated analysis was forwarded to your attention.  The area ground water level is 400'. A windmill which has not pumped due east of the location. A dirt tank which only fills with rain water is leading to the location.	Pit Closure  Pit C
OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  12. Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompilation.  03/07/2002: Removed 95 barrels BS&W from pit and disposed at Ga 04/01/2002: Removed 20 mill liner and contaminated soil from 15' X Covered pit and leveled area.  06/27/2002: Notified OCD of soil samplings scheduled for 7/1/2002.  07/01/2002: Samples were taken from bottom of pit area as indicated analysis was forwarded to your attention.  The area ground water level is 400'. A windmill which has not pumped due east of the location. A dirt tank which only fills with rain water is leading to the location.	Pit Closure  ails, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion  andy Marley.  20' X 3' pit and disposed at Gandy Marley.  d on the attached diagram. The sampling  ad water in 10 or more years is located 1 mile ocated 1.5 miles north of the location. A
OTHER:  12. Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompilation.  03/07/2002: Removed 95 barrels BS&W from pit and disposed at Ga 04/01/2002: Removed 20 mill liner and contaminated soil from 15' X Covered pit and leveled area.  06/27/2002: Notified OCD of soil samplings scheduled for 7/1/2002.  07/01/2002: Samples were taken from bottom of pit area as indicated analysis was forwarded to your attention.  The area ground water level is 400'. A windmill which has not pumped due east of the location. A dirt tank which only fills with rain water is fresh water station in located 3.5 miles north of the location.	Pit Closure  ails, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion  andy Marley.  20' X 3' pit and disposed at Gandy Marley.  d on the attached diagram. The sampling  ad water in 10 or more years is located 1 mile ocated 1.5 miles north of the location. A
OTHER:  12. Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompilation.  03/07/2002: Removed 95 barrels BS&W from pit and disposed at Ga 04/01/2002: Removed 20 mill liner and contaminated soil from 15' X Covered pit and leveled area.  06/27/2002: Notified OCD of soil samplings scheduled for 7/1/2002. 07/01/2002: Samples were taken from bottom of pit area as indicated analysis was forwarded to your attention.  The area ground water level is 400'. A windmill which has not pumped due east of the location. A dirt tank which only fills with rain water is I fresh water station in located 3.5 miles north of the location.	Pit Closure  ails, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion  andy Marley.  20' X 3' pit and disposed at Gandy Marley.  d on the attached diagram. The sampling  ad water in 10 or more years is located 1 mile ocated 1.5 miles north of the location. A
OTHER:  12. Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompilation.  03/07/2002: Removed 95 barrels BS&W from pit and disposed at Ga 04/01/2002: Removed 20 mill liner and contaminated soil from 15' X Covered pit and leveled area.  06/27/2002: Notified OCD of soil samplings scheduled for 7/1/2002.  07/01/2002: Samples were taken from bottom of pit area as indicated analysis was forwarded to your attention.  The area ground water level is 400'. A windmill which has not pumped due east of the location. A dirt tank which only fills with rain water is fresh water station in located 3.5 miles north of the location.	Pit Closure  ails, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion  andy Marley.  20' X 3' pit and disposed at Gandy Marley.  d on the attached diagram. The sampling  ad water in 10 or more years is located 1 mile ocated 1.5 miles north of the location. A
OTHER:  12. Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompilation.  03/07/2002: Removed 95 barrels BS&W from pit and disposed at Ga 04/01/2002: Removed 20 mill liner and contaminated soil from 15' X Covered pit and leveled area.  06/27/2002: Notified OCD of soil samplings scheduled for 7/1/2002. 07/01/2002: Samples were taken from bottom of pit area as indicated analysis was forwarded to your attention.  The area ground water level is 400'. A windmill which has not pumpedue east of the location. A dirt tank which only fills with rain water is liften the fresh water station in located 3.5 miles north of the location.	Pit Closure  ails, and give pertinent dates, including estimated dates. Attach wellbore diagram of proposed completion and Marley.  20' X 3' pit and disposed at Gandy Marley.  d on the attached diagram. The sampling and water in 10 or more years is located 1 mile ocated 1.5 miles north of the location. A  mowledge and belief.  Analyst  DATE 8/28/02
OTHER:  12. Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompilation.  03/07/2002: Removed 95 barrels BS&W from pit and disposed at Ga 04/01/2002: Removed 20 mill liner and contaminated soil from 15' X Covered pit and leveled area.  06/27/2002: Notified OCD of soil samplings scheduled for 7/1/2002. 07/01/2002: Samples were taken from bottom of pit area as indicated analysis was forwarded to your attention.  The area ground water level is 400'. A windmill which has not pumpedue east of the location. A dirt tank which only fills with rain water is liften the water station in located 3.5 miles north of the location.  Thereby certify that the information above is true and complete to the best of my keep starting and complete to the complete starting and complete starting and complete starting and complete	Pit Closure  ails, and give pertinent dates, including estimated dates. Attach wellbore diagram of proposed completion andy Marley.  20' X 3' pit and disposed at Gandy Marley.  d on the attached diagram. The sampling and water in 10 or more years is located 1 mile ocated 1.5 miles north of the location. A  mowledge and belief.  Analyst  DATE 8/28/02  Telephone No. (505) 622-7330