

CIS
AP

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088, Santa Fe, New Mexico 87504-2088

WELL API NO.	30-005-62798
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	McBride State
8. Well No.	#3
9. Pool name or Wildcat	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3810 GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Hanson Operating Company, Inc.
3. Address of Operator P.O. Box 1515, Roswell, NM 88202-1515	

4. Well Location Unit Letter G : 1675 Feet From The North Line and 2310 Feet From The East Line Section 28 Township 10S Range 27E NMPM Chaves County	
--	--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Hanson Operating Company, Inc. plans to plug & abandon the above well in the following manner:

Surface plug with 10 sxs cement.
Plug 970'-870' with 25 sxs cement and tag.
Plug 2623'-2523' with 25 sxs cement.
Plug 4745'-4645' with 25 sxs cement.
Plug 5625'-5525' with 25 sxs cement.
Set CIBP at 6248' with 35 sxs cement on top.
6050.

* Brine gel between cement plugs.
Notify N.M.O.C.D. to witness Plugging Operations.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Betsy Speer TITLE Production Analyst DATE 1-19-01
TYPE OR PRINT NAME Betsy Speer TELEPHONE NO. 505-622-7370

(This space for State Use)

APPROVED BY Mike Stillfield TITLE Field Rep. II DATE 1/31/2001
CONDITIONS OF APPROVAL, IF ANY: