	State of New Mex	-iaa	- **
Submit 3 Copies to Appropriate District Office	Ener, Minerals and Natural Res		Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobba, NM 88240	OIL CONSERVATION P.O. Box 208		WELL API NO. 30-005-62801
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico	87504-2088 NOV 2'90	5. Indicate Type of Lease STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		O. C. D.	6. State Oil & Gas Lease No. LG 5246
SUMPRY MOT	TICES AND REPORTS ON WELL	S ARTESIA, OFFICE	
DO NOT USE THIS FORM FOR PH DIFFERENT RESE	IOPOSALS TO DRILL OR TO DEEPEN (ERVOIR, USE "APPLICATION FOR PER C-101) FOR SUCH PROPOSALS.)	OH PLUG BACK TO A	7. Lease Name or Unit Agreement Name
1. Type of Well: OIL GAS WELL [X] WELL [OTHER		Pathfinder AFT State
2. Name of Operator YATES PETROLEUM CORPO	RATION (8. Well No.
3. Address of Operator	MITTON /		9. Pool name or Wildcat
105 South 4th St., Ar	tesia, NM 88210	•	Diablo - Fuuselman
4. Well Location			
Unit Letter :	660 Feet From The South	Line and 2310	Feet From The East Line
Section 21	Township 10S Ran	nge 27E	NMPM Chaves County
	10. Elevation (Show whether I	DF, RKB, RT, GR, e tc.) .7	
11. Check	Appropriate Box to Indicate N	Nature of Notice, R	Report, or Other Data
NOTICE OF IN		SUE	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLIN	G OPNS. X PLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND C	EMENT JOB X
OTHER:			e, Production Casing X
12. Describe Proposed or Completed Ope work) SEE RULE 1103.	rations (Clearly state all persinent details, as	ad give pertinent dates, incl.	uding estimated date of starting any proposed
of spud. Resume Ran 23 joints 10- float set 961'. wt. 12.7). Taile 10-5-90. Bumped WOC. Drilled out minutes. Reduced TD 6415'. Reache 29.7# N-80 LT&C, jts 7-5/8" 29.7# 6373'. DV tool @	d drilling 14-3/4" hole 3/4" 40.5# J-55 ST&C cas Cemented w/450 sx Pacesed in w/200 sx "C" + 2% (plug to 700 psi, release 5:30 PM 10-6-90. WOC I hole to 9-1/2". d TD 10-24-90. Ran 151 26 jts 7-5/8" 26.4# N-80 LT&C, casing set 64 3948'. Cmt'd 1st stage	5:00 PM 10-3-9 sing set 1005'. Etter Lite C w/CaCl2 (yield 1. ed pressure, help hrs. NU and joints 7-5/8" LT&C, 102 jts w/500g. Surbon	Guide shoe set 1005', insert 1/4#/sx Celloseal (yield 1.84, 32, wt. 14.8). PD 10:30 PM 1d OK. Circulated 55 sacks. 1 tested to 1000 psi for 30 casing as follows: 20 jts 7-5/8" 5 7-5/8" 26.4# J-55 LT&C, and 3 noe set 6415'. Float collar set 1.32, wt 14.8). PD 3:30 PM 10-26-9
I hereby certify that the information above is	true and complete to the best of my knowledge and	d belief.	(cont'd next page)
SIGNATURE Andrew	Soolett n	nr Production	Supervisor DATE 11-1-90
TYPE OR PRINT NAME Juan:	ita Goodlett		TELEPHONE NO. 505/748-1471
(This space for State Use) ORIGINAL	SIGNED BY		NOV 6 1990
MIKE WILL	L!AM \$ OR, DISTRICT ()	m.e	DATE
APPROVED BY SUPERVIS	UT, DISTRICT !!		

CONDITIONS OF APPROVAL, IF ANY:

Submit 3 Copies to Appropriate

APPROVED BY ---

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Ener , Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I OIL CONSERV			
P.O. Box 1980, Hobbs, NM 88240	VATIOI . Box 2088	N DIFFERMEN	WELL API NO. 30-005-62801
OISTRICT II Santa Fe, New 88210		37504-2088	5 Indicate Type of Lease
DISTRICT III		NON 5.80	STATE X FEE 6. State Oil & Gas Lesse No.
000 Rio Brazos Rd., Aztec, NM 87410		0. C. ·	LG 5246
SUNDRY NOTICES AND REPORTS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DIFFERENT RESERVOIR. USE "APPLICATION (FORM C-101) FOR SUCH PROPOS	O DEEPEN (IN FOR PER	OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
. Type of Well: OE. GAS WELL XX WELL OTHER			Pathfinder AFT State
Name of Operator YATES PETROLEUM CORPORATION			8. Well No. 10
. Address of Operator 105 South 4th St., Artesia, NM 88210		1.5	9. Pool name or Wildcat Diablo - Fusselman
Well Location Unit Letter 0 : 660 Feet From The Sout	th	Line and2310	O Feet From The East Line
Section 21 Township 10S	Rar	nge 27E DF, RKB, RT, GR, etc.)	NMPM Chaves County
77777777777777777777777777777777777777		327 GR	
Check Appropriate Box to I NOTICE OF INTENTION TO:	Indicate N	Nature of Notice, R SUB	eport, or Other Data SSEQUENT REPORT OF:
ERFORM REMEDIAL WORK PLUG AND ABANDO	ON 🔲	REMEDIAL WORK	ALTERING CASING
EMPORARILY ABANDON CHANGE PLANS		COMMENCE DRILLING	G OPNS. PLUG AND ABANDONMENT
ULL OR ALTER CASING		CASING TEST AND CE	
THER:	[_]	OTHER: Sur	face, Production Casing X
			
2. Describe Proposed or Completed Operations (Clearly state all persina work) SEE RULE 1103. cont'd — Circulated 100 sx. Opened DV tool w/5 + 5#/salt + 5#/sx Gilsonite + 1/4# Cellite "C" Neat (yield 1.32, wt 14.8). Bumped plug to 1000 psi for 15 minutes	500 psi. 11oseal PD 6:00	. Circulated 1 (yield 1.98, w) PM 10-26-90.	hour. Cmt'd stage 2 - 850 sx t 12.40. Tailed in w/100 sx Closed tool with 2250 psi.
work) SEE RULE 1103. cont'd - Circulated 100 sx. Opened DV tool w/5 + 5#/salt + 5#/sx Gilsonite + 1/4# Cellite "C" Neat (yield 1.32, wt 14.8). Bumped plug to 1000 psi for 15 minutes	500 psi 11oseal PD 6:00 s, held	. Circulated 1 (yield 1.98, w) PM 10-26-90. OK. Circulate	hour. Cmt'd stage 2 - 850 sx t 12.40. Tailed in w/100 sx Closed tool with 2250 psi.
Circulated 100 sx. Opened DV tool w/5 + 5#/salt + 5#/sx Gilsonite + 1/4# Cellite "C" Neat (yield 1.32, wt 14.8). Bumped plug to 1000 psi for 15 minutes Thereby certify that the information above is true and complete to the best of my	500 psi. 11oseal PD 6:00 s, held	. Circulated 1 (yield 1.98, w) PM 10-26-90. OK. Circulate	hour. Cmt'd stage 2 - 850 sx t 12.40. Tailed in w/100 sx Closed tool with 2250 psi. d 10 sacks. WOC. WOCU.
cont'd - Circulated 100 sx. Opened DV tool w/5 + 5#/salt + 5#/sx Gilsonite + 1/4# Cellite "C" Neat (yield 1.32, wt 14.8). Bumped plug to 1000 psi for 15 minutes I hereby certify that the information above is true and complete to the best of my	500 psi. 11oseal PD 6:00 s, held	. Circulated 1 (yield 1.98, w) PM 10-26-90. OK. Circulate	hour. Cmt'd stage 2 - 850 sx t 12.40. Tailed in w/100 sx Closed tool with 2250 psi. d 10 sacks. WOC. WOCU.

- TITLE -