

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brizos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

APR 30 1991

WELL API NO. 30-005-62828
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. L-794
7. Lease Name or Unit Agreement Name Hanlad 16 State
8. Well No. 1
9. Pool name or Wildcat Diablo San Andres
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3889' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Hanson Operating Company, Inc. ✓
3. Address of Operator P. O. Box 1515, Roswell, New Mexico 88202-1515	4. Well Location Unit Letter K : 2005 Feet From The South Line and 2310 Feet From The West Line Section 16 Township 10-S Range 27-E NMPM Chaves County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3889' GR	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged & Abandoned in the following manner:

04/23/91 Pmp 60 bbls brine water; couldn't break circ. Spotted 100' 26 sx Class "C" top San Andres 1500-1400'. Pulled to top of Queen. Pmp 100' 26 sx Class "C" plug w/4% CaCl 975-875'. Pulled up to 557' waited 1 1/2 hrs. Attempted to circ; couldn't circ. RIH to tag plug. Went down to 1500'; didn't tag. Spotted 100' 26 sx Class "C" plug w/4% CaCl @1500'. SD.
04/24/91 RIH w/tbg. Tagged plug @1440'. Pmp 15 sx Class "C" plug w/4% CaCl & wood shavings to bring plug to required depth. Pmp 35 sx Class "C" plug w/4% CaCl @975'. Waited 2 hrs. RIH to 875' attempted to break circ; couldn't circ. RIH to tag plug. Didn't tag; went down to 1290'. Pulled up to 975'. Pmp 100' 26 sx Class "C" plug w/4% CaCl. Pulled to 557'. Pmp 30 sx Class "C" plug 50'in and 50' out of 8-5/8" csg shoe. RIH to tag plug @990'. Pulled upto 557' Attempted to establish circ; wouldn't circ. Pmp 35 sx Class "C" plug w/4% CaCl @557'. SD.
04/25/91 Loaded hole & broke partial circ. RIH to tag plug; didn't tag. Pmp 35 sx Class "C" plug w/4% CaCl & 1 bag flocele 50' in & 50' out of 8-5/8" csg shoe. SD; waiting on cem. RIH tagged plug @ 540'. Pmp 35 sx Class "C" plug w/4% CaCl & 1 bag flocele. SD; waiting on cem.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Lisa L. Jennings TITLE Production Analyst DATE 4-29-91
TYPE OR PRINT NAME Lisa L. Jennings TELEPHONE NO. 622-7330

(This space for State Use)

APPROVED BY Johnny Robinson TITLE OIL AND GAS CONTROL DATE 7-8-91
CONDITIONS OF APPROVAL, IF ANY:

OK GW

Post ID-2
5-10-91
P&A