

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-005-62829
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG 5246
7. Lease Name or Unit Agreement Name Pathfinder AFT State
8. Well No. 13
9. Pool name or Wildcat Diablo Fusselman Associated

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator YATES PETROLEUM CORPORATION	3. Address of Operator 105 South 4th St., Artesia, NM 88210	4. Well Location Unit Letter <u>F</u> : <u>2310</u> Feet From The <u>North</u> Line and <u>1850</u> Feet From The <u>West</u> Line Section <u>21</u> Township <u>10S</u> Range <u>27E</u> NMPM <u>Chaves</u> County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3855' GR
---	--	--	---	--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Production Casing ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 6750'. Reached TD 1:45 AM 2-25-91. Ran 165 joints 7" 23# and 26# J-55 as follows: 35 jts 7" 26# J-55 LT&C, 124 jts 7" 23# J-55 L&TC, 6 jts 7" 26# J-55 LT&C, casing set 6750'. Guide shoe set 6750', float collar set 6708'. DV tool set 4009'. Cemented in 2 stages. Stage 1: 670 sx Premium Plus "C", 5#/sx Salt, .7% Halad 322, 1/4#/sx Flocele. PD 10:30 AM 2-26-91. Circulated 80 sx to pit. Open DV tool with 500 psi. Stage 2: 1275 sx Premium Plus "C", 5#/sx Salt, .5% Halad 322, 1/4#/sx Flocele. PD 3:00 PM 2-26-91. Circulate 50 sacks to pit. Rig released 4:00 PM 2-26-91. Note: Waited 3 hrs between cement stages.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 3-6-91
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT 19

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

MAR 13 1991