

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-005-62829
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG 5246
7. Lease Name or Unit Agreement Name Pathfinder AFT State
8. Well No. 13
9. Pool name or Wildcat Diablo Fusselman Associated

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	RECEIVED MAR 14 1991 O. C. D. ARTESIA, OFFICE
2. Name of Operator YATES PETROLEUM CORPORATION	
3. Address of Operator 105 South 4th St., Artesia, NM 88210	
4. Well Location Unit Letter <u>F</u> : <u>2310</u> Feet From The <u>North</u> Line and <u>1850</u> Feet From The <u>West</u> Line Section <u>21</u> Township <u>10S</u> Range <u>27E</u> NMPM Chaves County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3855' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Perforate, Treat <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-7-91. Drilled out DV tool at 4009'.

3-9-91. Perforated 6442-6729' w/69 - .40" holes as follows: 6442, 43, 44, 45, 46, 47, 48, 57, 58, 59, 69, 70, 71, 72, 73, 74, 75, 83, 84, 6502, 04, 06, 07, 13, 14, 15, 16, 19, 33, 35, 37, 38, 70, 80, 81, 82, 83, 84, 85, 86, 93, 95, 97, 6603, 05, 07, 11, 14, 19, 54, 58, 59, 61, 62, 63, 64, 68, 69, 73, 74, 85, 6715, 17, 19, 21, 23, 25, 27 and 6729'. Acidized perforations 6654-6729' w/1500 gals 20% NEFE acid. Acidized perforations 6579-6619' w/1500 gals 20% NEFE acid. Acidized perforations 6442-6538' w/2000 gals 20% NEFE acid. Straddled perforations 6442-6729'. Acidized with 25000 gals 20% NEFE, 30000# Block + ball Sealers.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Juanita Goodlett

TITLE Production Supervisor

DATE 3-13-91

TYPE OR PRINT NAME

Juanita Goodlett

TELEPHONE NO. 505/748-147

(This space for State Use)

ORIGINAL SIGNED BY

MIKE WILLIAMS

SUPERVISOR, DISTRICT II

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

MAR 21 1991