Submit 3 Copies to Appropriate District Office

State of New Mexico nerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

OIL CONSERVATION DIVISION P.O. Box 2088

Santa Fe, New Mexico 8756CEDVED

		10
WELL API NO.		
30-005		
5. Indicate Type of Le	ase	
	STATE	FEE
6. State Oil & Gas Lea	ise No.	
LG 7444		
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	<del>,,,,,,,,,,,</del>	<del>,,,,,,,</del> ,

District III		STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	FEB 1 () 1992	
, , , , , , , , , , , , , , , , , , , ,		6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WE	O. C. D.	
( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN	FERSIENS CIFFICE	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PE	RMIT	7. Lease Name or Unit Agreement Name
(FORM C-101) FOR SUCH PROPOSALS.)		
1. Type of Well:		
OIL GAS WELL X OTHER		MANNES STATE
2. Name of Operator		
SOUTHEASTERN PETROLEUM, INC.		8. Well No.
3. Address of Operator		1 34 9. Pool name or Wildcat
911 N. PEARSON, ROSWELL, NM 8820	7	
4. Well Location	1	MONTOYA - WILDCAT
Unit Letter I: 1980 Feet From The SOUTH	Line and 660	Feet From The <u>EAST</u> Line
Section 34 Township 3S R	ange 27E	NMPM CHAVES County
10. Elevation (Show whether	DI', KKB, RI, GR, etc.)	<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>
(/////// GR 4029		<u> </u>
11. Check Appropriate Box to Indicate	Nature of Notice, Re	eport, or Other Data
NOTICE OF INTENTION TO:	_	SEQUENT REPORT OF:
		oe doent the offi of .
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS	00111151105 55011111	
Change Plans	COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING	CASING TEST AND CE	MENT JOB
OTHER: WELL COMPLETION III		i.:
OTHER: WELL COMPLETION	OTHER:	X
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, a work) SEE RULE 1103.		
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, a work) SEE RULE 1103.	nd give pertinent dates, includ	ling estimated date of starting any proposed
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, a work) SEE RULE 1103.  PERFORATED PENN FORMATION FROM 6557!	nd give pertinent dates, includ	ling estimated date of starting any proposed
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, a	nd give pertinent dates, includ	ling estimated date of starting any proposed
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, a work) SEE RULE 1103.  PERFORATED PENN FORMATION FROM 6557' TO SURFACE IN 20 MIN.	nd give perlinent dales, includ	shots PF W/VAN GUN. GAS
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, a work) SEE RULE 1103.  PERFORATED PENN FORMATION FROM 6557' TO SURFACE IN 20 MIN.  PERFORATED PENN FORMATION FROM 6333'	nd give perlinent dales, includ	shots PF W/VAN GUN. GAS
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, a work) SEE RULE 1103.  PERFORATED PENN FORMATION FROM 6557!	nd give perlinent dales, includ	shots PF W/VAN GUN. GAS
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, a work) SEE RULE 1103.  PERFORATED PENN FORMATION FROM 6557' TO SURFACE IN 20 MIN.  PERFORATED PENN FORMATION FROM 6333' SURFACE IN 24 MIN.	nd give perlinent dales, includ	shots PF W/VAN GUN. GAS
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, a work) SEE RULE 1103.  PERFORATED PENN FORMATION FROM 6557' TO SURFACE IN 20 MIN.  PERFORATED PENN FORMATION FROM 6333'	nd give perlinent dales, includ	shots PF W/VAN GUN. GAS
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, a work) SEE RULE 1103.  PERFORATED PENN FORMATION FROM 6557' TO SURFACE IN 20 MIN.  PERFORATED PENN FORMATION FROM 6333' SURFACE IN 24 MIN.  SET RBP MOVED UP TO SAN ANDRES FORMATION	nd give perlinent dales, included to the following of the	SHOTS PF W/VAN GUN. GAS
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, a work) SEE RULE 1103.  PERFORATED PENN FORMATION FROM 6557' TO SURFACE IN 20 MIN.  PERFORATED PENN FORMATION FROM 6333' SURFACE IN 24 MIN.  SET RBP MOVED UP TO SAN ANDRES FORMATION PERFORATED FROM 2350' TO 2354' AND EXCEPTION 2550' TO 2354' TO 2350' TO 2354' TO 2354' TO 2350' TO 2354' TO 23	nd give perlinent dales, included to the following of the	SHOTS PF W/VAN GUN. GAS  SPF W/VAN GUN. GAS TO
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, a work) SEE RULE 1103.  PERFORATED PENN FORMATION FROM 6557' TO SURFACE IN 20 MIN.  PERFORATED PENN FORMATION FROM 6333' SURFACE IN 24 MIN.  SET RBP MOVED UP TO SAN ANDRES FORMATION PERFORATED FROM 2350' TO 2354' AND FROM STIMULATED W/15% HCL Aid. SQUEEZED OF	nd give perlinent dales, included to the following of the	SHOTS PF W/VAN GUN. GAS  SPF W/VAN GUN. GAS TO
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, a work) SEE RULE 1103.  PERFORATED PENN FORMATION FROM 6557' TO SURFACE IN 20 MIN.  PERFORATED PENN FORMATION FROM 6333' SURFACE IN 24 MIN.  SET RBP MOVED UP TO SAN ANDRES FORMATION	nd give perlinent dales, included to the following of the	SHOTS PF W/VAN GUN. GAS  SPF W/VAN GUN. GAS TO
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, a work) SEE RULE 1103.  PERFORATED PENN FORMATION FROM 6557' TO SURFACE IN 20 MIN.  PERFORATED PENN FORMATION FROM 6333' SURFACE IN 24 MIN.  SET RBP MOVED UP TO SAN ANDRES FORMATION FROM 2350' TO 2354' AND FROM STIMULATED W/15% HCL Aid. SQUEEZED OF PACKER @ 6266'.	nd give perlinent dales, included to the following of the	SHOTS PF W/VAN GUN. GAS  SPF W/VAN GUN. GAS TO  63' W/4" CSG GUN.  OVED BACK TO PENN SET
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, a work) SEE RULE 1103.  PERFORATED PENN FORMATION FROM 6557' TO SURFACE IN 20 MIN.  PERFORATED PENN FORMATION FROM 6333' SURFACE IN 24 MIN.  SET RBP MOVED UP TO SAN ANDRES FORMATION PERFORATED FROM 2350' TO 2354' AND FROM STIMULATED W/15% HCL Aid. SQUEEZED OF	nd give perlinent dales, included to the following of the	SHOTS PF W/VAN GUN. GAS  SPF W/VAN GUN. GAS TO  63' W/4" CSG GUN.  OVED BACK TO PENN SET
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, a work) SEE RULE 1103.  PERFORATED PENN FORMATION FROM 6557' TO SURFACE IN 20 MIN.  PERFORATED PENN FORMATION FROM 6333' SURFACE IN 24 MIN.  SET RBP MOVED UP TO SAN ANDRES FORMATION FROM 2350' TO 2354' AND FROM STIMULATED W/15% HCL Aid. SQUEEZED OF PACKER @ 6266'.  SWABBED TUBING DOWN SHUT WELL IN. WAS	nd give perlinent dales, included to the following of the following the	SHOTS PF W/VAN GUN. GAS  SPF W/VAN GUN. GAS TO  63' W/4" CSG GUN.  OVED BACK TO PENN SET
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, a work) SEE RULE 1103.  PERFORATED PENN FORMATION FROM 6557' TO SURFACE IN 20 MIN.  PERFORATED PENN FORMATION FROM 6333' SURFACE IN 24 MIN.  SET RBP MOVED UP TO SAN ANDRES FORMATION FROM 2350' TO 2354' AND FROM STIMULATED W/15% HCL Aid. SQUEEZED OF PACKER @ 6266'.	nd give perlinent dales, included to the following of the following the	SHOTS PF W/VAN GUN. GAS  SPF W/VAN GUN. GAS TO  63' W/4" CSG GUN.  OVED BACK TO PENN SET
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, a work) SEE RULE 1103.  PERFORATED PENN FORMATION FROM 6557' TO SURFACE IN 20 MIN.  PERFORATED PENN FORMATION FROM 6333' SURFACE IN 24 MIN.  SET RBP MOVED UP TO SAN ANDRES FORMATION PERFORATED FROM 2350' TO 2354' AND FROM STIMULATED W/15% HCL Aid. SQUEEZED OF PACKER @ 6266'  SWABBED TUBING DOWN SHUT WELL IN. WAT	nd give perlinent dates, included to the following of the	SHOTS PF W/VAN GUN. GAS  SPF W/VAN GUN. GAS TO  63' W/4" CSG GUN.  OVED BACK TO PENN SET  INE.
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, a work) SEE RULE 1103.  PERFORATED PENN FORMATION FROM 6557' TO SURFACE IN 20 MIN.  PERFORATED PENN FORMATION FROM 6333' SURFACE IN 24 MIN.  SET RBP MOVED UP TO SAN ANDRES FORMATION PERFORATED FROM 2350' TO 2354' AND FROM STIMULATED W/15% HCL Aid. SQUEEZED OF PACKER @ 6266'  SWABBED TUBING DOWN SHUT WELL IN. WAT	nd give perlinent dales, included to the following of the following the	SHOTS PF W/VAN GUN. GAS  SPF W/VAN GUN. GAS TO  63' W/4" CSG GUN.  OVED BACK TO PENN SET  INE.
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, a work) SEE RULE 1103.  PERFORATED PENN FORMATION FROM 6557' TO SURFACE IN 20 MIN.  PERFORATED PENN FORMATION FROM 6333' SURFACE IN 24 MIN.  SET RBP MOVED UP TO SAN ANDRES FORMATION PERFORATED FROM 2350' TO 2354' AND FROM STIMULATED W/15% HCL Aid. SQUEEZED OF PACKER @ 6266'  SWABBED TUBING DOWN SHUT WELL IN. WAT	nd give perlinent dates, included to the following of the	SHOTS PF W/VAN GUN. GAS  SPF W/VAN GUN. GAS TO  63' W/4" CSG GUN.  OVED BACK TO PENN SET  INE.  T DATE 1/30/92
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, a work) SEE RULE 1103.  PERFORATED PENN FORMATION FROM 6557' TO SURFACE IN 20 MIN.  PERFORATED PENN FORMATION FROM 6333' SURFACE IN 24 MIN.  SET RBP MOVED UP TO SAN ANDRES FORMATION PERFORATED FROM 2350' TO 2354' AND FROM STIMULATED W/15% HCL Aid. SQUEEZED OF PACKER @ 6266'.  SWABBED TUBING DOWN SHUT WELL IN. WAIT TYPE OF PRINT NAME  A. J. "SONNY" LONGO	nd give perlinent dates, included to the following of the	SHOTS PF W/VAN GUN. GAS  SPF W/VAN GUN. GAS TO  63' W/4" CSG GUN.  OVED BACK TO PENN SET  INE.
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, a work) SEE RULE 1103.  PERFORATED PENN FORMATION FROM 6557' TO SURFACE IN 20 MIN.  PERFORATED PENN FORMATION FROM 6333' SURFACE IN 24 MIN.  SET RBP MOVED UP TO SAN ANDRES FORMATION FROM 6333' PERFORATED FROM 2350' TO 2354' AND FROM STIMULATED W/15% HCL Aid. SQUEEZED OF PACKER @ 6266'  SWABBED TUBING DOWN SHUT WELL IN. WAS Interest of the best of my knowledge and stonature	nd give perlinent dates, included to the following of the	SHOTS PF W/VAN GUN. GAS  SPF W/VAN GUN. GAS TO  63' W/4" CSG GUN.  OVED BACK TO PENN SET  INE.  T DATE 1/30/92