

MARTIN YATES, III
1912 - 1985
FRANK W. YATES
1936 - 1986



105 SOUTH FOURTH STREET
ARTESIA, NEW MEXICO 88210

TELEPHONE (505) 748-1471

S. P. YATES
CHAIRMAN OF THE BOARD
JOHN A. YATES
PRESIDENT
PEYTON YATES
EXECUTIVE VICE PRESIDENT
RANDY G. PATTERSON
SECRETARY
DENNIS G. KINSEY
TREASURER

Salt Creek Unit #3, NM-42554
1980' FNL, 660' FEL, Sec. 11-T8S-R21E
Chaves County, NM

DRILL STEM TESTS

DST #1 3225-3335' (110') ABO: TIMES: 5", 60", 60", 180". RECOVERY: 30'
drilling mud, Chl 67000 @ 45 psi. PRESSURES: IHP 1697, IFP 87-93, ISIP 312,
FFP 93-104, FSIP 340, FHP 1692, BHT 98°.

DST #2 3335-3465' (130'): TIMES: 5", 60", 60", 120", 60". RECOVERY: 75'
drilling mud. SAMPLER: 3500 cc mud. PRESSURES: IHP 1613.91, IFP 39.58-28.33,
ISIP 1289.84, 2nd FP 45.18-48.76, FSIP 1163.87, FFP 62.89-70.61, FHP 1589.49.