

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

WELL API NO.

**30-005-62906**

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

**VA-2058**

7. Lease Name or Unit Agreement Name:

**Aviator AVO State**

Well No.

**#1**

Pool name or Wildcat

**Undesignated Wolfcamp**

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☒ Other ☐

2. Name of Operator

**Yates Petroleum Corporation**

3. Address of Operator

105 S. 4<sup>th</sup> Street Artesia, NM 88210

4. Well Location

Unit Letter **E** : **1980** feet from the **North** line and **990** feet from the **West** line

Section **33** Township **9S** Range **27E** NMPM **Chaves** County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

**3891' GR**

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☒

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Perforate, acidize ☒

Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

We propose to attempt to complete this well as follows:

Perforate Cisco 6074-6144'.

Acidize perms 6074-6144' with 2600 gals 15% IC HCL.

If the Cisco is not productive, or if the gas rate is low:

Perforate the Wolfcamp 5906-5936'.

Acidize perms 5906-5936' with 3000 gals 15% IC HCL.

If both zones are productive, zones will be downhole commingled with proper approval.

**C107 A**  
**from Santa Fe**

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Susan Herpin TITLE Engineering Technician DATE February 5, 2002

Type or print name **Susan Herpin**

Telephone No. **505-748-1471**

(This space for State use)

**ORIGINAL SIGNED BY TIM W. GUN**  
**DISTRICT II SUPERVISOR**

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE **FEB 08 2002**

Conditions of approval, if any:

