

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

WELL API NO.

30-005-62906

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

VA-2058

7. Lease Name or Unit Agreement Name:

Aviator AVO State

7. Well No.

#1

8. Pool name or Wildcat

Undesignated Wolfcamp

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☒ Other ☐

2. Name of Operator

Yates Petroleum Corporation

3. Address of Operator

105 S. 4th Street Artesia, NM 88210

4. Well Location

Unit Letter E : 1980 feet from the North line and 990 feet from the West line

Section 33

Township 9S

Range 27E

NMPM

Chaves

County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

3891' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☒

COMMENCE DRILLING OPNS ☐

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: Perforate, acidize ☒

Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

3/20/02 - MIRU pulling unit.

3/21/02 - Perforate Wolfcamp 5916-5928', 26 holes and Cisco 6074-6096', 46 holes, .42".

3/22/02 - Acidize perms 6074-6096' with 2200 gals 15% IC HCL. Swab test.

3/26/02 - Straddle perms 5916-5928'. Acidized with 1200 gals 15% IC HCL. Pumped 6 bbls into formation, and communicated with Wolfcamp perms 5885-5895'. Move packer to straddle all Wolfcamp perms 5885-5928' and pumped remaining acid. Swab test.

3/28/02 - Rig down and move out.

4/5/02 - Decision to plug and abandon. Notified NMOCD of intent to start plugging.

4/8/02 - Set CIBP at 6050', capped with 35' cement. Set CIBP at 5850', capped with 35' cement.

Note: Mike Bratcher with NMOCD on location.

4/9/02 - Set 25 sxs cement plug at 4850'. Pulled 5-1/2" csg slips, cut csg at 3650', and TOH with 5-1/2" csg.

See Attached

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Susan Herpin TITLE Engineering Technician DATE January 15, 2002

Type or print name Susan Herpin

Telephone No. 505-748-1471

(This space for State use)

APPROVED BY

TITLE Field Rep ID

DATE MAY 10 2002

Conditions of approval, if any:

Yates Petroleum Corporation  
Aviator AVO State #1  
API – 30-005-62906  
Section 33 T9S R27E  
Chaves County, NM

Describe proposed or completed operations continued:

4/10/02 – TIH with tbg to 3750'. Pumped 40 sxs cement plug. WOC 3 hours and tagged plug at 3537'.

Set 35 sxs cement plug at 2650'.

Set 35 sxs cement plug at 1450'.

Set 40 sxs cement plug at 985' across the 8-5/8" casing shoe. WOC 3 hours. Tagged plug at 855'.

Set 25 sxs cement plug 90' to surface. Top off casing with cement.

Cut off anchors, fill pit and install dry hole marker.

Note: Mike Bratcher with NMOCD on location.