		a _state	
Submit 3 Copies to Appropriate District Office	Energy, "nerals and Natur	al Resources Department	Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION P.O. Box 2088		WELL API NO. 30-005-62911
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mez	xico 87504-2088	5. Indicate Type of Lease STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		•	6. State Oil & Gas Lease No. VB-427
	AND DEPORTS ON	WELLS	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name
1. Type of Well: OL: WELL WELL X	OTHER	RECEIVED	Hanlad AKZ State
2. Name of Operator		• •	8. Well No.
YATES PETROLEUM CORPO	RATION	<u>05'94</u>	2 9. Pool name or Wildcat
3. Address of Operator	. Ambania MM 99	210	Paloma Mesa
105 South Fourth Stre 4. Well Location	et - Artesia, NM . 00	and the second	ratolia nesa
4. Well Location OFFICE Unit Letter M : 330 Feet From The South Line and 1225 Feet From The West Line			
12	Transition 90	Range 27E	NMPM Chaves County
Section 13	Township 8S 777777777777777777777777777777777777	whether DF, RKB, RT, GR, etc.)	
	39	943' GR	
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF IN		SU	BSEQUENT REPORT OF:
	PLUG AND ABANDON		
	CHANGE PLANS		IG OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING			
OTHER:			e perforations X
12. Describe Proposed or Completed Operations (Clearly state all perinent details, and give perinent date, including estimated date of starting any proposed work) SEE RULE 1103. 9-24-26-94 - Rigged up wireline. TIH with cement retainer and set at 6388'. TOOH with setting tool and rigged down wireline. TIH with 2-7/8" tubing. Sting into retainer at 6388'. Pressured annulus to 600 psi. Establish injection rate down tubing of 3 BPM at 0 psi. Mixed and pumped 100 sacks Class H, 4/10% CF-14 and 100 sacks "H" Neat. With 90 sacks of cement in perforations 6396-6455', squeezed to 3000 psi. Sting out of retainer and reverse casing clean with 2% KCL water. TOOH with 2-7/8" tubing. Shut down. 9-27-94 - TIH with sand jet tool and 2-7/8" tubing. Rigged up wireline and TIH with 1-11/16" gamma ray and correlated sand jet tool into place. TOOH with gamma ray tool and rigged down wireline. Made 20 min sand jet cut at 6369'. Pulled up 11' and made 10 min cut at 6358'. After 10 mins, lost jet in tool. Reverse sand out of hole and TOOH with 2-7/8" tubing and sand jet tool. TIH with new sand jet tool and 2-7/8" tubing. Tagged - sand at 5352'. Reverse casing clean to 6371'. Pulled up and made additional 15 min cut at 6358'. Pulled up 4' and made 20 min sand jet cut at 6354'. Dropped down and reversed casing clean to 5371'. TOOH with 20 stands of 2-7/8" tubing. Shut down. Thereby centry that he information above is true and complete to the best of my knowledge and beief. SIGNATURE WILL THE RUSTY Klein			
(This space for State Use)			OCT 😕 5 1994
AUTROVED BY DATE DATE DATE			
STREET FOR ADDOLLS TANY			