

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

RECEIVED

WELL API NO. 30--00562-962
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name L.E. Ranch
8. Well No. 1
9. Pool name or Wildcat n.a.
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3735' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐
ARTESIA, OFFICE

2. Name of Operator
RATLIFF OPERATING CORP.

3. Address of Operator
P.O. Box 2044, Amarillo, TX 79105-2044

4. Well Location
Unit Letter M: 566 Feet From The South Line and 15 Feet From The West Line
Section 29 Township 11 South Range 28 East NMPM Chaves County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☒
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOBS ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1. Set cast iron bridge plug @ 7200'; 2. Recover casing (hope-fully 6550') and install 100' plug w/50' in & 50' out (40 sx total) and tag;
3. Install 100' plug @ 4200' (Tubb); 4. Install 100' plug @ 2345' to 2445';
5. Install 100' plug @ 298' to 398'; 6. Install 10' plug @ top & place proper marker as discussed w/Jim Morrow.
P.S. put 35' of cement above cast iron bridge plug. Also tag under 4. & 5. above.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Harvey L. Ratliff, Jr. TITLE President
TYPE OR PRINT NAME Harvey L. Ratliff, Jr.

DATE 8/29/94
(806) 376-6688
TELEPHONE NO.

(This space for State Use)

APPROVED BY [Signature] TITLE _____ DATE _____

CONDITIONS OF APPROVAL IF ANY:

For record only

8-25-94

Ratliff Opr Co.
L.E. Ranch #1
29-11-28

Chares - Plugging
Procedure

⑥ 10' in
Top.

cir C

⑤ 100' -
298' - 398'

13 ³/₈ - 348

④ ~~50' in~~
100' plug
2345' to 2445'
Tag.

8 ⁵/₈ at 2395

③ 100' plug at
4200' - Tubb.

② Rec pipe from
± 6550 -
100' plug - 50' in
+ 50' out of stab.
(min 40 sks) Tag

Top Cement 6572
Bond Log.

① CIBP + 35'
cement at 7200

Fusselman
Perfs - 7280 + -
7320

4 ¹/₂ at 7376

Caled by Harvey Ratliff
HFM