

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL AP. NO. 20-10562-962
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name L.E. Ranch
8. Well No. 1
9. Pool name or Wildcat W.C. Furselman

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator RATLIFF OPERATING CORP.	3. Address of Operator P.O. Box 2044, Amarillo, TX 79105-2044	4. Well Location Unit Letter M : 566 Feet From The South Line and 15 Feet From The West Line Section 29 Township 11 South Range 28 East NMPM Chaves County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3735' GR			

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1. Set cast iron bridge plug @ 7200'; dumped 35' cement thereon. 2. Cut casing @ 6,000', try to work loose, casing parted @ 588', pull 13 joints of casing; run 4½" casing overshot on 4½" casing; fish casing. 3. Run 2 3/8" tubing to 6050'; circulate mud, spot 25 sacks cement from 6050' to 5700' (350' plug). 4. Pull tubing to 4200', spot 25 sacks cement from 4200' to 3850' (350' plug), pull tubing; try to cut casing, could not get cutter down. 5. Run wireline cutter in hole, cut casing @ 2430', pull & lay down 4½" casing, run 2 3/8" tubing to 2580', spot 80 sacks cement, shut-down. (9/20/94). 6. Tag cement @ 2151' (9/3/94) from 2580 to 2151' (429' plug), pulled tubing to 399', spot 25 sacks from 399' to 274', pull tubing to 30', circulate 10 sacks to surface, cut off wellhead, put in marker. Cement was Class "C" cement & mud was Salt Gell--25 lb per bbl. The work was performed from 8/30/94 til 9/03/94.

Part ID-2
9-23-94
PFA

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Harvey L. Ratliff, Jr. TITLE President DATE 9/15/94
TYPE OR PRINT NAME Harvey L. Ratliff, Jr. TELEPHONE NO. (806)-376-6688

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep DATE 3-7-95
CONDITIONS OF APPROVAL, IF ANY: