

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-62965
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VB-0402
7. Lease Name or Unit Agreement Name Kells State
8. Well No. 2
9. Pool name or Wildcat Southeast Acme San Andres
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3928' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator ELK OIL COMPANY
3. Address of Operator Post Office Box 310, Roswell, New Mexico 88202-0310
4. Well Location Unit Letter A : 330 Feet From The North Line and 660 Feet From The East Line Section 14 Township 8 South Range 27 East NMMP Chaves County

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3928' GR
--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to Plug and Abandon Well as follows:

- (1) Set CIBP at 2050'. w/35' cement.
- (2) Cut and recover 1500' of 5 1/2" casing.
- (3) Set 100' plug, 50 in/50 out of casing stub at 1500'.
- (4) Set 100' plug at 8 5/8 shoe at 436'.
- (5) 10 sxs surface. Tag.

RECEIVED

Tag. OCT - 2 1996

OIL CON. DIV.
DIST. 2

Notify N.M.O.C.C. in sufficient time to witness

TAGS

Plugging Mud between Plugs.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE _____ TITLE President DATE 10/01/96

TYPE OR PRINT NAME Joseph J. Kelly TELEPHONE NO. (505)623-3190

(This space for State Use) ORIGINAL SIGNED BY TIM W. GUM

DISTRICT II SUPERVISOR

APPROVED BY _____ TITLE _____ DATE OCT 15 1996

CONDITIONS OF APPROVAL, IF ANY: