

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-005-62968
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VB-233
7. Lease Name or Unit Agreement Name Carl ANO State
8. Well No. 1
9. Pool name or Wildcat South East Acme San Andres
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3967' GR

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210	4. Well Location Unit Letter 0 : 330 Feet From The South Line and 2310 Feet From The East Line Section 1 Township 8S Range 27E NMPM Chaves County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3967' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-29-95 - Moved in and rigged up pulling unit. Installed BOP. TIH with 2-7/8" tubing to 2253'. Circulate hole with 10# brine water with 25#/bbl salt gel. Mixed and pumped 75 sacks Class C 3% CaCl<sub>2</sub>. POOH with tubing to 1100'. WOC 1 hour. Dropped down and tagged cement plug at 2061'. TOOH with tubing to 510'. Mixed and pumped 75 sacks Class C 3% CaCl<sub>2</sub>. TOOH with tubing. WOC 1 hour. TIH with 2-7/8" tubing and tagged cement plug at 362'. TOOH with tubing. Removed BOP and casinghead. Ran 3" tubing to 95'. Mixed and pumped 20 sacks Class C from 95' to surface. TOOH with tubing. Cut off anchors. Cleaned location. Installed regulation abandonment marker. **PLUGGED AND ABANDONED - FINAL REPORT.** Plugging completed 8-28-95. NOTE: Plugging witnessed by Ken Livingston w/OCD-Artesia.

OIL CON. DIV. *Post ID-2*  
DIST. 2 *9-22-95*  
*PLA*

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE Aug. 29, 1995  
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY Ken Livingston TITLE F.O. I DATE 10-31-95

CONDITIONS OF APPROVAL, IF ANY: