

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

AUG 24 1993

A.C.D.

WELL API NO.
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name ROSS FEE
8. Well No. 1
9. Pool name or Wildcat Wildcat
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL 3974'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER P & A
2. Name of Operator McCLELLAN OIL CORPORATION
3. Address of Operator P O Drawer 730, Roswell, NM 88202-0730

4. Well Location Unit Letter D : 660' Feet From The North Line and 660' Feet From The West Line Section 18 Township 8 South Range 28 East NMPM Chaves County
--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-7-93 Ran 7" 23# & 29# casing to 2170' and cemented with 25 sx cement.
8-16-93 TD well at 2410' with 6-1/8" bit.
8-17-93 Shot 7" casing off at 1720' and pulled out of hole.
8-18-93 Plug well as follows (verbal from OCD Artesia):

1. Loaded hole with heavy gel water.
2. Set 1st plug 55 sx 2137' to TD (tagged at 2137').
3. Set 2nd plug 45 sx 1590' to 1769' (tagged at 1590').
4. Set 3rd plug 35 sx 1160' to 1260'.
5. Set 4th plug 60 sx 620' to 400'.
6. Set 5th plug 60' to surface. Circulated cement.

NO FURTHER REPORTS

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mitch Lee TITLE Agent DATE 8-19-93
TYPE OR PRINT NAME Mitch Lee TELEPHONE NO. 622-3200

(This space for State Use)

APPROVED BY Karl Swenson TITLE _____ DATE 7-25-94
CONDITIONS OF APPROVAL, IF ANY: