

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-005-62985
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-2982
7. Lease Name or Unit Agreement Name Quincy, NM State
8. Well No. 4
9. Pool name or Wildcat South East Acme San Andres

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator YATES PETROLEUM CORPORATION	
3. Address of Operator 105 South 4th St., Artesia, NM 88210	
4. Well Location Unit Letter <u>E</u> : <u>2310</u> Feet From The <u>North</u> Line and <u>990</u> Feet From The <u>West</u> Line Section <u>12</u> Township <u>8S</u> Range <u>27E</u> NMPM Chaves County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3952' GR</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Perforate & acidize <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-24-95 - Cleaned location, set and tested anchors. Made cut off on 5-1/2" casing. Moved in and rigged up pulling unit. Installed tubing head and BOP. Tested casing to 1500 psi. TIH w/bit, scraper and 2-7/8" tubing to 2208'. Displaced casing with 2% KCL water. TOOH with 2-7/8" tubing, scraper and bit. Rigged up wireline. TIH with logging tools and ran CNL log. TOOH with logging tools. TIH with logging tools and ran CBL/CCL/GR log. TOOH with logging tools and rigged down wireline. Shut down.

1-25-95 - Rig up wireline. TIH with 4" casing guns and perforated 2150-2192' (San Andres P-1) with 31 .42" holes (1 SPF) as follows: 2150-2155' and 2168-2192'. TOOH with casing guns and rigged down wireline. TIH with packer and 2-7/8" tubing. Spot acid across perforations 2150-2192'. Pulled up and set packer at 2086'. Removed BOP and nipped up wellhead. Acidize perforations 2150-2192' with 2500 gallons 20% NEFE acid and ball sealers. Swabbing.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE 1-26-95

TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

APPROVED BY _____ TITLE _____ DATE FEB 13 1995

CONDITIONS OF APPROVAL, IF ANY: