Submit 3 Copies to Appropriate District Office

APPROVED BY-

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

FEB

DATE -

3 1994

AST

Diemier i			
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVA		WELL API NO.
• •	P.O. Bo		
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Me	exico 87504-2088	30-005-62989
		A	5. Indicate Type of Lease STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		JAN 6 1994	6. State Oil & Gas Lease No.
,,,			V-2717
SLINDRY NO.	TICES AND REPORTS ON	IWELLS	
(DO NOT USE THIS FORM FOR PE			
DIFFERENT RES	ERVOIR. USE "APPLICATION FO	OR PERMIT	7. Lease Name or Unit Agreement Name
	C-101) FOR SUCH PROPOSALS	.)	
l. Type of Well: OIL GAS —	_		
MET X MET	OTHER		Galway State
. Name of Operator			8. Well No.
ELK OIL COMPANY			1
Address of Operator			9. Pool name or Wildcat
Post Office Box 310,	Roswell, New Mexico	88202-0310	Wildcat San Andres
Well Location			
Section 25 I. Check NOTICE OF IN ERFORM REMEDIAL WORK MPORARILY ABANDON	Appropriate Box to India TENTION TO:	heiher DF, RKB, RT, GR, etc.) 1944' GR cate Nature of Notice, Re	SEQUENT REPORT OF: ALTERING CASING
		SOMMETOE BUILDING	OPNS PLUG AND ABANDONMENT
LL OR ALTER CASING		CASING TEST AND CE	
			MENT JOB
HER:		CASING TEST AND CE	MENT JOB
HER:	ations (Clearly state all pertinent deta	CASING TEST AND CE	MENT JOB
HER:	ations (Clearly state all pertinent deta	CASING TEST AND CEI OTHER:	MENT JOB
HER:	Propose to plug and	CASING TEST AND CE	MENT JOB
HER: 2. Describe Proposed or Completed Oper work) SEE RULE 1103. (1) F (2) S	Propose to plug and	CASING TEST AND CEI OTHER:	MENT JOB ing estimated date of starting any proposed OWS:
THER: 2. Describe Proposed or Completed Oper work) SEE RULE 1103. (1) F (2) S (3) In	Propose to plug and Fill hole with mud set 10 sx plug at surface	CASING TEST AND CE	MENT JOB ing estimated date of starting any proposed OWS:
HER: 2. Describe Proposed or Completed Oper work) SEE RULE 1103. (1) F (2) S (3) In	Propose to plug and Fill hole with mud set 10 sx plug at surfacents at 14 X 4 dry hole make the control of the	CASING TEST AND CEI OTHER:	MENT JOB
HER: 2. Describe Proposed or Completed Oper work) SEE RULE 1103. (1) F (2) S (3) In	Propose to plug and Fill hole with mud set 10 sx plug at surfacents at 14 X 4 dry hole make the control of the	CASING TEST AND CE	MENT JOB ing estimated date of starting any proposed OWS:
HER: 2. Describe Proposed or Completed Oper work) SEE RULE 1103. (1) F (2) S (3) In (4) L	Propose to plug and Fill hole with mud set 10 sx plug at surfacenstall 4 X 4 dry hole make evel and clean location.	CASING TEST AND CEI OTHER:	MENT JOB ing estimated date of starting any proposed OWS:
2. Describe Proposed or Completed Oper work) SEE RULE 1103. (1) F (2) S (3) In (4) L hereby certify that the information above is true	Propose to plug and Fill hole with mud set 10 sx plug at surfacenstall 4 X 4 dry hole make evel and clean location.	CASING TEST AND CEI OTHER:	ing estimated date of starting any proposed OWS: Part ID - 2 3 - 4 - 94 P4 H
THER: 2. Describe Proposed or Completed Oper work) SEE RULE 1103. (1) F (2) S (3) In (4) L thereby certify that the information above is true.	Propose to plug and Fill hole with mud set 10 sx plug at surfacenstall 4 X 4 dry hole make evel and clean location.	CASING TEST AND CEI OTHER:	MENT JOB ing estimated date of starting any proposed OWS: Part ID - 2 3 - 4-94 P4-A
THER: 2. Describe Proposed or Completed Oper work) SEE RULE 1103. (1) F (2) S (3) In (4) L thereby certify that the information above is true ignature	Propose to plug and Fill hole with mud set 10 sx plug at surfacenstall 4 X 4 dry hole make evel and clean location.	CASING TEST AND CEI OTHER:	ing estimated date of starting any proposed OWS: Part ID - 2 3 - 4 - 94 P4 H