

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

# OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-005-63012
3. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name Basil ANS Com
2. Name of Operator YATES PETROLEUM CORPORATION	8. Well No. 1
3. Address of Operator 105 South Fourth Street - Artesia, NM 88210	9. Pool name or Wildcat Pecos Slope Abo
4. Well Location Unit Letter <u>A</u> : <u>660</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>23</u> Township <u>7S</u> Range <u>25E</u> NMPM Chaves County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3679' GR

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	

### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <u>Perforate, acidize &amp; frac</u> <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-22-94 - Cleaned location. Cut off 4-1/2" casing and welded on bell nipple. Moved in and rigged up pulling unit. Pulled slips on 4-1/2" casing. TIH with 1600' of 1" tubing between 4-1/2" X 13-3/8". Cemented with 480 sacks Pacesetter Lite (65-35-6) (weight 12.8). TOOH with 1" tubing. Nippled up Larkin head and BOP. Picked up 3-7/8" bit, 4-1/2" scraper and 2-3/8" tubing. Tagged PBTD at 4155'. Displaced hole with 2% KCL. Tested casing to 2000#. TOOH with tubing. Rigged up wireline and ran GR/CBL log. Perforated 3679-3944' with 16 .42" holes as follows: 3679-3685' w/4 holes, 3843-3846' w/3 holes and 3930-3944' with 9 holes. 7-23-94 - TIH w/4-1/2" packer and RBP. Straddled perforations 3930-3944'. Acidized perfs. 3930-3944' with 900 gallons 7-1/2% NEFE acid with ball sealers. Moved tools and straddled perforations 3843-3846'. Acidized perforations 3843-3846' with 300 gallons 7-1/2% NEFE and ball sealers. Moved tools. Straddled perforations 3679-3685'. Acidized perforations 3679-85' with 400 gallons 7-1/2% NEFE acid and ball sealers. Released tools. TOOH. Nippled down BOP. Nippled up frac head. Frac'd perforations 3679-3944' (via 4-1/2" casing) with 136200 gallons 35# linear gel and 258200# 20-40 Brady sand. Shut in overnight.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE 7-27-94  
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505-748-1471

(This space for State Use)

SUPERVISOR, DISTRICT II

JUL 29 1994

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_