

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-005-63018
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Ladson State
8. Well No. #1
9. Pool name or Wildcat Diablo San Andres

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	RECEIVED
2. Name of Operator Hanson Operating Company, Inc.	SEP 21 '94
3. Address of Operator P.O. Box 1515, Roswell, New Mexico 88202-1515	O. C. D.
4. Well Location Unit Letter <u>J</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>990</u> Feet From The <u>East</u> Line Section <u>33</u> Township <u>10S</u> Range <u>27E</u> NMPM <u>Chaves</u> County	ARTESIA, OFFICE
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3764'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On September 9, 1994, plugging orders were given by Jim Morrow w/NMOCD.
The above captioned well was plugged and abandoned in the following manner:
On September 11, 1994, set a 30sx 100' Class "C" plug at 6605' top of Fusselman formation.
Waited 2 1/2 hours and tagged plug at 6512'. Set a 30sx 100' Class "C" plug at 6150'
top of Penn Formation. Set a 30sx 100' Class "C" plug at 4855' top of ABO Formation.
Set a 30sx 100' Class "C" plug at 1398' top of San Andres Formation.
Set a 30sx 100' Class "C" plug 50' in and 50' out the 8 5/8" casing shoe at 522'.
Waited 3 hours and tagged plug at 532'. Gary Williams witnessed this plug.
Set another 20sx of Class "C" cement at 524'.
Set a 10' Class "C" plug at surface.

Pat ID-2
10-14-94
P4A

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Patricia A. McGraw TITLE Production Analyst DATE 09/20/94
TYPE OR PRINT NAME Patricia A. McGraw TELEPHONE NO. 622-7330

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep II DATE 7-20-95
CONDITIONS OF APPROVAL, IF ANY: