			m 1 27 - m 1		CIST
Form 3160-5 June 1990)	UNITED DEPARTMENT ( BUREAU OF LAN			2 10 230 31 14 235	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 Lease Designation and Serial No.
Do not use this form	SUNDRY NOTICES AN n for proposals to drill o a "APPLICATION FOR P	D REPORTS OF or to deepen or re	NWELLS entry to a different +		NM-28162 If Indian, Allottee or Tribe Name
۰.		TRIPLICATE		7	If Unit or CA, Agreement Designation
1. Type of Well Oil Gas Well X Well	Other				Vell Name and No.
	UM CORPORATION	(50	05) 748–1471)		orpe MI Federal Com #1 NPI Well No.
	St., Artesia, NM Sec., T., R., M., or Survey Descri			10.	30-005-63058 Field and Pool, or Exploratory Area Pecos Slope Abo
-	0' FWL of Section		(Unit E, SWNW)	11.	County or Parish, State
12. CHECK A	PPROPRIATE BOX(s)	TO INDICATE N	ATURE OF NOTIC	E, REPORT,	
TYPE OF SI	TYPE OF SUBMISSION TYPE OF ACT				<u></u>
Notice of I	nient		ndonment	ַרָּ נ	Change of Plaus New Construction
X Subsequent	l Report		iging Back ing Repair		
L_] Final Abar	adonment Notice		ring Casing er <u>Intermediate c</u> cement	(	Conversion to Injection Dispose Water Note: Report results of multiple completion on Well Completion or Recompletion Report and 1 og form )
13. Describe Proposed or Comp	ons and measured and true vertical d	lenths for all markers and	roues betanent to any work?).		
give subsurface location TD 1600'. Rea (1602.88') of Float collar s 14.8). PD 6:3	ons and measured and true vertical d ached TD at 12:00 ( casing set at 160) set at 1558'. Cem 30 PM 3-3-97. Bum d tested to 1000#	lepths for all markers and PM 3-3-97. R O'. 1-Texas ented with 20 ped plug to 1 for 30 minute	an 39 joints of Pattern notched O sacks "C" and 000 psi, OK. C	8-5/8" 24 guide sho 2% CaCl2 ement did out at 6:	# J-55 8rd ST&C e set at 1600'. (yield 1.34, weight not circulate. WOC.
give subsurface location TD 1600'. Rea (1602.88') of Float collar s 14.8). PD 6:2 Nippled up and	ons and measured and true vertical d ached TD at 12:00 ( casing set at 160) set at 1558'. Cem 30 PM 3-3-97. Bum d tested to 1000#	lepths for all markers and PM 3-3-97. R O'. 1-Texas ented with 20 ped plug to 1 for 30 minute	an 39 joints of Pattern notched O sacks "C" and OOO psi, OK. C s, OK. Drilled 7/8". Resumed	8-5/8" 24 guide sho 2% CaCl2 ement did out at 6: drilling.	# J-55 8rd ST&C e set at 1600'. (yield 1.34, weight not circulate. WOC.
TD 1600'. Rea (1602.88') of Float collar s 14.8). PD 6: Nippled up and 11 hours and	ons and measured and true vertical d ached TD at 12:00 casing set at 160 set at 1558'. Cem 30 PM 3-3-97. Bum d tested to 1000# 30 minutes. Reduc	lepths for all markers and PM 3-3-97. R O'. 1-Texas ented with 20 ped plug to 1 for 30 minute	an 39 joints of Pattern notched O sacks "C" and OOO psi, OK. C s, OK. Drilled 7/8". Resumed	8-5/8" 24 guide sho 2% CaCl2 ement did out at 6: drilling.	# J-55 8rd ST&C e set at 1600'. (yield 1.34, weight not circulate. WOC.
give subsurface location TD 1600'. Rea (1602.88') of Float collar s 14.8). PD 6: Nippled up and 11 hours and 11 hours and 14 hereby certify that the f Signed Light	orregoing is true and correct	lepths for all markers and PM 3-3-97. R O'. 1-Texas ented with 20 ped plug to 1 for 30 minute ed hole to 7-	an 39 joints of Pattern notched O sacks "C" and OOO psi, OK. C s, OK. Drilled 7/8". Resumed	8-5/8" 24 guide sho 2% CaCl2 ement did out at 6: drilling. History 1997	# J-55 8rd ST&C e set at 1600'. (yield 1.34, weight not circulate. WOC.
give subsurface location TD 1600'. Rea (1602.88') of Float collar s 14.8). PD 6: Nippled up and 11 hours and 11 hours and	orregoing is true and correct	lepths for all markers and PM 3-3-97. R O'. 1-Texas ented with 20 ped plug to 1 for 30 minute ed hole to 7-	an 39 joints of Pattern notched O sacks "C" and OOO psi, OK. C s, OK. Drilled 7/8". Resumed	8-5/8" 24 guide sho 2% CaCl2 ement did out at 6: drilling. History 1997	# J-55 8rd ST&C e set at 1600'. (yield 1.34, weight not circulate. WOC. 00 AM 3-4-97. WOC

\$

\*See Instruction on Reverse Side