

Form C-103  
Revised 1-1-89

Energy, Minerals and Natural Resources Department

CISF  
H

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-005-63071
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	Ponderosa State
8. Well No.	#2
9. Pool name or Wildcat	SE Acme San Andres
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3933 GR

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Hanson Operating Company, Inc.
3. Address of Operator P.O. Box 1515, Roswell, NM 88202-1515	4. Well Location Unit Letter G : 1650 Feet From The North Line and 1650 Feet From The East Line Section 23 Township 8S Range 27E NMPM Chaves County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Hanson Operating Company, Inc. plans to plug & abandon the above well in the following manner:

10 sxs cement surface plug.  
Spot 25 sxs cement plug at 579'-479' and tag.  
Spot 25 sxs cement plug at 1045'-945' and tag.  
Circulate brine gel to surface.  
Run & set CIBP at 2020' with 35 sxs cement.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Betsy Speer TITLE Prod. Analyst DATE 2-14-01  
TYPE OR PRINT NAME Betsy Speer TELEPHONE NO. 505-622-7330

(This space for State Use)

APPROVED BY Mr. S. G. Gifford TITLE Field Rep. II DATE 2/20/2001  
CONDITIONS OF APPROVAL, IF ANY: