Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form	C-103
Ravis	ed 1-1-89

DISTRICT P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	
30-005-63078	
5. Indicate Type of Lease	

STATE 6. State Oil & Gas Lease No.

	77 0000
	V-2982
mmm	

SUNDRY NOTICES AND REPORTS					
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DIFFERENT RESERVOIR. USE "APPLICATION"	7. Lease Name or Unit Agreement Name				
(FORM C-101) FOR SUCH PROPOS	ALS.)	HAM I			
1. Type of Well:		tarinan name			
OIL GAS WELL OTHER	2	e CEIVE	Quincy AMQ State		
2. Name of Operator	UTI		8. Well Na		
YATES PETROLEUM CORPORATION			16		
3. Address of Operator		MAR 27 1997	9. Pool same or Wildcat		
105 South 4th St., Artesia, NM 88210			Acme San Andres, Southeast		
4. Well Location Unit Letter $\frac{N}{N}$: $\frac{330}{N}$ Feet From The $\frac{N}{N}$		l Con. P.	W _o		
Unit Letter N: 330 Feet From The 30	outh ""	Line and 10	Feet From The West Line		
10			NMPM Chaves County		
Section 12 Township 8S	Rai www.whether	nge 27E DF, RKB, RT, GR, etc.)	NMPM Chaves County		
		9' GR	<i>\(\(\(\(\(\(\) \\ \) \\ \)</i>		
11. Check Appropriate Box to I	ndicate N	Nature of Notice, F	eport, or Other Data		
NOTICE OF INTENTION TO:			SEQUENT REPORT OF:		
\Box	_				
PERFORM REMEDIAL WORK L PLUG AND ABANDO	ис	REMEDIAL WORK	ALTERING CASING		
TEMPORARILY ABANDON CHANGE PLANS		COMMENCE DRILLIN	G OPNS. PLUG AND ABANDONMENT		
PULL OR ALTER CASING		CASING TEST AND C	EMENT JOB		
OTHER:	_ 🗆	OTHER: Product	ion casing & cement X		
12. Describe Proposed or Completed Operations (Clearly state all pertine	nt details, an	d give pertinent dates, incl	uling estimated date of starting any proposed		
work) SEE RULE 1103.					
TD 2215'. Reached TD at 1:30 AM 3-22-	-97 R	an 54 joints o	f 5-1/2" 15.5 $\#$ casing as follows:		
l joint of 5-1/2" 15.5# J-55 sandblasted (42.00'); 4 joints of 5-1/2" 15.5# J-55 sand-					
blasted (160.37'): 12 joints of $5-1/2$ '	" 15.5#	J-55 varnishe	1 (496.90'); I marker joint		
(19 98') and 36 joints of $5-1/2$ " 15.5%	# J-55	varnished (149	5.85') (Total 2218.32') or		
casing set at 2215'. Regular guide sh	noe set	at 2214'. F1	oat collar set at 2171'.		

Waiting on completion unit.

at 6:00 PM 3-22-97.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. SKONATURE TITLE Operation	s Technician March 25, 1997
TYPEOR PRINT NAME Rusty Klein	<u>тецерноне но. 505/748-1</u> 471

Bottom marker joint set at 1494'. Cemented with 145 sacks 65-35 Poz C gel and 1/4#sack celloflake (yield 1.98, weight 12.4). Tailed in with 200 sacks "C", .6% FL62, 2% CD32 and .10% sodium metasilicate (yield 1.32, weight 14.8). PD 3:00 PM 3-22-97. Bumped plug to 1500 psi for 2 minutes, OK. Circulated 34 sacks. WOC. Released rig

ORIGINAL SIGNED BY TIM W. GUM (This space for State Use) DISTRICT II SUPERVISOR

APR 3 1997 TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED BY-