

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-005-63079
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	V-2982
7. Lease Name or Unit Agreement Name	Quincy AMQ State
8. Well No.	17
9. Pool name or Wildcat	Acme San Andres, Southeast
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3939' GR

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER ☐  
2. Name of Operator  
YATES PETROLEUM CORPORATION  
3. Address of Operator  
105 South 4th St., Artesia, NM 88210

4. Well Location  
Unit Letter N : 330 Feet From The South Line and 2310 Feet From The West Line  
Section 12 Township 8S Range 27E NMPM Chaves County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Perforate & acidize <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-7-97 - Cleaned location, set and tested anchors. Rigged up crane truck and wireline. TIH with logging tools and tagged PBDT at 2085'. TOOH with logging tools and rigged down wireline.

4-8-97 - Moved in and rigged up pulling unit. Nippled up BOP. TIH with bit, collars and 2-7/8" tubing. Tagged cement at 2116'. Rigged up swivel and drilled out 100' of cement to 2216'. Circulated well clean. TOOH with tubing, drill collars and bit. Rigged up wireline. TIH with logging tools and ran CNL/CBL/GR/CCL log. TOOH with logging tools and rigged down wireline. Shut well in.

4-9-97 - Rigged up wireline. TIH with 4" casing guns and perforated 2161-2200' w/79 .42" holes (San Andres). TOOH with casing guns and rigged down wireline. TIH with 2-3/8" tubing and seating nipple. Spotted 2 bbls acid. Pulled up and set seating nipple at 2113'. Acidized perforations 2161-2200' with 7000 gallons 20% HCL acid and ball sealers. Swabbing.

4-10-97 - Swabbed. Pumped 50 bbls 2% KCL. NU BOP. TOOH with tubing. TIH with production tubing. Released well to production department.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Operations Technician DATE April 10, 1997  
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM  
DISTRICT II SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE APR 17 1997

CONDITIONS OF APPROVAL, IF ANY: