IN 10037 DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT RECEIVED Auge of the set of the term of the interior of the interinterior of the interinterior of the interior of the interior of th				1 .		
SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS A 'I haims and intermed the segments, use "intermed" researcher, use "APPLICATION FOR PERMIT—" for such that state the segment, use "APPLICATION FOR PERMIT—" for such that state the segment is the Name SUBMIT IN TRIPLICATE Type of Well	rm 3160-5 ine 1990)	DEPARTMENT O	F THE INTERIOR	RECEIVE	D Budg Ex	t Bureau No. 1004-0135 pires: March 31, 1993
Do not use this form for proposals to drill or to deepen or result, the Part Present Part of the Part		BUREAU OF LAN	D MANAGEMENI			•
Do not use this form for proposals to drill or to deepen or repetcy the PURPERIATE BOTTOR TO PROPENT TO SULPHISTIC	SUN	NDRY NOTICES AN	D REPORTS ON W	ELLS	6. If Indian	
SUBMIT IN TRIPLICATE Type of Wall Type of Wall Concer Well Concer Nume of Operator Concer YATES PETROLEUM CORPORATION (505) 748-1421) Address and Telephone No. 30-005-63101 105 South 4th St., Artesia, NM 88210 10 Pold and Pold Telephone No. 125 South 4th St., Artesia, NM 88210 10 Pold and Pold Telephone No. 130' FSL & 2200' FEL of Section 13-765-R25E (Unit 0, SWSE) 10 Pold and Pold Telephone No. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA Chaves Co., NM TYPE OF SUBMISSION TYPE OF ACTION Notice of future Abandoment Bosequent Report Chaves The Concertion Notice Imaging Back Operation State Processing Concertion Notes Imaging Back Operatis State Processing Concertion Notes	Do not use this form fo Use ''/	or proposals to drill or APPLICATION FOR PE	r to deepen or reento ERMIT—" for suct pe	ABEAL OF LAND	MUMT.	
Type of Wall	<u>,</u>	SUBMIT IN	TRIPLIÇATE	- KUSWELL UFF		r CA, Agreement Designation
Nume of Operator Utility Tarks PETROLEUM CORPORATION Utility Tarks 14713 Tarks 14713 YATES PETROLEUM CORPORATION (505) 748-14713 0.47144 Mb. 0.47144 Mb. YATES PETROLEUM CORPORATION (505) 748-14713 0.47144 Mb. 0.47144 Mb. YATES PETROLEUM CORPORATION (505) 748-14713 0.47144 Mb. 0.47144 Mb. JOB South 4th St., Artesia, NM 88210 D. ATVed Mb. 0.47144 Mb. 0.47144 Mb. JOB South 4th St., Artesia, NM 88210 D. ATVed Mb. 9.47144 Mb. 0.47144 Mb. JOB South 4th St., Artesia, NM 88210 D. ATVed Mb. 9.47144 Mb. 9.47144 Mb. JOB South 4th St., Artesia, NM 88210 D. ATVed Mb. 9.47144 Mb. 9.47144 Mb. JOB South 4th St., Artesia, NM 88210 D. ATVed Mb. 9.47144 Mb. 9.47144 Mb. JOB South 4th St., Artesia, NM 8210 D. ATVed Mb. 9.47144 Mb. 9.47144 Mb. JOB South 4th St., Artesia, Mathematica, Mathem						e and No.
YATES PETROLEUM CORPORATION (505) 748-1471 30-005-63101 Address and Telephone No. 30-005-63101 30-005-63101 OS South 4th St., Artesia, NM 88210 10-Neid and Rod, or Exploratory Area Jacation of Well (Focue, See, T. R. M., or Surrey Description) 10-Neid and Rod, or Exploratory Area 330' FSL & 2200', FEL of Section 13-T6S-R25E (Unit 0, SWSE) 10-Neid and Rod, or Exploratory Area CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA - TYPE OF SUBMISSION TYPE OF ACTION Notice of Insut Anadameter Booker Completed Operations (Cherry and all periment data), and give periment data, including enhanced to thice the starting One represent the starting Final Abandonneet Notice Chaire and the starting One represent the starting Description of Cherry and all periment data), and give periment data work. ¹ Chaire at accompletion to the starting Prescription and maximut and maximut and analytic and the of starting and transmit and maximut and maximut and analytic and the starting of the starting of the starting of the starting and target of the starting transmit and maximut		Other	Ot	LUUN. P	Teck]	a MD Federal #9
105 South 4th St., Artesia, NM 88210 10 10 Fdd ad Fod, or Exploratory Area 26000 of Well (Fooage, Sec. T. R. M. or Surry Description) 330' FSL 6 2200', FEL of Section 13-TGS-R25E (Unit 0, SWSE) 10 Fdd ad Fod, or Exploratory Area 330' FSL 6 2200', FEL of Section 13-TGS-R25E (Unit 0, SWSE) I. Commy or Final, Sue Chaves Co., NM CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA . TYPE OF SUBMISSION TYPE OF Action Notice of Insen Abandonment New Construction Notice of Insen Pregging task New Construction Water Share Office Pregging task New Construction Other Perforate & frac Dispose Water Water Share Office Other Perforate & frac Dispose Water Water Share Office Precemption and memory during and preprint during training and preprint of the Water Share Office Observertice to complete document Notice The Perforate & frac Dispose Water Water Share Office Observertice to complete document Notice The Perforate & frac Dispose Water Water Share Office Observertice to complete document Notice The Perforate & frac Dispose Water Water Share Office Observertice to complete document Notece The Pereforate & frac <t< td=""><td></td><td>CORPORATION</td><td>(505)</td><td>748-1471)</td><td></td><td>No.</td></t<>		CORPORATION	(505)	748-1471)		No.
330' FSL & 2200' FEL of Section 13-T6S-R25E (Unit 0, SWSE) II. County or Pariah, Sure CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA Chaves Co., NM CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF SUBMISSION TYPE OF ACTION Bodie of states Chaves of the state of t	105 South 4th S				10. Field an	
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF SUBMISSION INDICATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION INDICATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA Notice of Inset INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA INDICATE NATURE OF NOTICE, AREA INDICATE NATURE OF NOTICE, AREA INDICATE NATURE OF NOTICE, AREA INDICATE NATURE OF NOTACE INDICATE NATURE				it O, SWSE)		
TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandoament Abandoament Change of Plans. Notice of Intent Recompletion Hugging Back Non-Routine Fracturing Image: Subsequent Report Hugging Back Non-Routine Fracturing Image: Subsequent Report Hugging Back How-Routine Fracturing Image: Subsequent Report Hugging Back Hugging Back Image: Subsequent Report Hugging Back Hugging Back Image: Subsequent Report Hugging Back Hugging Back Image: Subsequent Report Subsequent State S					C	haves Co., NM
Notice of linear Abandonment Mon-Routine Fracturing Describe Frant Abandonment Mon-Routine Fracturing Dispose Mater Abandonment Mon-Routine Fracturing Dispose Mater Maters Abandonment Abandonment Mon-Routine Fracturing Dispose Mater Abandonment Mon-Routine Fracturing Dispose Mater Maters Abandonment Mon-Routine Fracturing Dispose Mater Conversion to Injection Mon-Routine Fracturing Dispose Mater Conversion to Injection Mon-Routine Fracturing Dispose Mater (Describe Proposed or Completed Operations (Clearly state all perintent details, and give perintent dates, including estimated date of starting stary proposed work. If will afteronally diffied give substrifee teamints formaters and tested and stores perintent dates formaters and tested and stores perintent dates formaters and tested and content Stard and flowed wow Mireelline. Constances formaters and flowed maters and flowed well head. Rigged down pulling unit. Monade	CHECK APP	ROPRIATE BOX(s) T	O INDICATE NATU	RE OF NOTICE, R	EPORT, OR O	THER DATA 4
Bubsequent Repon Binal Abandonment Notice Becompletion Binal Abandonment Notice Becompletion Binal Abandonment Notice Binal Your A	TYPE OF SUBM	MISSION		TYPE OF AC	TION	
Image: Subsequent Report Image: Privaging Back Image: Non-Routine Fracturing Image: Privaging Back Image: Casing Repair Image: Casing Repair Image: Casing Repair Image: Privaging Back Image: Casing Repair Image: Casing Repair Image: Casing Repair Image: Privaging Back Image: Casing Repair Image: Casing Repair Image: Casing Repair Image: Privaging Back Image: Casing Repair Image: Casing Repair Image: Casing Repair Image: Privaging Back Image: Casing Repair Image: Casing Repair Image: Casing Repair Image: Privaging Back Image: Casing Repair Image: Casing Repair Image: Casing Repair Image: Privaging Back Image: Casing Repair Image: Casing Repair Image: Casing Repair Image: Privaging Back Image: Casing Repair Image: Casing Repair Image: Casing Repair Image: Privaging Back Image: Casing Repair Image: Casing Repair Image: Casing Repair Image: Casing Repair Image: Privaging Back Image: Casing Repair I	Notice of Inten	t	Abandoam	cnt		ge of Plans
Final Abandonment Notice						
Final Abandonment Notice Altering Calling Other_Perforate & frac Dispose Water Conversion to Injection Dispose Water Dispose Water Dispose Water Dispose Water Dispose Water (Describe Proposed or Completed Operations (Clearly state all perlinent data), and give perlinent data, including estimated date of starting any proposed work. If well is directionally drilled, give suboufface location, set and tested anchors. Rigged up wireline. TIH with logging tools and ran CBL/GR/CCL log. TOOH with logging tools. TIH with 3–3/8" casing guns and restrict 3776–3884' w/44 .38" holes as follows: 3776–3786' and 3874–3884' (2 SFF – Abo). TOOH with casing guns and rigged down wireline. 6–13–97 – Frac'd perforations 3776–3884' with 144350 gallons 20# crosslink gel and 400000# 16–30 Brady sand. Moved in and rigged up pulling unit. Shut well in for 30 minutes. Opened well up and flowed well back. TIH with tubing and tagged sand at 4080'. Washed 90' of sand to 4170'. Circulated well clean. Set seating nipple at 3704'. Nippled down BOP. Nippled up wellhead. Rigged down pulling unit. Moved in and rigged up foam unit. Unloadi fluid with foam unit. 6–14–16–97 – Continue to unload fluid with foam unit. ROSWELLAREA JUL 1 1997 BUREAU OF LAND MANAGEMENT JUL 1 1997 BUREAU OF LAND MANAGEMENT JUL 1 1997 BUREAU OF LAND MANAGEMENT June 27, 1997 Tite	LA Subsequent Rep	port				-
Pescribe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and twe vertical depths for all markers and zones periment to this work.)* Gongeteau Recompleted Operations (Clearly state all periment details, and give periment dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations, such measured and twe vertical depths for all markers and zones periment to this work.)* Gongeteau Recompleted Operations (Clearly state all clearly state and tests and toose periment to this work.)* Gongeteau Recompleted Operations and measured and twe vertical depths for all markers and zones periment to this work.)* Gongeteau Recompleteau Reco	Final Abandon	ment Notice				
Computing Repertant legions) Describe Proposed or Completed Operations (Clearly state all pertinent details, and give perlinent details, and g			X Other P	erforate & frac		
give ubsurface locations and measured and rue vertical depth for all markers and zones periments to this work.)* 6-12-97 - Cleaned location, set and tested anchors. Rigged up wireline. TIH with logging tools. TIH with 3-3/8" casing guns and perforated 3776-3884' w/44 .38" holes as follows: 3776-3786' and 3874-3884' (2 SPF - Abo). TOOH with casing guns and rigged down wireline. 6-13-97 - Frac'd perforations 3776-3884' with 144350 gallons 20# crosslink gel and 400000# 16-30 Brady sand. Moved in and rigged up pulling unit. Shut well in for 30 minutes. Opened well up and flowed well back. TIH with tubing and tagged sand at 4080'. Washed 90' of sand to 4170'. Circulated well clean. Set seating nipple at 3704'. Nippled down BOP. Nippled up wellhead. Rigged down pulling unit. Moved in and rigged up foam unit. Unloading fluid with foam unit. 6-14-16-97 - Continue to unload fluid with foam unit Released well to production department. Automation Automation Automation Table_Operations Technician Date JUL 1 1997 BUREAU OF LAND MANAGEMENT Noted in state office use Approved by					Completion	or Recompletion Report and Log form.)
6-12-97 - Cleaned location, set and tested anchors. Rigged up wireline. TIH with logging tools and ran CBL/GR/CCL log. TOOH with logging tools. TIH with 3-3/8" casing guns and perforated 3776-3884' w/44 .38" holes as follows: 3776-3786' and 3874-3884' (2 SPF - Abo). TOOH with casing guns and rigged down wireline. 6-13-97 - Frac'd perforations 3776-3884' with 144350 gallons 20# crosslink gel and 400000# 16-30 Brady sand. Moved in and rigged up pulling unit. Shut well in for 30 minutes. Opened well up and flowed well back. TIH with tubing and tagged sand at 4080'. Washed 90' of sand to 4170'. Circulated well clean. Set seating nipple at 3704'. Nippled down BOP. Nippled up wellhead. Rigged down pulling unit. Moved in and rigged up foam unit. Unloadin fluid with foam unit. 6-14-16-97 - Continue to unload fluid with foam unit. Released well to production department ACCEPTED FOR RECORD PETER W. CHESTER JUL 1 1997 BUREAU OF LAND MANAGEMENT ROSWELL RESOURCE AREA Signed With future to unload fluid with foam to the second perform RECORD PETER W. CHESTER JUL 1 1997 BUREAU OF LAND MANAGEMENT ROSWELL RESOURCE AREA June 27, 1997 The Date Date Date	Describe Proposed or Completed	d Operations (Clearly state all peri and measured and true vertical de	inent details, and give pertinent of puts for all markers and zones.	dates, including estimated date of pertinent to this work.)*	of starting any proposed	work. If well is directionally drilled,
TOOH with casing guns and rigged down wireline. 6-13-97 - Frac'd perforations 3776-3884' with 144350 gallons 20# crosslink gel and 400000# 16-30 Brady sand. Moved in and rigged up pulling unit. Shut well in for 30 minutes. Opened well up and flowed well back. TIH with tubing and tagged sand at 4080'. Washed 90' of sand to 4170'. Circulated well clean. Set seating nipple at 3704'. Nippled down BOP. Nippled up wellhead. Rigged down pulling unit. Moved in and rigged up foam unit. Unloading fluid with foam unit. 6-14-16-97 - Continue to unload fluid with foam unit. Released well to production department. Accepted for Record PETER W. CHESTER JUL 1 1997 BUREAU OF LAND MANAGEMENT A. Thereby cerify that the foregoing is style and correct Signed Title	6-12-97 - Cleane	ed location, set	and tested ancho OOH with logging	ors. Rigged up g tools. TIH w	ith 3-3/8" d	asing guns and
16-30 Brady sand. Moved in and rigged up pulling unit. Shut well in for 30 minutes. Opened well up and flowed well back. TIH with tubing and tagged sand at 4080'. Washed 90' of sand to 4170'. Circulated well clean. Set seating nipple at 3704'. Nippled down BOP. Nippled up wellhead. Rigged down pulling unit. Moved in and rigged up foam unit. Unloading fluid with foam unit. 6-14-16-97 - Continue to unload fluid with foam unit	COULS and Lan OF			s: 3776-3786'	1 2027 200	34' (2 SPF - Abo).
Opened well up and flowed well back. TIH with tubing and tagged sand at 4080'. Washed 90' of sand to 4170'. Circulated well clean. Set seating nipple at 3704'. Nippled down BOP. Nippled up wellhead. Rigged down pulling unit. Moved in and rigged up foam unit. Unloadin fluid with foam unit. 6-14-16-97 - Continue to unload fluid with foam unit Released well to production department PETER W. CHESTER JUL 1 1997 BUREAU OF LAND MANAGEMENT A 1 hereby certify that the foregoing is Mus and correct Signed	perforated 3776- TOOH with casing	g guns and rigged	l down wireline.			
of sand to 4170'. Circulated well clean. Set seating nipple at 3704'. Nippled down BOP. Nippled up wellhead. Rigged down pulling unit. Moved in and rigged up foam unit. Unloading fluid with foam unit. 6-14-16-97 - Continue to unload fluid with foam unit. Released well to production department ACCEPTED FOR RECORD PETER W. CHESTER JUL 1 1997 BUREAU OF LAND MANAGEMENT ROSWELL RESOURCE AREA JUL 27, 1997 (This space for Federal d'State office use) Approved by	perforated 3776- TOOH with casing 6-13-97 - Frac'd	g guns and rigged perforations 37	l down wireline. 776-3884' with la	44350 gallons 20	0# crosslinl	c gel and 400000#
fluid with foam unit. 6-14-16-97 - Continue to unload fluid with foam unit. Released well to production departme ACCEPTED FOR RECORD PETER W. CHESTER JUL 1 1997 BUREAU OF LAND MANAGEMENT A 1 hereby certify that the foregoing is thus and correct Signed	perforated 3776- TOOH with casing 6-13-97 - Frac'd 16-30 Brady sand	g guns and rigged l perforations 37 l. Moved in and	l down wireline. 76-3884' with la rigged up pullin	44350 gallons 20 ng unit. Shut	O∦ crosslin well in for	c gel and 400000# 30 minutes.
ACCEPTED FOR RECORD PETER W. CHESTER JUL 1 1997 BUREAU OF LAND MANAGEMENT A. I hereby certify that the foregoing is true and correct Signed	perforated 3776- TOOH with casing 6-13-97 - Frac'd 16-30 Brady sand Opened well up a of sand to 4170'	g guns and rigged l perforations 37 l. Moved in and and flowed well b . Circulated we	down wireline. 76-3884' with la rigged up pullin back. TIH with ell clean. Set	44350 gallons 2 ng unit. Shut tubing and tagg seating nipple	0# crosslin well in for ed sand at 4 at 3704'. 1	c gel and 400000# 30 minutes. 4080'. Washed 90' Nippled down BOP.
A I hereby certify that the foregoing is into and correct Signed	perforated 3776- TOOH with casing 6-13-97 - Frac'd 16-30 Brady sand Opened well up a of sand to 4170' Nippled up wellh fluid with foam	g guns and rigged l perforations 37 l. Moved in and and flowed well b d. Circulated we nead. Rigged dow unit.	down wireline. 76-3884' with la rigged up pullin back. TIH with ell clean. Set so m pulling unit.	44350 gallons 2 ng unit. Shut tubing and tagg seating nipple Moved in and	0# crosslin well in for ed sand at 4 at 3704'. I rigged up fo	c gel and 400000# 30 minutes. 4080'. Washed 90' Nippled down BOP. Dam unit. Unloadi
JUL 1 1997 A. I hereby certify that the foregoing is stue and correct BUREAU OF LAND MANAGEMENT Signed JUL Signed JUL Market Title Operations Technician Date June Approved by Title	perforated 3776- TOOH with casing 6-13-97 - Frac'd 16-30 Brady sand Opened well up a of sand to 4170' Nippled up wellh fluid with foam	g guns and rigged l perforations 37 l. Moved in and and flowed well b d. Circulated we nead. Rigged dow unit.	down wireline. 76-3884' with la rigged up pullin back. TIH with ell clean. Set so m pulling unit.	44350 gallons 2 ng unit. Shut tubing and tagg seating nipple Moved in and unit. Release	0# crosslin well in for ed sand at 4 at 3704'. I rigged up fo d well to p	c gel and 400000# 30 minutes. 4080'. Washed 90' Nippled down BOP. Dam unit. Unloadi
4. 1 hereby certify that the foregoing is true and correct Signed Image: State office use) (This space for Federal de State office use) Approved by	perforated 3776- TOOH with casing 6-13-97 - Frac'd 16-30 Brady sand Opened well up a of sand to 4170' Nippled up wellh fluid with foam	g guns and rigged l perforations 37 l. Moved in and and flowed well b d. Circulated we nead. Rigged dow unit.	down wireline. 76-3884' with la rigged up pullin back. TIH with ell clean. Set so m pulling unit.	44350 gallons 20 ng unit. Shut tubing and tagg seating nipple Moved in and unit <u>Release</u>	0# crosslin well in for ed sand at 4 at 3704'. I rigged up fo d well to p	c gel and 400000# 30 minutes. 4080'. Washed 90' Nippled down BOP. Dam unit. Unloadi
4. I hereby certify that the foregoing is true and correct BUREAU OF LAND MANAGEMENT 4. I hereby certify that the foregoing is true and correct Title_Operations Technician Signed June 27, 1997 (This space for Federal de State office use) Title	perforated 3776- TOOH with casing 6-13-97 - Frac'd 16-30 Brady sand Opened well up a of sand to 4170' Nippled up wellh fluid with foam	g guns and rigged l perforations 37 l. Moved in and and flowed well b d. Circulated we nead. Rigged dow unit.	down wireline. 76-3884' with la rigged up pullin back. TIH with ell clean. Set so m pulling unit.	44350 gallons 20 ng unit. Shut tubing and tagg seating nipple Moved in and unit <u>Release</u>	0# crosslin well in for ed sand at 4 at 3704'. I rigged up fo d well to p	c gel and 400000# 30 minutes. 4080'. Washed 90' Nippled down BOP. Dam unit. Unloadi
4. I hereby certify that the foregoing is the and correct Signed	perforated 3776- TOOH with casing 6-13-97 - Frac'd 16-30 Brady sand Opened well up a of sand to 4170' Nippled up wellh fluid with foam	g guns and rigged l perforations 37 l. Moved in and and flowed well b d. Circulated we nead. Rigged dow unit.	down wireline. 76-3884' with la rigged up pullin back. TIH with ell clean. Set so m pulling unit.	44350 gallons 20 ng unit. Shut tubing and tagg seating nipple Moved in and unit <u>Release</u> PETER	O# crosslin well in for ed sand at 4 at 3704'. I rigged up for d well to p ED FOR RECORD W. CHESTER	c gel and 400000# 30 minutes. 4080'. Washed 90' Nippled down BOP. Dam unit. Unloadi
4. I hereby certify that the foregoing is the and correct Signed	perforated 3776- TOOH with casing 6-13-97 - Frac'd 16-30 Brady sand Opened well up a of sand to 4170' Nippled up wellh fluid with foam	g guns and rigged l perforations 37 l. Moved in and and flowed well b d. Circulated we nead. Rigged dow unit.	down wireline. 76-3884' with la rigged up pullin back. TIH with ell clean. Set so m pulling unit.	44350 gallons 20 ng unit. Shut y tubing and tagg seating nipple Moved in and unit <u>Release</u> PETER JUL	0# crosslin well in for ed sand at 4 at 3704'. I rigged up for d well to p D FOR RECORD W. CHESTER 1 1997	t gel and 400000# 30 minutes. 4080'. Washed 90' Nippled down BOP. Dam unit. Unloadin coduction departmen
Signed Date (This space for Federal de State office use) Title Approved by Title	perforated 3776- TOOH with casing 6-13-97 - Frac'd 16-30 Brady sand Opened well up a of sand to 4170' Nippled up wellh fluid with foam	g guns and rigged l perforations 37 l. Moved in and and flowed well b d. Circulated we nead. Rigged dow unit.	down wireline. 76-3884' with la rigged up pullin back. TIH with ell clean. Set so m pulling unit.	44350 gallons 20 ng unit. Shut y tubing and tagg seating nipple Moved in and unit <u>Release</u> <u>ACCEPTE</u> <u>PETER</u> JUL	0# crosslin well in for ed sand at 4 at 3704'. I rigged up for d well to p D FOR RECORD W. CHESTER 1 1997	t gel and 400000# 30 minutes. 4080'. Washed 90' Nippled down BOP. Dam unit. Unloadin coduction departmen
Approved by Date Title	perforated 3776- TOOH with casing 6-13-97 - Frac'd 16-30 Brady sand Opened well up a of sand to 4170' Nippled up wellh fluid with foam 6-14-16-97 - Con	g guns and rigged l perforations 37 l. Moved in and and flowed well b '. Circulated we nead. Rigged dow unit. ntinue to unload	down wireline. 76-3884' with la rigged up pullin back. TIH with ell clean. Set so m pulling unit.	44350 gallons 20 ng unit. Shut y tubing and tagg seating nipple Moved in and unit <u>Release</u> <u>ACCEPTE</u> <u>PETER</u> JUL	0# crosslin well in for ed sand at 4 at 3704'. I rigged up for d well to p D FOR RECORD W. CHESTER 1 1997	t gel and 400000# 30 minutes. 4080'. Washed 90' Nippled down BOP. Dam unit. Unloadin coduction departmen
	perforated 3776- TOOH with casing 6-13-97 - Frac'd 16-30 Brady sand Opened well up a of sand to 4170' Nippled up wellh fluid with foam 6-14-16-97 - Com	g guns and rigged l perforations 37 l. Moved in and and flowed well b '. Circulated we nead. Rigged dow unit. ntinue to unload	down wireline. 76-3884' with 14 rigged up pullin back. TIH with ell clean. Set on pulling unit. fluid with foam	44350 gallons 20 ng unit. Shut t tubing and tagg seating nipple Moved in and unit <u>Release</u> <u>ACCEPTE</u> <u>PETER</u> JUL BUREAU OF LAN <u>ROSWELL RE</u>	0# crosslin well in for ed sand at a at 3704'. I rigged up fo d well to p D FOR RECORD W. CHESTER 1 1997 ND MANAGEMEN SOURCE AREA	t gel and 400000# 30 minutes. 4080'. Washed 90' Nippled down BOP. Dam unit. Unloadin coduction department
	perforated 3776- TOOH with casing 6-13-97 - Frac'd 16-30 Brady sand Opened well up a of sand to 4170' Nippled up wellh fluid with foam 6-14-16-97 - Com	g guns and rigged l perforations 37 l. Moved in and and flowed well b d. Circulated we nead. Rigged dow unit. htinue to unload	down wireline. 76-3884' with 14 rigged up pullin back. TIH with ell clean. Set on pulling unit. fluid with foam	44350 gallons 20 ng unit. Shut t tubing and tagg seating nipple Moved in and unit <u>Release</u> <u>ACCEPTE</u> <u>PETER</u> JUL BUREAU OF LAN <u>ROSWELL RE</u>	0# crosslin well in for ed sand at a at 3704'. I rigged up fo d well to p D FOR RECORD W. CHESTER 1 1997 ND MANAGEMEN SOURCE AREA	t gel and 400000# 30 minutes. 4080'. Washed 90' Nippled down BOP. Dam unit. Unloadin coduction department
	perforated 3776- TOOH with casing 6-13-97 - Frac'd 16-30 Brady sand Opened well up a of sand to 4170' Nippled up wellh fluid with foam 6-14-16-97 - Con	g guns and rigged l perforations 37 l. Moved in and and flowed well b . Circulated we nead. Rigged dow unit. ntinue to unload	down wireline. 76-3884' with 14 rigged up pullin back. TIH with ell clean. Set on pulling unit. fluid with foam 	44350 gallons 20 ng unit. Shut t tubing and tagg seating nipple Moved in and unit <u>Release</u> <u>ACCEPTE</u> <u>PETER</u> JUL BUREAU OF LAN <u>ROSWELL RE</u>	0# crosslin well in for ed sand at a at 3704'. I rigged up fo d well to p D FOR RECORD W. CHESTER 1 1997 ND MANAGEMEN SOURCE AREA Date	t gel and 400000# 30 minutes. 4080'. Washed 90' Nippled down BOP. Dam unit. Unloadin coduction department June 27, 1997

a sama a

. .

*See Instruction on Reverse Side