

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.  
30-005-63107

5. Indicate Type of Lease  
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

McClintock Fee

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator  
Marbob Energy Corp.

8. Well No.  
1

3. Address of Operator  
P.O. Box 227, Artesia N.M. 88210

9. Pool name or Wildcat  
Twin Lakes; Devonian,  
Southwest

4. Well Location  
Section 30 Township 9-S Range 28-E NMPM Chaves N.M. County  
Feet From The North Line and 508 Feet From The West Line

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3888 G.R.

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, including estimated date of starting any proposed work) SEE RULE 1103.

- (1) Set 5 1/2 CIBP at 6735' cap w/35' cement
- (2) Load hole w/mud 10# brine w/2s # gel / barrel.
- (3) Cut 5 1/2 casing at free point and pull out of hole
- (4) Spot 100' cement plug at 5 1/2 stub 50' in and 50' out and tag
- (5) Spot 100' cement plug at 8 5/8 shoe 50' in and 50' out and tag
- (6) Spot 100' cement plug at 13 3/8 shoe 50' in and 50' out and Tag.
- (7) Spot 05" surface plug and spot P & A marker

4d Spot 100' plug @ 3200-3100'.

Notify N.M.O.C.C. in sufficient time to witness

Tags

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Raymond Maldonado TITLE Supervisor DATE 4-14-97

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

APPROVED BY Tim W. Evans B6N TITLE District Supervisor DATE 4-28-97

CONDITIONS OF APPROVAL, IF ANY: