Submit 3 Copies to Appropriate District Office

State of New Mexico En., Minerals and Natural Resources Department

F	erm C-10	cl	51
1	erm C-100 levised 1-1	-89 17	1'
		- 1	1

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION P.O. Box 2088

WELL API NO. 30-005-63118

P.O. Drawer DD, Artesia, NM 88210

Santa Fe, New Mexico 87504-2088

5. Indicate Type of Lease FEE X STATE

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410

6. State Oil & Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERIME IVE 1. Type of Well: WELL X WELL Sacra SA Com OTHER 8. Well No. 2. Name of Operator YATES PETROLEUM CORPORATION 9. Pool name or Wildcat 3. Address of Operator 105 South 4th St., Artesia, NM 88210 Pecos Slope Abo 4 Well Location Line and $_1500$ J: 2310 Feet From The South Feet From The East Line Unit Letter __ County hip 6S Range 25E 10. Elevation (Show whether DF, RKB, RT, GR, etc.) **NMPM** Chaves 34 Township Section 3711' GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: ALTERING CASING REMEDIAL WORK PLUG AND ABANDON PERFORM REMEDIAL WORK PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. **CHANGE PLANS** TEMPORARILY ABANDON CASING TEST AND CEMENT JOB **PULL OR ALTER CASING** OTHER: Perforate & frac OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 5-22-97 - Cleaned location, set and tested anchors. Rigged up wireline. TIH with logging tools and ran CBL/GR/CCL log. TOOH with logging tools. TIH with 3-3/8" casing guns and perforated 3608-3673' w/50 .38" holes as follows: 3608-14, 3630-3634, 3648-3653 and 3667-3673' (2 SPF - Abo). TOOH with casing guns and rigged down wireline. Nippled up frac valve. Frac'd perforations 3608-3673' with 144350 gallons 20# crosslink gel and 400000# 16-30 Brady sand. Shut well in for 30 minutes. Opened well up and flowed well down overnight. 5-23-97 - Moved in and rigged up pulling unit. Nippled down frac valve. Nippled up BOP. TIH with seating nipple and tubing. Tagged sand at 3669'. Washed sand down to 4000'. Circulated well clean. Pulled up and set seating nipple at 3539'. Nippled down BOP. Nippled up wellhead. Swabbing. 5-24-97 - Continue to swab. 5-25-27-97 - Continue to swab. Released well to production department. information above is true and complete to the best of my knowledge and belief.

I hereby certify that the

TYPE OR PRINT NAME

SIGNATURE _

APPROVED BY-

DELCTION OF THE W. GUM

Rusty Klein

GISTRICT H SUPERVISOR

mma Operations Technician

JUN 1 0 1997

DATE May 29, 1997

TELEPHONE NO. 505/748-14

CONDITIONS OF APPROVAL, IF ANY: