DISTRICT I PO. Box 1980, Hobbs, NM 88240 PO. Box 1980, Hobbs, NM 88240 PO. Box 2088 Santa Fe, New Mexico 87504-2088 Santa Fe, New Mexico 87504-2088 Sindicate Type of Lease STATE 6. State Oil & Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE 'APPLICATION FOR PERMIT' (FORM C-101) FOR SUCH PROPOSALS) 1. Type of Well: OR. Wall C. Wall OR. Wall C. Artesia, NM 88210 2. Name of Operator YATES PETROLEUM CORPORATION 3. Address of Operator YATES PETROLEUM CORPORATION 3. Address of Operator YATES PETROLEUM CORPORATION 3. Address of Operator YATES PETROLEUM CORPORATION 3. Mell Location Unit Latter E: 1980 Feet From The North Line and 1300 Feet From The West Section 23 Township 7S Range 25E NMPM Chaves Section 23 Township 7S Range 25E NMPM Chaves 10. Elevation (Show whather DF, RKB, RT, GR, stc.) 3670' GR 10. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASI TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABA PULL OR ALTER CASING OTHER: Spud & conductor OTHER: Spud & conductor 12. Describe Proposed or Completed Operations (Clearly state all perinent details, and give perinent datas, including estimated data of starting any propowort) SEE RULE 1103. Spudded a 20" hole with rat hole machine at 1:45 PM 7-30-97. Set 40' of 16" conpipe. Cemented to surface. NOTE: Notified OCD-Artesia of spud.	
YATES PETROLEUM CORPORATION 3. Address of Operator 105 South 4th St., Artesia, NM 88210 4. Well Location Unit Letter E: 1980 Feet From The North Line and 1300 Feet From The West Section 23 Township 7S Range 25E NMPM Chaves 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3670 GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASI TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABA PULL OR ALTER CASING OTHER: Spud & conductor 12. Describe Proposed or Completed Operations (Clearly state all periment details, and give pertinent dates, including estimated date of starting any propowork) SEE RULE 1103. Spudded a 20" hole with rat hole machine at 1:45 PM 7-30-97. Set 40' of 16" cor	FEE X
4. Well Location Unit Letter E: 1980 Feet From The North Section 23 Township 7S Range 25E NMPM Chaves 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3670 ' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASI TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABA PULL OR ALTER CASING OTHER: Spud & conductor 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proportion work) SEE RULE 1103. Spudded a 20" hole with rat hole machine at 1:45 PM 7-30-97. Set 40' of 16" cor	
Spudded a 20" hole with rat hole machine at 1:45 PM 7-30-97. Set 40' of 16" cor	NG
pipe. demented to surface. Note. Notified our-Artesia of spud.	
TD 40'. Waiting on rotary tools.	- Section
AUG 1 8 1997 OUL WORD. POU	∭ .

SIGNATURE TYPE OR PRINT NAME RUSTLY Klein

Operations Technician

DATE Aug. 11, 1997

THE PHONE NO. 505/748-1

(This space for State Use)

APPROVED BY DISTRICT II SUPERVISOR

AUG. 18 1997

THE DATE Aug. 11, 1997

THE PHONE NO. 505/748-1

CONDITIONS OF APPROVAL, IF ANY: