

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-005-63124
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name Spool SU
2. Name of Operator YATES PETROLEUM CORPORATION	8. Well No. 8
3. Address of Operator 105 South 4th St., Artesia, NM 88210	9. Pool name or Wildcat Pecos Slope Abo
4. Well Location Unit Letter <u>E</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>1300</u> Feet From The <u>West</u> Line Section <u>23</u> Township <u>7S</u> Range <u>25E</u> NMPM Chaves County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3670' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: Perforate, acidize & frac ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-6-8-97 - Rigged up wireline. TIH with logging tools and ran Sonic & CNL logs. TOOH with logging tools and TIH with logging tools and ran CBL log. TOOH with logging tools and rigged down wireline. Cleaned location, set and tested anchors. Moved in and rigged up pulling unit. Nippled up BOP. Rigged up wireline. TIH with 3-1/8" casing guns and perforated 3624-3931' w/27 .38" holes as follows: 3624, 28, 30, 32, 34, 3721, 23, 25, 27, 29, 65, 67, 77, 79, 87, 89, 3827, 29, 31, 33, 35, 67, 87, 3925, 27, 29 & 3931'. TOOH with casing guns and rigged down wireline. TIH with RBP, packer and tubing. Straddled perforations 3827-3931'. Acidized with 500 gallons 7-1/2% NEFE HCL acid & ball sealers. Moved tools and straddled perforations 3721-3789'. Acidized with 500 gallons 7-1/2% NEFE HCL acid and ball sealers. Moved tools and straddled perforations 3624-3634'. Acidized with 400 gallons 7-1/2% NEFE HCL acid and ball sealers. TOOH with RBP, packer and tubing.  
9-9-97 - Frac'd perforations 3624-3931' (Abo) with 50000 gallons 20# guar gel and 100000# 20-40 Brady sand. Shut well in overnight.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

CONTINUED ON NEXT PAGE:

SIGNATURE Rusty Klein TITLE Operations Technician DATE Sept. 12, 1997  
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM  
DISTRICT II SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

SEP 26 1997

CONDITIONS OF APPROVAL, IF ANY: