j	RA	Oi.	ons.	Division
M.	0.06	•••		

	•	- 12 a	Oi. ons. [Division	0/5			
	INTERNATION OF A TELE		101		. ,			
form 3160-5 June 1990)	UNITED STATES	A LINES DE LOS	M 3821	0-2884t Bureau No. 1004-011	35			
Julie 1990)	DEPARTMENT OF THE I			Expires: March 31, 1993 Lease Designation and Serial No.				
	BUREAU OF LAND MAN	AGEMENT		•				
S	SUNDRY NOTICES AND REPO	RTS ON WELLS	<u> -</u> ;	NM-93184 5. If Indian, Allottee or Tribe Nam				
Do not use this form	n for proposals to drill or to deep "APPLICATION FOR PERMIT—	en or reentry to a different		, I Indian, Amorece of Thee trans				
	SUBMIT IN TRIPLIC	CATE		7. If Unit or CA, Agreement Desi	gnation			
I. Type of Well		A A		. Well Name and No.				
Oil X Gas Well Name of Operator	Other			Jasper ARJ Federa	1 #1			
YATES PETROLE	UM CORPORATION	(505) 748 -1471)	9	. API Well No.				
3. Address and Telephone No.		Och ARI	IFOIX	30-005-63142				
	St., Artesia, NM 88210		3.2	0. Field and Pool, or Exploratory				
	Sec., T., R., M., or Survey Description)	and the second second		Foor Ranch Precamb	orian			
660' FSL & 175	O' FEL of Section 25-T8S	-R26E (Unit Q, SWSE)		1. County of Parish, State				
		The second secon		Chaves Co., N	νf			
		OATE MATURE OF MOT	LOE DEBORT		. 34			
12. CHECK AI	PPROPRIATE BOX(s) TO INDI	TATE NATURE OF NOT	ICE, REPORT	, OR OTHER DATA	. 14			
TYPE OF SU	JBMISSION	TYPE	OF ACTION					
Notice of I	ntent	Abandonment		Change of Plans				
		Recompletion		New Construction				
X Subsequent	Report	Plugging Back		Non-Routine Fracturing				
r		Casing Repair		Water Shut-Off				
Final Abar	donment Notice	Altering Casing X Other Perforate &	frac Abo	Conversion to Injection Dispose Water				
		[A] Other Terrorace a		(Note: Report results of multiple completion or Recompletion Report an				
13. Describe Proposed or Comp	oleted Operations (Clearly state all pertinent details	, and give pertinent dates, including estim	nated date of starting ar	ny proposed work. If well is direction	onally drilled,			
give subsurface location	ons and measured and true vertical depths for all d in and rigged up pulli	markers and zones pertinent to this work	wireline.	TIH with 1.875"	gauge			
12-9-9/ - Move	d on/off tool. TOOH. TI	H with 1.875" select	t lock blan	king plug. Set i	n			
on/off tool at	6236' Bled well down.	Loaded and tested	to 600 psi	. Nippied up bor	•			
Pologod on/of	f tool TOOH with tubin	 TIH with RBP and 	d set KB₽⊸a	t 5200°. 100H.				
12_10_07 - Rio	and un wireline. TIH wi	th 4" casing guns ar	na periorat	ed litto-litto Mil	6			
42" holos (4	SPF - Abo). TOOH with c	asing guns and rigge	ed down wir	eline. Ilu with				
alram and tub	ling Shut down due to h	igh winds. Packer s	set at 3000	. Shut well in.	+			
	rished TIH with tubing to	4900'. Shut well:	ın. Kigged	down pulling uni	, L •			
Waiting to frac.								
12 16 07 Mov	12-12-15-97 - Prep to frac. 12-16-97 - Moved in and rigged up pulling unit. TOOH with tubing. Nippled down BOP and							
Lorlin hard Ninnled up frac valve. Frac'd perforations 5110-5118 (Via 5-1/2 casing)								
with 30000 gal	llons 20# linear gel and	60000# 20-40 Brady	sand. Pres	ssured out with 84	, ·			
with 30000 gallons 20# linear gel and 60000# 20-40 Brady sand. Pressured out with 84 bbls flush (37 bbls shy of full flush). Shut well in overnight. 12-17-97 - Nippled down frac head. Nippled up BOP. TIH with retrieving tool. Tagged								
12-17-97 - Nip	opled down frac head. Ni	ppled up BOP. TIH	with retrie	ving tool. lagge	ia irc-			
sand at 4840'	Rigged up stripper hea	d and swivel. Wash	ed sand to	atched onto packe	r with			
ulated clean.	Released RBP. TOOH. T ng plug. Released packet	. TOOH TIH With	seating nir	ople and tubing.				
/ /		. 100m. III wien						
14. I hereby certify that the f				JED ON NEXT PAGE:				
Signed & usty	of fler Ti	le <u>Operations Techni</u>		EFFER FOR RECORD) 98			
(This space for Federal o	r State office use)		PELE	R W. CHESTER	<u> </u>			
Approved by	Ti	ile		Date				
Conditions of approval, i	f any:		£					
	•		- J JAN	J T				