

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-005-63145
Indicate Type of Lease STATE ☐ FEE ☒
State Oil & Gas Lease No.
Lease Name or Unit Agreement Name Ramos FEE
Well No. 2
Pool name or Wildcat Long Arroyo, Dev., NE

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER	
Name of Operator Marbob Energy Corporation	
Address of Operator P.O. Box 227 Artesia, N.M. 88210	
Well Location Unit Letter <u>F</u> : <u>2596</u> Feet From The <u>North</u> Line and <u>2027</u> Feet From The <u>West</u> Line Section <u>33</u> Township <u>12S</u> Range <u>28E</u> NMPM Chaves County	
Elevation (Show whether DF, RKB, RT, GR, etc.) 3605' GR	

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ANBANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Notify OCD 24 Hrs. before starting plugging

1. POH w/ tubing
2. Set 5 1/2 CIBP @ 8100 (perf 8134 - 8177) cap w/ 35' cmt.
3. Spot 100' plug @ ~~5970~~ 5970-6070' inside? outside of csg.
4. Spot 100' plug @ ~~5040~~ 5040-5140' inside? outside of csg. ← 100' plug inside? outside of csg 2815'-2915'
5. Spot 100' plug @ 1680 (8 5/8 shoe @ 1630) woc tag 1580-1680 - in? outside of csg TAG
6. Spot 100' plug @ 365' (13 3/8 shoe @ 311) woc tag 245'-365' - inside? outside of csg. TAG
7. Spot 60' plug from 60' to surface 60' plug 0-60' inside? outside of csg.
8. Cut off well head install dry hole marker

Salt gel mud consisting of 10#
Brine W/25# of gel per bbl
must be placed between each plug

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE PRODUCTION ANALYST DATE 10/2/02

TYPE OR PRINT NAME _____ TELEPHONE NO. _____

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep ID DATE OCT 18 2002

CONDITIONS OF APPROVAL, IF ANY: