
	CISI		
Submit 3 Copies To Appropriate Fistrict State of New Mexico	Form C-103		
Office Energy, Minerals and Natural R	esources Revised March 25, 1999		
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.		
District II 811 South First, Artesia, NM 88210 OIL CONSERVATION DIV	VISION 30005-63194  5. Indicate Type of Lease		
District III 2040 South Pacheco	STATE FEE		
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District IV	6. State Oil & Gas Lease No.		
2040 South Pacheco, Santa Fe, NM 87505	o. Date of the East 14.		
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name:		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BAD DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SU	CK TO A  CH  Twin Lakes San Andres Unit		
PROPOSALS.)  1. Type of Well:			
Oil Well Gas Well Other Injection			
2. Name of Operator	7. Well No. 311		
Concho Oil & Gas Corp.	8. Pool name or Wildcat		
3. Address of Operator 110 W. Louisiana Ste 410; Midland, Tx 79701	Twin Lakes; San Andres (Assoc)		
4. Well Location			
Unit Letter D: 1700 Feet from the North line and	nd 990 feet from the West line		
Section 31 Township 8S Rang			
10. Elevation (Show whether DR, RK	B, RT, GR, etc.)		
3978 GR	of Notice Penert or Other Data		
11. Check Appropriate Box to Indicate Nature	SUBSEQUENT REPORT OF:		
NOTICE OF INTENTION TO:	MEDIAL WORK ALTERING CASING		
PERIOR OR METALE MOTOR CONTROL OF THE PERIOR			
TEMPORTULE TO THE STATE OF THE	MMENCE DRILLING OPNS. PLUG AND ABANDONMENT		
FULL ON ALIEN ONOMO	SING TEST AND  MENT JOB		
F7 OT	HER: MIT/TEMPORARILY ABANDON		
Official and the second of the			
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.			
-			
Concho Oil & Gas Corp. respectfully requests approval to plug and abandoned the Twin Lakes San Andres Unit			
#311 according to the following procedure:	22 2324 2526 2738 P9 30 37 PS OCD - ARTESIA		
<ol> <li>Notify NMOCD Artesia 24 hrs prior to commencement.</li> <li>Set 200' plug @ 2550-2750'. — Tag</li> </ol>	32223242520		
2. Set 200' plug @ 2550-2750'. — / 49 3. Circ hole w/ mud	2011		
4 C-4 400' plus @ 4000 2000'			
5. Set 100' plug @ <del>1580-1680</del> '. 1450' - 755°	/2 of 1991 93		
6. Set 100' plug @ 895-995'.	PECEIVED 33		
7. Circ cement from 160' to surface.	OCD - ARTESIA		
8. Cut off wellhead & install dry hole marker.	DET 1001  PECEIVED  OCD - ARTESIA		
I hereby certify that the information above is true and complete to the best	of my knowledge and belief.		
SIGNATURE TITLE P	roduction Analyst DATE 10-22-01		
Type or print name Perri Stathem Teler	phone No. 915/683-7443		
(This space for State use)	1-11/		
	suld the E DATE 10.29 AL		
APPPROVED BY TITLE Conditions of approval, if any:	DATE 10.29.01		

TO ALL AND ALL
vani
er or
- Carrier
A RANGE
The state of the s
The state of the s
To the second se
The state of the s
LE STATE OF THE ST
The state of the s
Personal
The second secon
T-8-055
CA COLOR
The second secon
V-A
The second management of the second management

## TLSAU #311



Original Perf Details: P1: 2668-74, 2681-83, 2689-91, 2695-99, 2701-03, 2706-08

BJ acidized w/ 6000 gals 20%

Feb-99 Reperforate and Halliburton acidized w/ 10000 gals 20%