			-	1210
		N M Oil CO	ons. Divisior	1
Form 3160-5	UNITED STAT	ES 1et St	reet	FORM APPROVED Budget Bureau No. 1004-0135
(June 1990)	DEPARTMENT OF THE	INTERIORI I S. ISI O	88210-2834	Expires: March 31, 1993
	BUREAU OF LAND MAI	AGEMEIAriosia, INM	UULIV LU	5. Lease Designation and Serial No.
SUNDF	RY NOTICES AND REP	ORTS ON WELLS	, -	NM-27061 6. If Indian, Allottee or Tribe Name
Do not use this form for p Use "APP	roposals to drill or to dee LICATION FOR PERMIT-		ent reservoir.	
·	SUBMIT IN TRIPL	ICATE	A 6	7. If Unit or CA, Agreement Designation
I. Type of Well Oil Gas Well X Well Other		i Rea	A 12	8. Well Name and No.
2. Name of Operator		OCD CD CET	En · ·	Crosby TV Federal #2
YATES PETROLEUM CO	RPORATION V	(505) 748-1471	J. 5	9. API Well No.
3. Address and Telephone No.	Antonia NM 99210		े ्रे/	<u>30-005-63218</u>
4. Location of Well (Footage, Sec., T.,	Artesia, NM 88210			10. Field and Pool, or Exploratory Area
1610' FNL & 1980' F	• •	8S-R25E (Unit F. SF	(NW)	Pecos Slope Abo
		ob 11152 (onite 1) 51		
	·····			Chaves Co., NM
12. CHECK APPROI	PRIATE BOX(s) TO IND	ICATE NATURE OF NO	DTICE, REPOR	T, OR OTHER DATA
TYPE OF SUBMISS	ION	וד	PE OF ACTION	
Notice of Intent		Abandonment		Change of Plans
Ŧ				New Construction
X Subsequent Report		Plugging Back		Non-Routine Fracturing
Final Abandonment I	Nation	Casing Repair		Water Shut-Off
	voice	Altering Casing X _{Other} Perforate,	acidize &	Conversion to Injection
		frac		Dispose Water Note: Report results of multiple completion on Well
13. Describe Proposed or Completed Oper	rations (Clearly state all pertinent detai	s, and give pertinent dates, including e	stimated date of starting a	Completion or Recompletion Report and Log form.) iny proposed work. If well is directionally drilled
2-26-28-2000 - Clea	and the second and the second and the second s	markers and zones permient to this	work.)*	
and rigged up pulli				" cut off. Moved in
2-29-2000 - TIH wit				D at 5276'. TOOH
with bit, scraper a	nd tubing. Rigged	up wireline. TIH	with logging	tools and ran GR/CCL/
CBL log. TOOH with	logging tools. The	"H with 4" casing g	uns and perf	orated 5178-5196' w/38
.49" holes (2 SPF - well in for night.	Ordovician). TOOP	l with casing guns	and rigged d	own wireline. Shut
3-1-2000 - TIH with	packer and RBP.	Set RBP at 5220' an	d packer at	5060' Acidized
perforations 5178-5	196' w/2000 gallons	15% iron control	acid and bal	1 sealers. Swabbed.
Shut well in.				
3-2-2000 - Bled wel		Shut well in.		
wireline. TIH with	Unset packer and	RBP. TOOH with pa	cker, RBP and	d tubing. Rigged up
TIH with stinger an	d tubing. Sting in	in set retainer at	tablished in	ed down wireline.
BPM at 1750 psi. M	ixed and pumped 200	sacks Class C wit	h .5% D112 a	nd .2% D46. Squeezed
perforations to 200	0# with 192 sacks i	n formation. Stin	g out of ret	ainer. Reversed 8
sacks to pit. Pull			7 16 1	
3-4-6-2000 - POOH w 14. I hereby certify that the foregoing is		ig. Snut down unti	1 Monday.	·····
SignedUstu		Onematican T1	INUED ON NEX	
(This space for Federal or State offic		le Operations Techn	iician	Date March 24, 2000
•	,		A LE COLLEGE ME L	
Approved by Conditions of approval, if any:	Ti		7000	Date
		APR 0 4	2003	
Title 18 U.S.C. Section 1001, makes it a	crime for any person knowingly and	willfully to make to any department or	agency of the United St	ates any false, fictitious or fraudulent statement:
or representations as to any matter within	is jurisdiction.	Br W		, Children of the second fill

YATES PETROLEUM CORPORATION Crosby TV Federal #2 Section 15-T8S-R25E Chaves County, New Mexico

SUNDRY NOTICE CONTINUED:

3-7-2000 - Rigged up wireline. TIH with 4" casing guns and perforated 5006-5014' w/18 .41" holes (2 SPF - Penn). TOOH with casing guns and rigged down wireline. TIH with packer and tubing. Set packer at 4932'. Acidized perforations 5006-5014' with 800 gallons of 7-1/2% iron control acid and ball sealers. Swabbed. Shut well in. 3-8-2000 - Swabbed. Shut well in. 3-9-2000 - Swabbed. Unset packer and TOOH with packer and tubing. Rigged up wireline. TIH with 4" casing guns and perforated 5082-5088' w/7 .42" holes (1 SPF - Wolfcamp). TOOH with casing guns and rigged down wireline. TIH with packer and tubing. Set packer at 5028'. Acidized perforations 5082-5088' with 600 gallons of 15% iron control acid and ball sealers. Swabbed. Shut well in. 3-10-2000 - Swabbed. Shut well in. 3-11-13-2000 - Swabbed. Shut well in. 3-14-2000 - Unset packer and TOOH with packer and tubing. Rigged up wireline. TIH with CIBP and set CIBP at 4950'. Capped CIBP with 35' of cement. TIH with 4" casing guns and perforated 4692-4704' w/26. 41'' holes (2 SPF - Wolfcamp). TOOH with casing guns and rigged down wireline. TIH with packer and tubing. Set packer at 4609'. Acidized perforations 4692-4704' with 1500 gallons of 20% iron control acid and ball sealers. Swabbed. Shut well in. 3-15-2000 - Swabbed. Shut well in. 3-16-2000 - Swabbed. Shut well in. 3-17-20-2000 - Shut in. 3-21-2000 - Unset packer and TOOH with packer and tubing. Rigged up wireline. TIH with CIBP and set CIBP at 4235'. Capped CIBP with 35' of cement. TIH with 4" casing guns and perforated 3850-4012' w/18 .41" holes (1 SPF - Abo). TOOH with casing guns and rigged down wireline. Shut well in. 3-22-2000 - TIH with tubing open ended to 4020'. Circulate hole clean. TOOH with

tubing and laid down tubing. Nippled down BOP and nippled up frac valve. Shut well in for night. Prep to frac.

3-23-2000 - Frac'd perforations 3850-4012' with 142700 gallons of 650 N2 foam and 240000# of 16-30 Brady sand. Flowing back frac.

Rustly Klein

Operations Technician March 24, 2000

11.10 B

