State of New Mexico Form C-103 Submit 3 Copies Energy, Minerals and Natural Resources Department Revised 1-1-89 to Appropriate District Office OIL CONSERVATION DIVISION DISTRICTI WELL API NO. P.O. Box 1980, Hobbs, NM 88240 P.O. BOX 2000 Santa Fe, New Mexico 87504611818 19202 30-005-63232 5. Indicate Type of Lease P.O. Drawer DD, Artesia, NM 88210 FEE STATEX 1000 Rio Brazos Rd., Aztec, NM 87410 State Oil & Gas Lease No. LG-2622 SUNDRY NOTICES AND REPORTS ON WELLS, PECE (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN ON PROPOSALS TO DRILL OR TO DEEPEN ON PROPOSALS TO DRILL OR TO DEEPEN ON PERMIT Lease Name or Unit Agreement Name (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: WELL X MET NSL Order Harvest ABR State 2. Name of Operator 1/ 8. Well No. YATES PETROLEUM CORPORATION 3. Address of Operator 9. Pool name or Wildcat 105 South 4th St., Artesia, NM 88210 Pecos Slope Abo 4. Well Location _ : _ 660 _ Line and _ 2139 __ Feet From The __ West __ Feet From The North Line Range **NMPM** Chaves County Township 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3561' GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data **NOTICE OF INTENTION TO:** SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK **ALTERING CASING** PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT **CHANGE PLANS** TEMPORARILY ABANDON CASING TEST AND CEMENT JOB **PULL OR ALTER CASING** OTHER: Perforate, acidize & frac OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 3-16-2000 - Cleaned location, set and tested anchors. 3-17-2000 - Moved in and rigged up pulling unit. Nippled up wellhead and BOP. TIH with bit, scraper and tubing and tagged PBTD at 4940'. TOOH with tubing, scraper and bit. Shut well in. 3-18-20-2000 - Rigged up wireline. TIH with logging tools and ran GR/CCL/CBL log. TOOH with logging tools. TIH with 4" casing guns and perforated 4536-4627' w/68.41" holes as follows: 4536-4543' w/16 holes and 4602-4627' w/52 holes (2 SPF - Penn). TOOH with casing guns and rigged down wireline. TIH with RBP and packer and tubing. Set RBP at 4658' and packer at 4500'. Shut well in. 3-21-2000 - Pulled packer to 4564 and set packer. Acidized perforations 4602-4627 with 2500 gallons of 7-1/2% iron control HCL acid and ball sealers. Eled well down. Unset packer & pulled 15K over to pull loose. Pulled packer to 4438' and set packer. Tested packer to 500 psi, OK. Swabbed. Shut well in. 3-22-2000 - Bled well down. Unset packer & TOOH, TIH and unset RBP. Moved RBP to 4564'

(This space for State Use) ORIGINAL SIGNED BY TIM W. GUM ISTRICT II SUPERVISOR

Rusty Klein

I hereby certify that the information above in true and complete to the best of my knowledge and belief.

MAY 2 3 2000

TELEPHONE NO. 505/748-1471

DATE May 16, 2000

Operations Technician

CONTINUED ON NEXT PAGE:

SIGNATURE _

TYPE OR PRINT NAME