• 4		
		Form C-103 Revised 1-1-48
20-015- to Appropriate		Oν
	iaa	
SI219 OT NEW MEX	ourses Department	
DISTRICT! Energy, Minerals and Natural Nes	Notifica Capatanama	NELL API NO.
Energy, Minerals and Natural Resources Department P.O. Box 1980, Hobbs NA: 88840 DISTRICT II P.O. Digwer 00, Artesia NAT 88210 P.O. Digwer 00, Artesia NAT 88210 P.O. Box 2088 Santa Fe, New Mexico 87504-2088		20 005 63234
DISTRICT III P.O. Downer CO., Artesia MRT 2022 10 P.O. Box 2088 RECENER Santa Fe, New Mexico 87504-2088		30-005-63234
P.O. Downer CO. Artesia New Pezz 10 RECURATE Santa Fe, New Mexico 87504-2088		S. Indicate Type of Lease
Anna To Amer Mt Arter Mt 687410 CVV		State X FEE
SUNDRY NOTICES AND REPORTS ON WELLS		6, Sinke Oil & Gas Luses No.
1 Propriet		LG-939
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name
NECEDENT RESERVOIR, USE METUCATION OF THE TIME		
(FORM C-101) FOR SUCH PROPOSALS.)		AL STATE
1. Type of Weat:		WITZ VN STATE
OR GAS		
WELL		8. Well No.
2. Name of Operator Yates Petroleum Corporation		
		FOOR RANCH PRE-PERMIAN GAS
105 South 4th., Artesia, NM 88210		T OOK TORON THE
4. Well Location	4090 E	set From The WEST Line
Unit Letter F : 1980 Feet From The NORTH	Line and 1980 F	set From the
00 D 26E	NMPM	CHAVES COUNTY
Section 20 Township 50 (Valige		
110. Elevation (Show whether Dr. PAS).	,,	
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data		
NOTICE OF INTENTION TO:	SUBSEQUEN	T REPORT OF:
	REMEDIAL WORK	ALTERING CASING
PBOOK REMEDIE NO.	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS	CASING TEST AND CEMENT JOB	=
PULL OR ALYER CASING		
OTHER	OTHER Temporary aband	ionment
OTHER 12. Describe Proposed or Completed Operations (Clearly state all pertient details, and give pertinenet dates, including estimated		
date of starting any proposed work) SEE RULE 1103.		
2-11-02- MIRU 2-12-02- Bled down; NU BOP & unset packer & RBP, POH, Dump 35' cement on top of CIBP @ 6050',		
2-12-02- Bled down; NO BOP & unset pastor. Till to 5200', SI & SD for nite. Set CIBP @ 5250'; dump 35' cement on top. Till to 5200', SI & SD for nite. Set CIBP @ 5250'; dump 35' cement on top. Till to 5200', SI & SD for nite.		
Set CIBP @ 5250'; dump 35' cement on top. 11H to 5200 : 3' to 500 Hornest Case of the Second Set CIBP @ 5250'; dump 35' cement on top. 11H to 5200 : 3' to 500 Hornest Case of the Second Secon		
NU & capped off well head. RD & move off location.		
TEMPORARY ABANDONED - February 13, 2002.		
Please see attached pressure test performed on 2-12-02. OCD - Artesia notified but did not witness.		
LIGOR DOC CHRONER PLANT		
		ENTERED MAR 1 1 2002
Temporary Abandoned Status approved		-11-1 1 1 7 ZUUZ
4-13-0C		
I hereby carety triat the information, above a true and complete to the bast or my knowledge and bi	quef.	/
_/ // // // // // // // // // // // // /	fITLE Operations	s Techician DATE 2/15/02
SIGNATURE ALCOHOL CHARLE		
- ·		TELEPHONE NO. 505-748-1471
TYPE OR PRINT NAME DONNA CLACK	्र व र्राः	
Title space for space (or space)	1 -/// D. A	DATE FUND S 4 0000
APPROVED BY		= - 2 1 2002
CONDITIONS OF APPROVAL, IF ANY:		of b
Post-it ^e	Fax Note 7671 Date	3-27-02 pegas
es partres 3/7/02 CS TO F	From	" /at
correst 5/1/02 Ci (Corresti	Co.	
	Pho	né #
Phone #		