

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

CISF  
AP

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.	30-005-63236
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	V-4652
7. Lease Name or Unit Agreement Name	Aurora AUR State
8. Well No.	1
9. Pool name or Wildcat	Wildcat Precambrian

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	YATES PETROLEUM CORPORATION
3. Address of Operator	105 South 4th St., Artesia, NM 88210
4. Well Location	Unit Letter <u>I</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>16</u> Township <u>9S</u> Range <u>26E</u> NMPM <u>Chaves</u> County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3761' GR
--	----------

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Abandon Penn, perforate & acidize <input checked="" type="checkbox"/>
	Wolfcamp

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-25-2000 - Moved in and rigged up pulling unit. Bled well down. Shut well in.

7-26-2000 - Bled well down. Nippled down wellhead. Nippled up BOP. Loaded tubing. Released packer. TOOH. Rigged up wireline. TIH with CIBP and set CIBP at 5800'. TOOH. TIH with 4" casing guns and perforated 5400-5408' w/18 .42" holes (2 SPF - Wolfcamp). TOOH with casing guns and rigged down wireline. TIH with packer and tubing and set packer at 5350'. Swabbed. Shut well in.

7-27-2000 - Bled well down. Loaded tubing. Released packer and TOOH with packer and tubing. Rigged up wireline. TIH with 4" casing guns and perforated 5388-5395' w/16 .42" holes (2 SPF - Wolfcamp). TOOH with casing guns and rigged down wireline. TIH with Arrowset packer with 2.25" on/off tool to 5344'. Nippled down BOP. Set packer. Flanged up. Swabbed. Acidized perforations 5388-5408' with 1500 gallons of 20% iron control HCL acid and ball sealrs. Swabbed & flow tested. Shut well in.

7-28-2000 - Released well to production department.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Operations Technician DATE July 31, 2000

TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY Jim W. Green TITLE District Supervisor DATE AUG 30 2000

CONDITIONS OF APPROVAL, IF ANY: