

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-005-63237

5. Indicate Type of Lease STATE ☒ FEE ☐

6. State Oil & Gas Lease No. LG-7420

7. Lease Name or Unit Agreement Name Dallas AUE State

8. Well No. 1

9. Pool name or Wildcat Foor Ranch Pre Permian

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3682' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. Name of Operator YATES PETROLEUM CORPORATION

3. Address of Operator 105 South 4th St., Artesia, NM 88210

4. Well Location Unit Letter I : 1500 Feet From The South Line and 660 Feet From The East Line

Section 35 Township 9S Range 26E NMMPM Chaves County

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3682' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: Perforate & acidize <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-15-2001 - Cleaned location, set and tested anchors. Welded on bell nipple.

8-16-2001 - Moved in and rigged up pulling unit. Nippled up wellhead and BOP. TIH with bit, scraper and tubing and tagged PBTD at 6394'. Circulated hole with 7% KCL water. TOOH with tubing, scraper and bit. Shut well in.

8-17-2001 - Rigged up wireline. TIH with logging tools and ran GR/CCL/CBL log. TOOH with logging tools. TIH with 4" casing guns and perforated 6360-6368' w/32 .42" holes (4 SPF - Granite wash). TOOH with casing guns and rigged down wireline. TIH with packer and 2.25" on/off tool with knockout plug. Set packer at 6300' and tested, OK. Shut well in.

8-18-20-2001 - Dropped bar. Swabbed. Shut well in.

8-21-2001 - Swabbed. Acidized perforations 6360-6368' with 250 gallons of 7-1/2% iron control HCL acid and ball sealers. Swabbed. Flow tested. Shut well in.

8-22-2001 - Swabbed & flow tested. Shut well in.

8-23-2001 - Acidized perforations 6360-6368' with 2000 gallons of 7-1/2% iron control

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

CONTINUED ON NEXT PAGE:

SIGNATURE Rusty Klein TITLE Operations Technician DATE Oct. 30, 2001

TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

NOV 16 2001

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: