				C(S)	
Submit 3 Copies To Appropriate District	State of	New Me	xico	411	Form C-103
Office District I	Energy, Minerals	and Natu	ral Resources	Ψ	Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240				WELL APINO.	
<u>District II</u> 811 South First, Artesia, NM 88210	OIL CONSERVATION DIVISION			30-005-63276 5. Indicate Type	
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.			STATE	FEE X
District IV	Santa Fe, NM 87505			6. State Oil & C	
1220 S. St. Francis Dr., Santa Fe, NM 87505					
SUNDRY NOTION	CES AND REPORTS O			7. Lease Name or	r Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH					
PROPOSALS.)	inon contraction (con	٠٠، ٥٠٠, ١٠٠		King TF	
1. Type of Well:	O.1 []	122	31415767>20		
Oil Well Gas Well X 2. Name of Operator	Other		* ***	7. Well No.	~,
Yates Petroleum Corpor	ation	(3) (3) (5)	SED ONCE DO	# 4	
3 Address of Operator 8 Pool name or Wildcat					
105 S. 4th Street Artesia, NM 88210 RECEIVED OCD - ARTESIA				Pecos Slop	pe Wildcat
1 1		<i>∵</i> 5 UUU	- ARTESIA 200		
4. Well Location					
Y Taris Y awar A . 440	fact from the Ne	arth 1im		feet from the	ast line
Unit Letter A: 660	leet from theNC	21111 1111	le and	ieet from the	dst line
Section 25	Township 6S	Range	25E N.	MPM Chave	es County
	10. Elevation (Show)			.)	
3751' GR					
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF IN	rention to:		SUB	SEQUENT RE	PORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	1 🗌	REMEDIAL WORI	K 🗆	ALTERING CASING []
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRI	LLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AN CEMENT JOB	ND	
OTHER:		П	OTHER: Set pro	duction casing	
Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of					
starting any proposed work). SEE F					
recompilation.					
10/19/00 – MI and RU pulling u		0.401 TILL		10001	
10/20/00 – TIH with bit and scraper. Tag PBTD at 5349'. TIH with CBL. TOC 3280'. 10/23/00 – Perf Cisco 5022-5040', 19 holes, and Wolfcamp 4773-4778', 6 holes, .42" holes.					
10/25/00 – Perf Wolfcamp 4732-4746', 15 holes, and 4762-4772', 11 holes, .42" holes.					
10/27/00 – Spot 50 gals 15% IC HCL across perfs 5022-5040'. Acidize perfs 5022-5040' with 900 gals 15% IC HCL.					
10/30/00 – Straddle perfs 4732-4778'. Acidize with 1500 gals 15% IC HCL.					
10/31/00 – Set CIBP at 4700'. Put 35' cement on top of CIBP. Perf Abo 3777-3783', 3786-3788', 3791-3792', 3869-					
3870', 3923-3926', 3961-3965' and 3969-3970', 2 JSPF, 50 holes, .42" holes.					
11/3/00 – Spot 500 gals 7.5% IC HCL across perfs 3777-3970'. 11/6/00 – Frac Abo with 58,800 gals 65Q N2 foamed 35# gelled 7% KCL water + 300,000# 16/30 mesh Brady					
sand, with 2000 gals 7.5% IC HCL ahead of frac. 11/7-11/12/00 – flow back frac.					
11/13/00 - TIH with SN and 2-3/8" tbg . Set SN at 3773'.					
11/16/00 – Rig down pulling ur	nit. Turn well over to	product	ion.		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
SIGNATURE MAGA TITLE Engineering Technician DATE September 13, 2001					
Type or print name Susan Her	roin			Telephone	e No. 505-748-1471
(This appear for State use)				retephone	.110. 000 / 10 11/1
`	GINAL SIGNED BY T TRICT II SUPERVISO	IM W. GL	JM		SEP 1 8 2001
APPPROVED BY Conditions of approval, if any:		""ITLE_			DATE 2001