Submit 3 Copies to Appropriate District Office		or New Mexico Natural Resources Departi	Form C-103 Revised 1-1-89
DISTRICT 1 P.O. Box 1980, Hobbs, NM 88240	OIL CONSER	VATION DIVISION D. Box 2088	WELL API NO.
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	O	8 Nexico 87504-2088	30-005-63301
DISTRICT III	Santa Fe 7	The state of the s	5. Indicate Type of Lease STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410		2001 2 12 RECEIVED 8	6. State Oil & Gas Lease No. 26827
SUNDRY NOT ( DO NOT USE THIS FORM FOR PR	ICES AND REPORT	CON WELLED . ARTESIA	
DIFFERENT RESE	RVOIR. USE "APPLICATI -101) FOR SUCH PROPO	SIN' FOR PERINIT' / /	7. Lease Name or Unit Agreement Name
1. Type of Well: OIL GAS WELL X	्ट,		. "
2. Name of Operator		7.02	Willow Spring "16" State
Reliance Energy, Inc	e. √	·	1
P.O. Box 10946, Mid	land, Texas 7970	)2	9. Pool name or Wildcat Wildcat
4. Weli Locauon Unit Letter N 66	50 So:	ith 1980	
		Line and _ 1980	Feet From The West Line
Section 16	Township 4S	Range 25E.  how whether DF, RKB, RT, GR, etc.)	NMPM Chaves County
		3864' GR	<i>*************************************</i>
11. Check	Appropriate Box to	Indicate Nature of Notice, R	
NOTICE OF IN	TENTION TO:	SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABAND	ON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CE	MENT JOB
OTHER:			
	ations (Clearly state all pertin		ding estimated date of starting any proposed
12. Describe Proposed or Completed Operwork) SEE RULE 1103.	ations (Clearly state all pertin		ding estimated date of starting any proposed
12 Describe Proposed or Completed Operwork) SEE RULE 1103.  1-16-01 Spud we	11 @ 10 a.m.	ent details, and give pertinent dates, inclu	w/insert float @ 882'.
12. Describe Proposed or Completed Operwork) SEE RULE 1103.  1-16-01 Spud we 1-17-01 Ran 21 1-18-01 Cemente	11 @ 10 a.m. jts 11-3/4" 42#,	ent details, and give pertinent dates, included the H-40, ST&C csg to 924'	w/insert float @ 882'.
12 Describe Proposed or Completed Operwork) SEE RULE 1103.  1-16-01 Spud we 1-17-01 Ran 21 1-18-01 Cemente No ceme	11 @ 10 a.m. jts 11-3/4" 42#, d csg w/400 sxs nt to Surface.	H-40, ST&C csg to 924' 35/65 Poz "C" & 100 sxs	w/insert float @ 882'. Class "C" w/2% CaCl.
12 Describe Proposed or Completed Operwork) SEE RULE 1103.  1-16-01 Spud we 1-17-01 Ran 21 1-18-01 Cemente No ceme	11 @ 10 a.m. jts 11-3/4" 42#, d csg w/400 sxs nt to Surface. to tag TOC @ 33	H-40, ST&C csg to 924' 35/65 Poz "C" & 100 sxs	w/insert float @ 882'. Class "C" w/2% CaCl.
12 Describe Proposed or Completed Operwork) SEE RULE 1103.  1-16-01 Spud we 1-17-01 Ran 21 1-18-01 Cemente No ceme	11 @ 10 a.m. jts 11-3/4" 42#, d csg w/400 sxs nt to Surface. to tag TOC @ 33 to pit. WOC 18	H-40, ST&C csg to 924' 35/65 Poz "C" & 100 sxs WOC.  O'. Perf'd w/400 sxs 3	w/insert float @ 882'. Class "C" w/2% CaCl.
12. Describe Proposed or Completed Operwork) SEE RULE 1103.  1-16-01	11 @ 10 a.m. jts 11-3/4" 42#, d csg w/400 sxs nt to Surface. to tag TOC @ 33 to pit. WOC 18	H-40, ST&C csg to 924' 35/65 Poz "C" & 100 sxs WOC.  O'. Perf'd w/400 sxs 3	w/insert float @ 882'. Class "C" w/2% CaCl.
12. Describe Proposed or Completed Operwork) SEE RULE 1103.  1-16-01 Spud we 1-17-01 Ran 21 1-18-01 Cemente No ceme Ran CBL 98 sxs	11 @ 10 a.m.  jts 11-3/4" 42#,  d csg w/400 sxs  nt to Surface.  to tag TOC @ 33  to pit. WOC 18	H-40, ST&C csg to 924' 35/65 Poz "C" & 100 sxs WOC.  O'. Perf'd w/400 sxs 3 hrs.	w/insert float @ 882'. Class "C" w/2% CaCl. 5/65 Poz "C". Circ
12 Describe Proposed or Completed Operwork) SEE RULE 1103.  1-16-01 Spud we 1-17-01 Ran 21 1-18-01 Cemente No ceme Ran CBL 98 sxs	11 @ 10 a.m.  jts 11-3/4" 42#,  d csg w/400 sxs  nt to Surface.  to tag TOC @ 33  to pit. WOC 18	H-40, ST&C csg to 924' 35/65 Poz "C" & 100 sxs WOC. 0'. Perf'd w/400 sxs 3 hrs.	w/insert float @ 882'. Class "C" w/2% CaCl. 5/65 Poz "C". Circ
12. Describe Proposed or Completed Operwork) SEE RULE 1103.  1-16-01 Spud we 1-17-01 Ran 21 1-18-01 Cemente No ceme Ran CBL 98 sxs  I hereby certify that the information above is tre SIONATURE Peggy Abe  (This space for State Use)	11 @ 10 a.m.  jts 11-3/4" 42#,  d csg w/400 sxs  nt to Surface.  to tag TOC @ 33  to pit. WOC 18	H-40, ST&C csg to 924' 35/65 Poz "C" & 100 sxs WOC.  O'. Perf'd w/400 sxs 3 hrs.	w/insert float @ 882'. Class "C" w/2% CaCl. 5/65 Poz "C". Circ