Submit 3 Coning To Ammoniate Director				- as	
Submit 3 Copies To Appropriate District Office State of New Mexico				(o Form C-103
District I Energy, Minerals and Natural Resources			V	Revised March 25, 1999	
1625 N. French Dr., Hobbs, NM 88240 District II				WELL API NO.	
811 South First, Artesia, NM 88210 OIL CONSERVATION DIVISION			30-005-63306		
District III 1000 Rio Brazos Rd., Aztec, NM 87410 1220 South St. Francis Dr.			5. Indicate Type		
District IV Santa Fe, NM 87505				X FEE	
1220 S. St. Francis Dr., Santa Fe, NM 87505				6. State Oil & C	Gas Lease No.
SUNDRY NOT	TICES AND REPORTS (ON WELL	<u> </u>		r Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				or other representation.	
PROPOSALS.)	Wager "AWG	" State			
1. Type of Well:	_				
Oil Well Gas Well	C Other		4		
2. Name of Operator			-	7. Well No.	
Yates Petroleum Corporation				#4	
3. Address of Operator	8. Pool name or Wildcat				
105 S. 4 th Street Arte	sia, NM 88210	. •c <i>u</i> . ,	ARIESIA	Wildcat O	rdovician
4. Well Location			57A 65		
4. Well Education			20 V3/		
Unit Letter D: 6	660 feet from the No	orth 1		c c a W	
om Better	leet nom the N	OHII I	ine and	feet from the	est line
Section 34	Cownship 98	Range	26E	NMPM Chave	• Committee
	10. Elevation (Show	whether D	R, RKB, RT, GR, etc.	c)	S County
, 	`	3786		,	
11. Check A	Appropriate Box to Ir			Report or Other 1	Data
11. Check Appropriate Box to Indicate Nature of Notice, Report NOTICE OF INTENTION TO: SUBSEQ					PORT OF:
PERFORM REMEDIAL WORK	PI.UG AND ABANDON				
	T 1.00 AND ABANDON		REMEDIAL WORI	<u> </u>	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRI	LLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	M JLTIPLE		CASING TEST AN	ID .	ADAINDONWENT
	COMPLETION		CEMENT JOB		
OTHER:			OTHER: set pro	oduction casina	cement [v]
Describe proposed or completed opera ions. (Clearly state all pertinent details, and give pertinent dates, including estimated date of					
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellhore diagram of proposed completion or					
recompliation.					
12/7/00 - Ran 151 jts. (6336.56') casing, set at 6336' as follows:					
75 jts 5-1/2" 15.5# J-55 SB (3125.18')					
76 jts. 5-1/2" 15.5# J-55 Varn (3211.38')					
Float shoe set at 6336.56' Float collar set at 6294.04' Top marker set at 3211.38'					
Cemented with 500 sxs Pecos Valley Lite with 1 pps D44 + 4 pps D42 + .2% D65 + .3% D167 + .2% D46 + .15% D13 (yld 1.42, wt 13). PD at 3:00 PM. Bumped plug to 1323 psi for 1 min. Held OK.					
Notified Artesia OCD (Mike Stubblefield) of operations 12-7-00.					
Rig released at 8:00 PM.	oprietieta) of operat	iions +2-7	-00.		
2 = = = = = = = = = = = = = = = = = = =					
I hereby certify that the information	above is true and compl	lete to the l	est of my knowledg	ge and belief.	
SIGNATURE Array 14	•				
SIGNATURE		TITLE _	Engineering T	echnician DAT	TE <u>August</u> , 2001
Type or print name Susan Hei					
Type or print name Susan Hei (This space for State use)	.h		 -	Telephone 1	No. 505-748-1471
(This space for State use)	d				
APPPROVED BY) or 9	TITLE			DATE.
Conditions of approval, if any:					_DATE
	\ _				