				(19/	
Submit 3 Copies To Appropriate District	State of New Mexico			- C, H	Form C-103
Office District I	Energy, Minerals and Natural Resources			VY	Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240				WELL API NO.	\
<u>District II</u> 311 South First, Artesia, NM 88210	OIL CONSERVATION DIVISION			30-005-63316	
District III	1220 South St. Francis Dr.			5. Indicate Type of Lease STATE X FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505			6. State Oil & Ga	
1220 S. St. Francis Dr., Santa Fe, NM 37505	ancis Dr., Santa Fe, NM			L-6811	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Gas Well X Other				7. Lease Name or Unit Agreement Name: Horizon "AWH" State	
2. Name of Operator		C	ENERSIA ?	7. Well No.	
Yates Petroleum Corpore	ation /	<i>bE1</i>	ARICO SI	#1	
3. Address of Operator 105 S. 4 th Street Artesia, NM 88210				8. Pool name or Wildcat Foor Ranch Pre-Permian	
4. Well Location		- {(3 }	SIFIE	l	
Unit Letter <u>A: 12</u> 6 Section 16		lange	26E	NMPM Chave	
		iner DR 3768'		2.)	
11 Check At	ppropriate Box to Indica			Report or Other	Data
NOTICE OF INT				SEQUENT RE	
PERFORM REMEDIAL WORK	PLUG AND ABANDON				ALTERING CASING [
TEMPORARILY ABANDON	CHANGE PLANS			COMMENCE DRILLING OPNS. X PLUG AND ABANDONMENT CASING TEST AND	
PULL OR ALTER CASING	MULTIPLE COMPLETION		CEMENT JOB		
OTHER:			OTHER:		
Describe proposed or completed opstarting any proposed work). SEE Frecompilation. 12/28/00 – Spud conductor he 1/1/01 – Resume drilling with r 1/3/01 – Set 27 jts. (1144.64') conset at 1102.12'. Cemented with Tailed in with 200 sxs "C" with 51 sxs. (Note: Notified Mike S 1/4/01 – Drilled out at 1:00 AM 1/9/01 – Drilled to 4675', started appreciable fluid loss downhous 1/18/01 – Reached TD of 6380 1/20/01 – Logging well and particles.	RULE 1103. For Multiple Coole at 10:00 AM. Set 40 totary tool at 2:00 AM. of 24# J-55 casing, set a ith 400 sxs 35:65 POZ "C 2% S1 (yld 1.32, wt 14.8) tubblefield with Artesia A. WOC 21 hrs. 45 mins. ed losing small amount tole. O' at 11:30 AM. rep to run csg. Logger'	omple: ' of 16 at 1144 ;" with). PD (OCD . Redu of fluid	etions: Attach well 6" conductor, co 4'. Texas Pattern 1 6% D20 + 2% S 1 at 3:15 AM. Bur 1 of operations of 1 uced hole to 7-7 1 d. Mix and pum 1 attach well	ement to surface an guide shoe set of the set of the shoe shoe shoe shoe shoe shoe shoe sh	at 1144'. Insert float d 1.99, wt 12.6). O psi, held OK. Circ.
Ž,					. TP August 07 0001
SIGNATURE And SIGNATURE		ITLE	Engineering		ATE <u>Augusi 27, 2001</u>
Type or print name Susan He				i elepnon	e No. 505-748-1471
APPPROVED BY	ORIGINAL SIGN DISTRICT II SU	NED B	Y TIM W. GUM		A05 2 9 3