office District I	State o	of New Mex	vico		Form C-103	
Istrict I	fice				Revised March 25, 1999	
525 N. French Dr., Hobbs, NM 88240	Linergy, winneral	Zaorgy, materials and reducted resources			WELL API NO.	
strict II	OIL CONCET	OIL CONSERVATION DIVISION			30-005-63331	
1 South First, Artesia, NM 88210	1220 South St. Francis Dr.			5. Indicate Type of Lease		
strict III 00 Rio Brazos Rd., Aztec, NM 87410				STATE X FEE		
istrict IV Santa Fe, NM 8/50			505	6. State Oil & G		
220 S. St. Francis Dr., Santa Fe, NM 7505						
SUNDRY NOTI	ICES AND REPORTS			7. Lease Name or	Unit Agreement Name:	
OO NOT USE THIS FORM FOR PROPO IFFERENT RESERVOIR. USE "APPLIC					-	
ROPOSALS.)	CATION FOR FERMIN (PC	AND CALOR D	N SUC M	Margaret R	Q State	
Type of Well:	,	201 🔥 🛧	· · ·	1		
Oil Well Gas Well X		<u>Alig</u>	20101			
Name of Operator		•	1	7. Well No.		
Yates Petroleum Corpo	ration	RECE	RTESIA-	#5		
Address of Operator				8. Pool name or		
105 S. 4 th Street Artes	sia, NM 88210	در ار		Wildcat Ba	sement	
Well Location				<u> </u>		
on Location						
Unit Letter : 1	500 feet from the	<mark>South</mark> li	ne and <u>1500</u>	feet from the	ast line	
			0.45			
Section 36	Township 4S 10. Elevation (Show			NMPM Chave	S County	
	TU. Elevation (Snow	v whether DR, 3922'		<i>c.j</i>		
11. Check A	Appropriate Box to I			Report or Other 1	Data	
NOTICE OF IN				SEQUENT REP		
	PLUG AND ABANDO		REMEDIAL WOR	in		
	CHANGE PLANS		COMMENCE DR	ILLING OPNS. X	PLUG AND ABANDONMENT	
	MULTIPLE		CASING TEST A	ND		
	COMPLETION		CEMENT JOB			
THER:			OTHER:			
				rive pertinent detec		
	ted operations (Classie	r ctate all mart			including actions	
2. Describe proposed or complet						
). SEE RULE 1103. Fo					
 Describe proposed or complet of starting any proposed work) or recompilation. 2/6-9/01 – /21/01 – Spud 1:00 PM with 20"). SEE RULE 1103. Fo Build location. hole. Set 40' of 16'' of	or Multiple Co conductor, c	ompletions: Attac	h wellbore diagram	of proposed completion	
 Describe proposed or complet of starting any proposed work) or recompilation. 2/6-9/01 – '21/01 – Spud 1:00 PM with 20'' '5/01 – Resumed drilling at 6:00). SEE RULE 1103. Fo Build location. hole. Set 40' of 16'' o AM, 14-3/4'' hole. No	or Multiple Co conductor, c otified Phil Ha	ompletions: Attac cement to surfac awkins of OCD .	h wellbore diagram e. Waiting on rotar	of proposed completion y tool.	
 Describe proposed or complet of starting any proposed work) or recompilation. 2/6-9/01 – /21/01 – Spud 1:00 PM with 20" /5/01 – Resumed drilling at 6:00 /7/01 – Reached TD of 14-3/4"). SEE RULE 1103. Fo Build location. hole. Set 40' of 16'' o AM, 14-3/4'' hole. No hole 4:00 PM. Ran 20	or Multiple Co conductor, c otified Phil Ho joints of 11-3.	ompletions: Attac cement to surfac awkins of OCD . 5/4" 42# H-40 (91	h wellbore diagram e. Waiting on rotar 1.71') casing set at	of proposed completion y tool. 900'.	
 Describe proposed or complet of starting any proposed work) or recompilation. 2/6-9/01 – /21/01 – Spud 1:00 PM with 20" /5/01 – Resumed drilling at 6:00 /7/01 – Reached TD of 14-3/4" fexas Pattern Notched guide shows). SEE RULE 1103. Fo Build location. hole. Set 40' of 16" o AM, 14-3/4" hole. No hole 4:00 PM. Ran 20 oe set at 900'. Insert f	or Multiple Co conductor, c bified Phil Ha joints of 11-3 loat set at 85	ompletions: Attac cement to surfac swkins of OCD . /4" 42# H-40 (91 54.33', Cemente	h wellbore diagram e. Waiting on rotar 1.71') casing set at d with 400 sxs 35:65	of proposed completion y tool. 900'.	
 Describe proposed or complet of starting any proposed work) or recompilation. 2/6-9/01 – 21/01 – Spud 1:00 PM with 20" 5/01 – Resumed drilling at 6:00 7/01 – Reached TD of 14-3/4" it exas Pattern Notched guide she #/sx polyseal (yld 1.99, wt 12.8)). SEE RULE 1103. Fo Build location. hole. Set 40' of 16" o) AM, 14-3/4" hole. No hole 4:00 PM. Ran 20 oe set at 900'. Insert f). Tailed in with 200 sx:	or Multiple Co conductor, c otified Phil Ha joints of 11-3 loat set at 85 s C + 2%CaC	ompletions: Attac cement to surfac awkins of OCD . :/4" 42# H-40 (91 54.33', Cemente Cl2 (yld 1.32, wt 1	h wellbore diagram e. Waiting on rotar 1.71') casing set at d with 400 sxs 35:65 4.8).	of proposed completion y tool. 900'. :6 C + 2% CaCl2 +	
 Describe proposed or complet of starting any proposed work) or recompilation. 2/6-9/01 – '21/01 – Spud 1:00 PM with 20" '5/01 – Resumed drilling at 6:00 '7/01 – Reached TD of 14-3/4" i exas Pattern Notched guide she #/sx polyseal (yld 1.99, wt 12.8) D at 3:15 AM 3/8/01. Bumped i). SEE RULE 1103. Fo Build location. hole. Set 40' of 16" o) AM, 14-3/4" hole. No hole 4:00 PM. Ran 20 oe set at 900'. Insert f). Tailed in with 200 sx:	or Multiple Co conductor, c otified Phil Ha joints of 11-3 loat set at 85 s C + 2%CaC	ompletions: Attac cement to surfac awkins of OCD . :/4" 42# H-40 (91 54.33', Cemente Cl2 (yld 1.32, wt 1	h wellbore diagram e. Waiting on rotar 1.71') casing set at d with 400 sxs 35:65 4.8).	of proposed completion y tool. 900'. 5:6 C + 2% CaCl2 +	
 Describe proposed or complet of starting any proposed work) or recompilation. 2/6-9/01 – (21/01 – Spud 1:00 PM with 20" (5/01 – Resumed drilling at 6:00 (7/01 – Reached TD of 14-3/4" f exas Pattern Notched guide she #/sx polyseal (yld 1.99, wt 12.8) D at 3:15 AM 3/8/01. Bumped p perations 5:10 PM 3/7/01.). SEE RULE 1103. Fo Build location. hole. Set 40' of 16" o AM, 14-3/4" hole. No hole 4:00 PM. Ran 20 oe set at 900'. Insert f). Tailed in with 200 sx plug to 544 psi, held C	or Multiple Co conductor, c otified Phil Ha joints of 11-3 loat set at 85 s C + 2%CaC DK. Circulate	ompletions: Attac cement to surfac awkins of OCD. (/4" 42# H-40 (91 54.33', Cemente Cl2 (yld 1.32, wt 1 ed 55 sxs. WOC.	h wellbore diagram e. Waiting on rotar 1.71') casing set at d with 400 sxs 35:65 4.8). Notified Phil Hawki	of proposed completion y tool. 900'. 5:6 C + 2% CaCl2 + ns of OCD of	
 Describe proposed or complet of starting any proposed work) or recompilation. 2/6-9/01 – /21/01 – Spud 1:00 PM with 20" /5/01 – Resumed drilling at 6:00 /7/01 – Reached TD of 14-3/4" l exas Pattern Notched guide she #/sx polyseal (yld 1.99, wt 12.8) D at 3:15 AM 3/8/01. Bumped (perations 5:10 PM 3/7/01. /8/01 – Drilled out plug and cer /21/01 – Reached TD of 5450' c). SEE RULE 1103. Fo Build location. hole. Set 40' of 16" of AM, 14-3/4" hole. No hole 4:00 PM. Ran 20 oe set at 900'. Insert f). Tailed in with 200 sx plug to 544 psi, held C ment at 9:15 PM. WO at 1:00 AM. Logging v	or Multiple Co conductor, c otified Phil Ha joints of 11-3 loat set at 85 s C + 2%CaC DK. Circulate C 18 hours. F well. Loggers	ompletions: Attac cement to surfac awkins of OCD. :/4" 42# H-40 (91 54.33'. Cemente Cl2 (yld 1.32, wt 1 ed 55 sxs. WOC. Reduced hole to s TD 5438'.	h wellbore diagram e. Waiting on rotar 1.71') casing set at d with 400 sxs 35:65 4.8). Notified Phil Hawki 11'' and resumed o	of proposed completion y tool. 900'. 5:6 C + 2% CaCl2 + hs of OCD of drilling.	
 Describe proposed or complet of starting any proposed work) or recompilation. 2/6-9/01 – /21/01 – Spud 1:00 PM with 20" /21/01 – Resumed drilling at 6:00 /7/01 – Reached TD of 14-3/4" if exas Pattern Notched guide sha #/sx polyseal (yld 1.99, wt 12.8) D at 3:15 AM 3/8/01. Bumped if perations 5:10 PM 3/7/01. /8/01 – Drilled out plug and cer /21/01 – Reached TD of 5450' c /22/01 – Ran 131 jts 4-1/2" casi). SEE RULE 1103. Fo Build location. hole. Set 40' of 16" of AM, 14-3/4" hole. No hole 4:00 PM. Ran 20 oe set at 900'. Insert f). Tailed in with 200 sx plug to 544 psi, held C ment at 9:15 PM. WO at 1:00 AM. Logging v ng set at 5450' as follo	or Multiple Co conductor, c ptified Phil Ha joints of 11-3 loat set at 85 s C + 2%CaC DK. Circulate C 18 hours. F well. Loggers ows: 61 joints	ompletions: Attac cement to surfac awkins of OCD . :/4" 42# H-40 (91 54.33'. Cemente Cl2 (yld 1.32, wt 1 ed 55 sxs. WOC. Reduced hole to s TD 5438'. s 4-1/2" 11.6 S95/	h wellbore diagram e. Waiting on rotar 1.71') casing set at d with 400 sxs 35:65 4.8). Notified Phil Hawki 11'' and resumed o P110 SB (2532.32');	of proposed completion y tool. 900'. 3:6 C + 2% CaCl2 + hs of OCD of drilling. 70 jts 4-1/2" \$95/110	
 Describe proposed or complet of starting any proposed work) or recompilation. 2/6-9/01 – /21/01 – Spud 1:00 PM with 20" /5/01 – Resumed drilling at 6:00 /7/01 – Reached TD of 14-3/4" I exas Pattern Notched guide she #/sx polyseal (yld 1.99, wt 12.8) D at 3:15 AM 3/8/01. Bumped poerations 5:10 PM 3/7/01. /8/01 – Drilled out plug and cer /21/01 – Reached TD of 5450' of /22/01 – Ran 131 jts 4-1/2" casi W (2918.4'). Set Regular guide). SEE RULE 1103. Fo Build location. hole. Set 40' of 16" of AM, 14-3/4" hole. No hole 4:00 PM. Ran 20 oe set at 900'. Insert f). Tailed in with 200 sx: plug to 544 psi, held C ment at 9:15 PM. WO at 1:00 AM. Logging v ng set at 5450' as follo e shoe at 5450', Float of	or Multiple Co conductor, co pified Phil Ha joints of 11-3 loat set at 85 s C + 2%CaC DK. Circulate C 18 hours. F well. Loggers ows: 61 joints collar at 540	ompletions: Attac cement to surfac awkins of OCD. 5/4" 42# H-40 (91 54.33'. Cemente Cl2 (yld 1.32, wt 1 ed 55 sxs. WOC. Reduced hole to s TD 5438'. s 4-1/2" 11.6 S95/ 17.5', Bottom mc	h wellbore diagram e. Waiting on rotar 1.71') casing set at d with 400 sxs 35:65 4.8). Notified Phil Hawki 11'' and resumed o P110 SB (2532.32'); rker 4214.21', Top n	of proposed completion y tool. 900'. 3:6 C + 2% CaCl2 + hs of OCD of drilling. 70 jts 4-1/2" \$95/110 harker 2921.41'.	
 Describe proposed or complet of starting any proposed work) or recompilation. 2/6-9/01 – '21/01 – Spud 1:00 PM with 20" '21/01 – Resumed drilling at 6:00 '7/01 – Reached TD of 14-3/4" I exas Pattern Notched guide she #/sx polyseal (yld 1.99, wt 12.8) D at 3:15 AM 3/8/01. Bumped poerations 5:10 PM 3/7/01. '8/01 – Drilled out plug and cer '21/01 – Reached TD of 5450' of '22/01 – Ran 131 jts 4-1/2" casi V (2918.4'). Set Regular guide emented with 705 sxs Pecos Vol). SEE RULE 1103. Fo Build location. hole. Set 40' of 16" of AM, 14-3/4" hole. No hole 4:00 PM. Ran 20 oe set at 900'. Insert f). Tailed in with 200 sx: plug to 544 psi, held C ment at 9:15 PM. WO at 1:00 AM. Logging v ing set at 5450' as follo e shoe at 5450', Float of alley Lites, 4 pps D42, 1	or Multiple Co conductor, c ptified Phil Ho joints of 11-3 loat set at 85 s C + 2%CaC DK. Circulate C 18 hours. F well. Loggers pws: 61 joints collar at 540 1 pps D44, .2 ^e	ompletions: Attac cement to surfac awkins of OCD. (/4" 42# H-40 (91 54.33'. Cemente Cl2 (yld 1.32, wt 1 ed 55 sxs. WOC. Reduced hole to s TD 5438'. s 4-1/2" 11.6 S95/ (7.5', Bottom mo % D65, .3% D167,	h wellbore diagram e. Waiting on rotar 1.71') casing set at d with 400 sxs 35:65 4.8). Notified Phil Hawki 11'' and resumed o P110 SB (2532.32'); rker 4214.21', Top n	of proposed completion y tool. 900'. 3:6 C + 2% CaCl2 + hs of OCD of drilling. 70 jts 4-1/2" \$95/110 harker 2921.41'.	
 Describe proposed or complet of starting any proposed work) or recompilation. 2/6-9/01 – 21/01 – Spud 1:00 PM with 20" 5/01 – Resumed drilling at 6:00 7/01 – Reached TD of 14-3/4" if xas Pattern Notched guide she #/sx polyseal (yld 1.99, wt 12.8) D at 3:15 AM 3/8/01. Bumped if berations 5:10 PM 3/7/01. 8/01 – Drilled out plug and cer 21/01 – Reached TD of 5450' of 22/01 – Ran 131 jts 4-1/2" casi V (2918.4'). Set Regular guide emented with 705 sxs Pecos Vo 9:45 PM. Bump plug to 1650 p). SEE RULE 1103. Fo Build location. hole. Set 40' of 16" of AM, 14-3/4" hole. No hole 4:00 PM. Ran 20 oe set at 900'. Insert f). Tailed in with 200 sx: plug to 544 psi, held C ment at 9:15 PM. WO at 1:00 AM. Logging v ing set at 5450' as follo e shoe at 5450', Float of alley Lites, 4 pps D42, T osi for 4 mins., held OK	or Multiple Co conductor, c ptified Phil Ha joints of 11-3 loat set at 85 s C + 2%CaC DK. Circulate C 18 hours. F well. Loggers pws: 61 joints collar at 540 1 pps D44, .2°	ompletions: Attac cement to surfac swkins of OCD. /4" 42# H-40 (91 54.33', Cemente Cl2 (yld 1.32, wt 1 ed 55 sxs. WOC. Reduced hole to s TD 5438', s 4-1/2" 11.6 S95/ /7.5', Bottom mo % D65, .3% D167, t 0 sxs.	e. Waiting on rotar 1.71') casing set at d with 400 sxs 35:65 4.8). Notified Phil Hawki 11" and resumed of P110 SB (2532.32'); rker 4214.21', Top n .2% D46, .1% D13 (s	of proposed completion y tool. 900'. 3:6 C + 2% CaCl2 + hs of OCD of drilling. 70 jts 4-1/2" \$95/110 harker 2921.41'.	
 Describe proposed or complet of starting any proposed work) or recompilation. 2/6-9/01 – /21/01 – Spud 1:00 PM with 20" /5/01 – Resumed drilling at 6:00 /7/01 – Reached TD of 14-3/4" l exas Pattern Notched guide she #/sx polyseal (yld 1.99, wt 12.8) D at 3:15 AM 3/8/01. Bumped poerations 5:10 PM 3/7/01. /8/01 – Drilled out plug and cer /21/01 – Reached TD of 5450' c /22/01 – Ran 131 jts 4-1/2" casi (yl (2918.4'). Set Regular guide emented with 705 sxs Pecos Vo 19:45 PM. Bump plug to 1650 p otified Phil Hawkins of OCD be). SEE RULE 1103. Fo Build location. hole. Set 40' of 16" of AM, 14-3/4" hole. No hole 4:00 PM. Ran 20 oe set at 900'. Insert f). Tailed in with 200 sx: plug to 544 psi, held C ment at 9:15 PM. WO at 1:00 AM. Logging v ng set at 5450' as follo e shoe at 5450' r, Float of alley Lites, 4 pps D42, psi for 4 mins., held OK fore running casing. Fi	or Multiple Co conductor, co ptified Phil Ha joints of 11-3, loat set at 85 s C + 2%CaC DK. Circulate C 18 hours. F well. Loggers collar at 540 1 pps D44, .2° Circulated Released rig	ompletions: Attac cement to surfac awkins of OCD . (/4" 42# H-40 (91 54.33', Cemente Cl2 (yld 1.32, wt 1 ed 55 sxs. WOC. Reduced hole to s TD 5438', s 4-1/2" 11.6 S95/ (7.5', Bottom mc % D65, .3% D167, t 0 sxs. 3:00 AM 3/23/01	h wellbore diagram (e. Waiting on rotar (1.71') casing set at d with 400 sxs 35:65 (4.8). Notified Phil Hawki (11" and resumed (P110 SB (2532.32'); rker 4214.21', Top n 2% D46, .1% D13 (of proposed completion y tool. 900'. 3:6 C + 2% CaCl2 + hs of OCD of drilling. 70 jts 4-1/2" \$95/110 harker 2921.41'.	
 Describe proposed or complet of starting any proposed work) or recompilation. 2/6-9/01 – /21/01 – Spud 1:00 PM with 20" /5/01 – Resumed drilling at 6:00). SEE RULE 1103. Fo Build location. hole. Set 40' of 16" of AM, 14-3/4" hole. No hole 4:00 PM. Ran 20 oe set at 900'. Insert f). Tailed in with 200 sx: plug to 544 psi, held C ment at 9:15 PM. WO at 1:00 AM. Logging v ng set at 5450' as follo e shoe at 5450' r, Float of alley Lites, 4 pps D42, psi for 4 mins., held OK fore running casing. Fi	or Multiple Co conductor, co ptified Phil Ha joints of 11-3, loat set at 85 s C + 2%CaC DK. Circulate C 18 hours. F well. Loggers collar at 540 1 pps D44, .2° Circulated Released rig	ompletions: Attac cement to surfac awkins of OCD . (/4" 42# H-40 (91 54.33', Cemente Cl2 (yld 1.32, wt 1 ed 55 sxs. WOC. Reduced hole to s TD 5438'. s 4-1/2" 11.6 S95/ 7.5', Bottom mo % D65, .3% D167, 10 sxs. <u>3:00 AM 3/23/01</u> jest of my knowled	h wellbore diagram e. Waiting on rotar 1.71') casing set at d with 400 sxs 35:65 4.8). Notified Phil Hawki 11" and resumed of 11" and resumed of P110 SB (2532.32'); rker 4214.21', Top n 2% D46, .1% D13 (s	of proposed completion y tool. 900'. 3:6 C + 2% CaCl2 + hs of OCD of drilling. 70 jts 4-1/2" \$95/110 harker 2921.41'. yld 1.42, wt 13.0). PD	
 Describe proposed or complet of starting any proposed work) or recompilation. 2/6-9/01 – '21/01 – Spud 1:00 PM with 20'' '5/01 – Resumed drilling at 6:00 '7/01 – Reached TD of 14-3/4'' lexas Pattern Notched guide she #/sx polyseal (yld 1.99, wt 12.8) D at 3:15 AM 3/8/01. Bumped porations 5:10 PM 3/7/01. '8/01 – Drilled out plug and cer '21/01 – Reached TD of 5450' c '22/01 – Ran 131 jts 4-1/2'' casi V (2918.4'). Set Regular guide emented with 705 sxs Pecos Vo 9:45 PM. Bump plug to 1650 potified Phil Hawkins of OCD be). SEE RULE 1103. Fo Build location. hole. Set 40' of 16" of AM, 14-3/4" hole. No hole 4:00 PM. Ran 20 oe set at 900'. Insert f). Tailed in with 200 sx: plug to 544 psi, held C ment at 9:15 PM. WO at 1:00 AM. Logging v ng set at 5450' as follo e shoe at 5450' r, Float of alley Lites, 4 pps D42, psi for 4 mins., held OK fore running casing. Fi	or Multiple Co conductor, co ptified Phil Ha joints of 11-3, loat set at 85 s C + 2%CaC DK. Circulate C 18 hours. F well. Loggers collar at 540 1 pps D44, .2° Circulated Released rig	ompletions: Attac cement to surfac awkins of OCD . (/4" 42# H-40 (91 54.33', Cemente Cl2 (yld 1.32, wt 1 ed 55 sxs. WOC. Reduced hole to s TD 5438'. s 4-1/2" 11.6 S95/ 7.5', Bottom mo % D65, .3% D167, 10 sxs. <u>3:00 AM 3/23/01</u> jest of my knowled	h wellbore diagram e. Waiting on rotar 1.71') casing set at d with 400 sxs 35:65 4.8). Notified Phil Hawki 11" and resumed of 11" and resumed of P110 SB (2532.32'); rker 4214.21', Top n 2% D46, .1% D13 (s	of proposed completion y tool. 900'. 3:6 C + 2% CaCl2 + hs of OCD of drilling. 70 jts 4-1/2" \$95/110 harker 2921.41'.	
 2. Describe proposed or complete of starting any proposed work) or recompilation. 2/6-9/01 – 21/01 – Spud 1:00 PM with 20" 25/01 – Resumed drilling at 6:00 27/01 – Reached TD of 14-3/4" fexas Pattern Notched guide she #/sx polyseal (yld 1.99, wt 12.8) D at 3:15 AM 3/8/01. Bumped for the start of the st). SEE RULE 1103. Fo Build location. hole. Set 40' of 16" of 0 AM, 14-3/4" hole. No hole 4:00 PM. Ran 20 oe set at 900'. Insert f). Tailed in with 200 sx: plug to 544 psi, held C ment at 9:15 PM. WO at 1:00 AM. Logging v ng set at 5450' as follo e shoe at 5450' as follo e shoe at 5450', Float of alley Lites, 4 pps D42, osi for 4 mins., held OK fore running casing. Fin above is true and com	or Multiple Co conductor, co ptified Phil Ho joints of 11-3 loat set at 85 s C + 2%CaC DK. Circulate C 18 hours. F well. Loggers ows: 61 joints collar at 540 1 pps D44, .2 Circulated Released rig s aplete to the b	ompletions: Attac cement to surfac awkins of OCD . (/4" 42# H-40 (91 54.33', Cemente Cl2 (yld 1.32, wt 1 ed 55 sxs. WOC. Reduced hole to s TD 5438'. s 4-1/2" 11.6 S95/ 7.5', Bottom mo % D65, .3% D167, 10 sxs. <u>3:00 AM 3/23/01</u> jest of my knowled	h wellbore diagram (e. Waiting on rotar (1.71') casing set at (a with 400 sxs 35:65 (4.8). Notified Phil Hawkin (11'' and resumed (P110 SB (2532.32'); rker 4214.21', Top n (.2% D46, .1% D13 (dge and belief.	of proposed completion y tool. 900'. 3:6 C + 2% CaCl2 + hs of OCD of drilling. 70 jts 4-1/2" S95/110 harker 2921.41'. yld 1.42, wt 13.0). PD TE August 14, 2001	
 Describe proposed or complet of starting any proposed work) or recompilation. 2/6-9/01 – 21/01 – Spud 1:00 PM with 20" 5/01 – Resumed drilling at 6:00 7/01 – Reached TD of 14-3/4" if exas Pattern Notched guide she #/sx polyseal (yld 1.99, wt 12.8) D at 3:15 AM 3/8/01. Bumped if perations 5:10 PM 3/7/01. 8/01 – Drilled out plug and cer 21/01 – Reached TD of 5450' co 22/01 – Ran 131 jts 4-1/2" casi V (2918.4') . Set Regular guide emented with 705 sxs Pecos Vo 9:45 PM. Bump plug to 1650 p otified Phil Hawkins of OCD be hereby certify that the information and the information is GNATURE). SEE RULE 1103. Fo Build location. hole. Set 40' of 16" of 0 AM, 14-3/4" hole. No hole 4:00 PM. Ran 20 oe set at 900'. Insert f). Tailed in with 200 sx: plug to 544 psi, held C ment at 9:15 PM. WO at 1:00 AM. Logging v ng set at 5450' as follo e shoe at 5450' as follo e shoe at 5450', Float of alley Lites, 4 pps D42, osi for 4 mins., held OK fore running casing. Fin above is true and com	or Multiple Co conductor, c otified Phil Ha joints of 11-3 loat set at 85 s C + 2%CaC DK. Circulate C 18 hours. F well. Loggers ows: 61 joints collar at 540 1 pps D44, .2° Circulated Released rig 3 plete to the b	ompletions: Attac cement to surfac awkins of OCD . (/4" 42# H-40 (91 54.33'. Cemente Cl2 (yld 1.32, wt 1 ed 55 sxs. WOC. Reduced hole to s TD 5438'. s 4-1/2" 11.6 S95/ (7.5', Bottom mc % D65, .3% D167, 10 sxs. <u>3:00 AM 3/23/01</u> est of my knowled Engineering	h wellbore diagram (e. Waiting on rotar (1.71') casing set at (a with 400 sxs 35:65 (4.8). Notified Phil Hawkin (11'' and resumed (P110 SB (2532.32'); rker 4214.21', Top n (.2% D46, .1% D13 (dge and belief.	of proposed completion y tool. 900'. 3:6 C + 2% CaCl2 + hs of OCD of drilling. 70 jts 4-1/2" \$95/110 harker 2921.41'. yld 1.42, wt 13.0). PD	
Describe proposed or complet of starting any proposed work) or recompilation. 2/6-9/01 – 21/01 – Spud 1:00 PM with 20" 5/01 – Resumed drilling at 6:00 7/01 – Reached TD of 14-3/4" if xas Pattern Notched guide sho #/sx polyseal (yld 1.99, wt 12.8) 0 at 3:15 AM 3/8/01. Bumped (berations 5:10 PM 3/7/01. 8/01 – Drilled out plug and cer 21/01 – Reached TD of 5450' c 22/01 – Ran 131 jts 4-1/2" casi V (2918.4') . Set Regular guide emented with 705 sxs Pecos Vo 9:45 PM. Bump plug to 1650 p otified Phil Hawkins of OCD be bereby certify that the information GNATURE). SEE RULE 1103. Fo Build location. hole. Set 40' of 16" of AM, 14-3/4" hole. No hole 4:00 PM. Ran 20 oe set at 900'. Insert f). Tailed in with 200 sx: plug to 544 psi, held C ment at 9:15 PM. WO at 1:00 AM. Logging v ng set at 5450' as follo e shoe at 5450', Float of alley Lites, 4 pps D42, osi for 4 mins., held OK fore running casing. Fin above is true and com	or Multiple Co conductor, co pified Phil Ha joints of 11-3 loat set at 85 s C + 2%CaC DK. Circulate C 18 hours. F well. Loggers bws: 61 joints collar at 540 1 pps D44, .2' Circulated Released rig plete to the b 	ompletions: Attack cement to surfact cankins of OCD. c/4" 42# H-40 (91 cankins of OCD. choice cankins of OCD. cankins of OCD. cankins of OCD. store cankins of OCD. store	h wellbore diagram (e. Waiting on rotar (1.71') casing set at (a with 400 sxs 35:65 (4.8). Notified Phil Hawkin (11'' and resumed (P110 SB (2532.32'); rker 4214.21', Top n (.2% D46, .1% D13 (dge and belief.	of proposed completion y tool. 900'. 3:6 C + 2% CaCl2 + hs of OCD of drilling. 70 jts 4-1/2" \$95/110 harker 2921.41'. yld 1.42, wt 13.0). PD TE <u>August 14, 2001</u> No. 505-748-1471	
 Describe proposed or completed of starting any proposed work) or recompilation. 2/6-9/01 – 21/01 – Spud 1:00 PM with 20" 5/01 – Resumed drilling at 6:00 7/01 – Reached TD of 14-3/4" fixas Pattern Notched guide she #/sx polyseal (yld 1.99, wt 12.8) Dat 3:15 AM 3/8/01. Bumped (portations 5:10 PM 3/7/01. 8/01 – Drilled out plug and cer 21/01 – Reached TD of 5450' cor 22/01 – Ran 131 jts 4-1/2" casis V (2918.4'). Set Regular guide emented with 705 sxs Pecos V cor 9:45 PM. Bump plug to 1650 potified Phil Hawkins of OCD between the properties of the properties). SEE RULE 1103. Fo Build location. hole. Set 40' of 16" of 0 AM, 14-3/4" hole. No hole 4:00 PM. Ran 20 oe set at 900'. Insert f). Tailed in with 200 sx: plug to 544 psi, held C ment at 9:15 PM. WO at 1:00 AM. Logging v ng set at 5450' as follo e shoe at 5450' as follo e shoe at 5450', Float of alley Lites, 4 pps D42, osi for 4 mins., held OK fore running casing. Fin above is true and com	or Multiple Co conductor, co pified Phil Ha joints of 11-3 loat set at 85 s C + 2%CaC DK. Circulate C 18 hours. F well. Loggers bws: 61 joints collar at 540 1 pps D44, .2' Circulated Released rig plete to the b 	ompletions: Attack cement to surfact cankins of OCD. c/4" 42# H-40 (91 cankins of OCD. choice cankins of OCD. cankins of OCD. cankins of OCD. store cankins of OCD. store	h wellbore diagram (e. Waiting on rotar (1.71') casing set at (a with 400 sxs 35:65 (4.8). Notified Phil Hawkin (11'' and resumed (P110 SB (2532.32'); rker 4214.21', Top n (.2% D46, .1% D13 (dge and belief.	of proposed completion y tool. 900'. 3:6 C + 2% CaCl2 + hs of OCD of drilling. 70 jts 4-1/2" S95/110 harker 2921.41'. yld 1.42, wt 13.0). PD	