Submit 3 Copies to Appropriate District Office

DISTRICT I

DISTRICT II

DISTRICT III

1625 N. French Dr., Hobbs, NM 88240

811 S. First Street, Artesia, NM 88210

1000 Rio Bzazos Rd., Aztec, NM 87410

Energy, Mineral

SUNDRY NOTICES AND REPORTS ON WELLS

State of New Mexico d Natural Resources Department CISK

Form C-103 Ravised March 25, 1999

## OIL CONSERVATION DIVISION

2040 South Pacheco Santa Fe, New Mexico 87505

WELL API NO. 30-005-63342  5. Indicata Type of Lease  STATE X FEE  6. State Oil & Gas Lease No. L-5349  7. Lease Name or Unit Agreement Name  STATE S.E.  RECEIVED  OCD ARTESIA		`	A/				
STATE X FEE  6. State Oil & Gas Lease No. L-5349  7. Lease Name or Unit Agreement Name  STATE S.E.  RECEIVED  OCD ARTESIA			2				
T. Lease Name or Unit Agreement Name  STATE S.E.  RECEIVED  OCD ARTESIA	5	. Indicate Type of Lease	STA	ATE	X	FEE	
STATE S.E. RECEIVED 3	6		). 	د دوست ر	510.7		
B. Well No. ARTESIA A	7	. Lease Name or Unit Agu	ement Narp		f		
1 32		STATE S.E.	1001	RE	CEIVI	ED	\$ 500 p
	8		1,5 1,5 1,2 1,2		· ART.	ESIA	25/
9. Pool Name of Wildost FOOR RANCH PRE-PERMIAN			PRE-P	ERMI	AN_:	<u> </u>	57 2
660 Feet From The WEST Line		660	Feet From	The	_	WEST	Lirue
EAST NMPM CHAVES County	EAS	т Т	4	CHA	VES_	Count	y

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)					7. Lease Name or	: Unit Aguement	Narpa 2		
I. Type of Weil: OIL GAS WELL WELL	X	OTHER			STATE	S.E.	RECE!	VED Tesia	- 131 - 131 - 131
Name of Operator  ELK OIL	COMPANY /				9. Pool Name o	Wildost	2		<u> </u>
3. Address of Operator POST C	FFICE BOX 310	, ROSWELL	NEW MEXICO	88202-0310	4		E-PERMIAN	<u> </u>	
4 Well Location Unit Letter M	: 880	Feet From The		Line and	66	O Feet	From The	WEST	Line
Section 23	Township	9 SOUTH	now whether DF, RKB, R	Range 26 E	AST	NMPM	<u>CHAVES</u>	County	
			3786' GR			Las Data			
11. NOTICE O	eport, or Oti SUBSEQU	ner Data ENT REP	ORT OF:						
PERFORM REMEDIAL WORK	PLUG	AND ABANDON		REMEDIAL WORK		A	LTERING CASING		
TEMPORARILY ABANDON	CHAN	IGE PLANS		COMMENCE DRILLI	ING OPNS.	F	LUG AND ABANDO	NMENT	
pull or alter casing	MULTI	PLE COMPLETION		CASING TEST AND	EMENTJOB				
OTHER:				OTHER:					X
12. Describe Proposed or Completed SEE RULE 1103 For Multiple APRIL 3 THRU APR							345 CIRCUL	ATED HO	OLE

WITH 7% KCL WATER. PULL OUT OF HOLE WITH TUBING AND BIT. RIG UP SCHLUMBERGER. RUN TIE-IN LOG, PERFORATE PRE-PERMIAN AT 6056'-59', 6062'-70', 6072'-74', 6076'-87', 2 SHOTS/FOOT. RIG DOWN SCHLUMBERGER. RUN IN HOLE WITH TUBING AND PACKER, SET PACKER AT 5978'. ACIDIZE WITH 3000 GALLONS. SWAB WELL IN. TESTED AT 800,000/DAY ON A 12/64" CHOKE, TP 800#. APRIL 9 THRU APRIL 11, 2001: RIG UP JSI TO SET PROFILE PLUG IN PACKER. GET OFF THE ON/OFF TOOL. TEST PACKER TO 2000#, HELD OKAY. CIRCULATE HOLE WITH 7% KCL. PULL OUT OF HOLE WITH TUBING. RIG UP SCHLUMBERGER, PERFORATE 5787'-5794', 4 HOLES PER FOOT. RIG DOWN SCHLUMBERGER. RUN IN HOLE WITH TUBING, BRIDGE PLUG AND PACKER. SET BP AT 6020', PACKER AT 5670'. ACIDIZE WITH 1500 GALLONS 15% HCL. SWAB WELL IN. TESTED AT 2000 / DAY ON A 12/64" CHOKE, TP 1700#.

		-						
YPE OR PRINT	NAME	JOSEPH J. KELLY						_
		IOCEDUL KELLY	,		TELEPHONE NO.		505-623-3190	
GNATURE			TITLE	FILGIDLINI				
	7			PRESIDENT		DATE	4/16/01	
hereby certify that	the information shows is	true and complete to the best of m	th Wicomedia Tra service					
RIG UP J	SI, PULL OUT	PROFILE PLUG. F	av land avide days and helpef	E WELL ON PRODUCT				_
	,	DROCH E DUIG E	DED TO PLACE	E WELL ON PRODUCT	TION.			
KILL WEL	L. PULL OUT	OF HOLE WITH TU	IBING AND BP.	RUN IN HOLE WITH I	TUBING, SET IN PACKER	A1 00		
ACIDIZE	WITH 1500 GF	ALLONS 13% HOL.		DUNE INTERIOR E MAIITHE	TUDING SET IN BACKER	ΔT 59	78'	

(This space for State Use)

original signed by tim W. Gilm nstrict a supervisor

HW 93 ZW

APPROVED BY CONDITIONS OF APPROVAL, IF ANY: