G. J. D. Coming To Augmonpieto District	St CNI	Mania		Form C-103
Submit 3 Copies To Appropriate District Office	State of New Mexico		Revised March 25, 1999	
District I	Energy, Minerals and Natural Resources		WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240 District II			30-005-63351	
811 South First, Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of	of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		·	X FEE
District IV	Santa Fe, NM 87505		6. State Oil & G	as Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		LG-0564		
87505 SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or	Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				-
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-1(1) FOR SUCH			Pueblo AXJ State Com	
PROPOSALS.)  1. Type of Well:				
Oil Well Gas Well X	Other	139 115		
2. Name of Operator		4 32	7. Well No.	
Yates Petroleum Corpor	ation	A COLUMN	#1	
3. Address of Operator		197 Con 6	8. Pool name or	
	ia, NM 88210 💎 📆	ECEIVED	Pecos Slop	oe Abo
	$\sigma_{i_{\lambda_{i_{i}}}}$	ARTIC		
4. Well Location	· <u>·</u>	150/A 20/		
100	o o o o o o	11 13000	C A. C 41	oct line
Unit Letter K: 198	feet from the South	- line and 1780	feet from the	esi ine
	m 41: <b>F</b> \$ Dec	24E	NMPM Chave	S County
Section 3	Township <b>5S</b> Ran 10. Elevation (Show whether			es County
		722' GR	(C.)	
11 (1) 1. A			Papart or Other	Data
	ppropriate Box to Indicate	e Nature of Notice,	SEQUENT RE	DODT OF:
NOTICE OF IN	TENTION TO:	501	SSEQUENT RE	PURT UF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	] REMEDIAL WO	RK 🔲	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DF	RILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE	CASING TEST	AND	
T GEE GROVE TERMS	COMPLETION	CEMENT JOB		
OTHER:		OTHER: set pro	duction casing	X
Describe proposed or completed op	perations. (Clearly state all per	tinent details, and give	pertinent dates, incl	uding estimated date of
starting any proposed work). SEE I	RULE 1103. For Multiple Co::	npletions: Attach well	lbore diagram of prop	oosed completion or
recompilation.				
6/14/01 - Ran 94 jts. (4113.42')	) casing set at 4114' as fo	lows:		
29 jts 4-1/2" 10.5# SB (1221.19				
65 jts. 4-1/2" 10.5# MV (2892.2	23')			
Float shoe set at 4114'. Float	collar set at 4071.22'.			
Cemented with 325 sxs Pecos	Valley Lite + 3 pps salt +	4 pps Gilsonite + .1	% dispersant + .4 $%$	% Fluid loss + .2%
Antifoam (yld 1.45, wt13). PD	at 10:00 PM. Bumped pl.	ug to 1249 psi for 4	mins., held OK.	
Notified Phil Hawkins, Artesia	OCD before running pipe			
Rig released at 2:00 AM 6/15/	01.			
I hereby certify that the information	above is true and complete to	the best of my knowle	edge and belief.	
SIGNATURE Sugar Chi	<u> </u>	e Paratarana	.Toobuloien D	ATE October 5 2001
SIGNATURE Aldin Uni	TITI	E <u>Engineering</u>	i lechnician Di	ATE OCIODEI 5, 2001
Type or print name Susan Herpin Telephone No. 505-748-1471				
	RIGINAL SIGNED BY TIM	w. Gum		OCT 16 200
	DISTRICT II SUPERVISOR		فالمعاو والمساعد ومهم	DATE
APPPROVED BY Conditions of approval, if any:	TIT	LE		DATE