			CISF	
Submit 3 Copies To Appropriate District Office <u>District 1</u> 1625 N. French Dr., Hobbs, NM 88240 <u>District 11</u> 811 South First, Artesia, NM 88210	hice Energy, Minerals and Natural Resources strict I 25 N. French Dr., Hobbs, NM 88240 strict II OUL CONSERVATION DIVISION		ELL API NO. -005-63418	Form C-103 Revised March 25, 1999
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 1220 South St. Francis Dr. District IV Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM Santa Fe, NM 87505			 5. Indicate Type of Lease STATE X FEE 6. State Oil & Gas Lease No. LG-0563 	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well:			7. Lease Name or Unit Agreement Name: Smernoff NL St.	
Oil Well Gas Well X Other 2. Name of Operator			Well No.	
Yates Petroleum Corporation			7. Well No. #9	
3. Address of Operator 105 S. 4 th Street Artesia, NM 88210			 Pool name or Wildcat Pecos Slope Abo 	
4. Well Location				
Unit Letter <u>H</u> : 1980 feet from the <u>North</u> line and <u>660</u> feet from the <u>East</u> line				
Section 2 Township 5S Range 24E NMPM Chaves County 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 1000000000000000000000000000000000000				
3938' GR				
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUE			QUENT REP	PORT OF:
	PLUG AND ABANDON			
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPNS.		
PULL OR ALTER CASING		CASING TEST AND CEMENT JOB		
OTHER: OTHER: Set pro				
Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 9/28/01 – Reached TD of 4206' at 7:30 AM. 9/29/01 – Run open hole logs. Logger's TD 4199'. 9/30/01 – Ran 97 joints (4208.07') casing set at 4206' as follows: 33 joints 4-1/2'' 10.5# J-55 SB (1362.93') 64 joints 4-1/2'' 10.5# J-55 MV (2845.14') Float shoe set at 4206'. Float collar set at 4162.95'. Bottom marker set at 3584.28'. Top marker set at 2843.07'. Cemented with 320 sxs Pecos Valley Lite + 4% D42 + 1 pps D44 + .2% D65 + .3% D167 + .2% D46 (yld 1.42, wt 13.0). Plug down at 7:30 AM. Bumped plug to 1180 psi for 4 mins, held OK. Notified Mike Bratcher with Artesia OCD before starting pipe. Rig released at 12:00 Noon 9/30/01.				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE AND CHIPPED TITLE Engineering Technician DATE December 18, 2001				
Type or print name Susan Herpin Telephone No. 505-748-1471				
(This space for State use)				
APPPROVED BY Conditions of approval, if any:	TITLE_			_DATE