			<b>~\5</b>	Kn)			
Submit 3 Copies To Appropriate District	State of New Mexico			Form C-103			
Office <u>District I</u>	Energy, Minerals and Natural Resources			,		Revised March 25, 1999	
1625 N. French Dr., Hobbs, NM 88240 District II				WELL API NO.			
811 South First, Artesia, NM 88210	OIL CONSERVATION DIVISION			<b>30-005-63420</b> 5. Indicate Type of Lease			
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.				STATE X FEE		
District IV	Santa Fe, NM 87505			6. State Oil & Gas Lease No.			
1220 S. St. Francis Dr., Santa Fe, NM 87505					3		
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DELIZEN OR FLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)  1. Type of Well:  Oil Well Gas Well X Other				7. Lease Name or Unit Agreement Name:  Smernoff NL State  7. Well No.			
2. Name of Operator	ention /			7. Well 1 # <b>7</b>	No.		
3. Address of Operator				8. Pool name or Wildcat			
105 S. 4th Street Artesia, NM 88210 and APRISTA II				Pecos Slope Abo			
4. Well Location							
Unit Letter F: 198	on the North	i <u>h</u> line	and <u>1500</u> fee	et from the _	West	line	
Section 2	Township <b>5S</b>	Range	24E	NMPM	Chav	es County	
5001011	10. Elevation (Show	.cther D.			Citat	es county	
200 200 200 200 200 200 200 200 200 200		3965	GR				
11. Check A	ppropriate Box to Ind	icate N	ature of Notice,	Report or (	Other I	Data	
NOTICE OF IN	TENTION TO:		SUE	SEQUEN	T REF	PORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WOR	RK		ALTERING CASING [	
TEMPORARILY ABANDON	CHANGE PLANS		ABANDONMENT			PLUG AND ABANDONMENT	
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST A CEMENT JOB	ND			
					_ <del></del>		
OTHER:			OTHER: set and				
Describe proposed or completed op starting any proposed work). SEE Frecompilation.  12/14/01— Moved in and rigge 12/17/01—TIH with bit and scroperforate Abo 3556-3562', 357 12/18/01—Frac Abo perfs 355 250,000# 16/30 Brady sand. P 12/20/01—TIH with 2-3/8" tubin 12/21/01—Release all equipments	ed to pulling unit.  aper. Tagged PBTD at 2-35841, 3600-3604137 (6-38301 with 111,000 gumped 2000 gals 7.5% ng. Bottom of tubing	: 4030'. : 4030'. : 7:7-3720 gals 650 :: IC HC :::dt 3554	TIH with CBL. TO 6', and 3816-383 N2 foamed 35 L ahead of frac ', seating nipple	Dore diagram  OC 3080'.  BO', total of # gelled 7%	of proposed of pro	es, .42".	
I hereby certify that the information	•		-	-			
SIGNATURE Avon Hey	2 TITU	Er_	gineering Tec	<u>hnician</u> [	)ATE <u></u>	ecember 31, 2001	
Type or print name Susan Herpin Telephone No. 505-748-1471							
(This space for State was)	ORIGINAL SIGNED BY	TIM W	. GUM			1 0 0000	
APPPROVED BY	DISTRICT II SUPERVIS	OR .				JAN 1 0 2822 DATE	
Conditions of approval, if any:		( 1 L L L			**	_DATE	