	<del>-</del>		~ C15 F.		
Submit 3 Copies To Appropriate District	State of New	Mexico	Shot I	Form C-103	
Office District I	Energy, Minerals and Natural Resources			Revised March 25, 1999	
1625 N. French Dr., Hobbs, NM 88240	625 N. French Dr., Hobbs, NM 88240		WELL API NO.		
811 South First, Artesia, NM 88210	histrict II 11 South First, Artesia, NM 88210 OIL CONSERVATION DIVISION		30-005-63432		
District III	1220 South St. Francis Dr.		5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87410 Santa Fe, NM 87505		STATE 6. State Oil & C	FEE X	
1220 S. St. Francis Dr., Santa Fe, NM 87505			o. State on & C	las Lease IVO.	
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)  1. Type of Well:			7. Lease Name or Unit Agreement Name:  Sacra SA		
Oil Well Gas Well X	Other	<b>★</b>			
2. Name of Operator	1	FHB 2002	7. Well No.		
Yates Petroleum Corpor	ration /	RECEIVED &	#21		
3. Address of Operator		APTECIA 4	8. Pool name or	* ** *	
105 S. 4 <sup>th</sup> Street Artes	ia, NM 88210	OCD ARTESIA OF	Cottonwo	od Ranch Penn	
4. Well Location					
Unit Letter <u>L: 19</u>	feet from the <u>South</u>	line and <u>660</u>	_ feet from the _ V	Vest line	
Section 35	Township 6S Range	e <b>25E</b> NN	IPM Chaves	County	
	10. Elevation (Show whether				
3699' GR					
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF IN	TENTION TO:	SUB	SEQUENT RE	PORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	] REMEDIAL WOR	К	ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	] COMMENCE DRI	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT		
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AI CEMENT JOB	ND		
OTHER:		OTHER set and	coment production o		
	perations (Clearly state all ner		cement production c		
Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.					
2/11/01 – Reached TD at 5325	5' at 5:30 AM.				
Run open hole logs. Logger's TD 5327'.					
2/13/02 – Ran 127 joints (5331.74') casing set at 5325' as follows:					
41 joints 5-1/2" 15.5# J-55 SB (1739.16')					
48 joints 5-1/2" 15.5# J-55 MV (2029.24') 13 joints 5-1/2" 15.5# J-55 SB (532.70')					
25 joints 5-1/2" 15.5# J-55 MV (1030.64')					
Float shoe set at 5325'. Float collar set at 5279.44'. Cemented with 1752 sxs Pecos Valley Lite with 1 pps D44 + 4					
pps D24 + .2% D65 + .3% D167 +.08% D13 (yld 1.42, wt 13). PD at 12:30 PM. Bumped plug to 1830 psi, held OK.					
Notified Van Barton with NMOCD of operations.					
Rig released at 4:30 PM 2/13/02.					
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
SIGNATURE MALL	puTITLE _	Engineering Tech		ebruary 25, 2002	
Type or print name Susan Her	pin		Telephone	No. <b>505-748-1471</b>	
(This space for State use)				MAD _ 1 2003	
APPPROVED BY Lecod Conditions of approval, if any:	Caly BA TITI	.E		DATE	