

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

WELL API NO.

30-005-63446

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

LG-2622

7. Lease Name or Unit Agreement Name:

Harvest ABR State

7. Well No.

#3

8. Pool name or Wildcat

Wildcat Basement

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☒ Other ☐

2. Name of Operator

Yates Petroleum Corporation

3. Address of Operator

105 S. 4th Street Artesia, NM 88210

4. Well Location

Unit Letter J : 1980 feet from the South line and 1980 feet from the East line

Section 36 Township 9S Range 24E NMPM Chaves County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

3558' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETION ☐

OTHER:

☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Set production casing

☒

Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

4/30/02 - TD 5025'. TIH with logging tools. Tools stuck. Fish logging tools.

5/2/02 - Decision to continue drilling. Drilling formation at 4:00 AM. Reached TD at 5100' at 2:15 PM.

5/3/02 - RIH with logging tools. Could not go past 4180'. Rig down loggers. Wash and ream to TD.

5/4/02 - Run open hole logs. Logs on bottom at 3:30 AM.

Ran 124 joints (5111.2') casing set at 5100' as follows:

41 joints 4-1/2" 11.6# N-80 SB (1656.08')

83 joints 4-1/2" 11.6# N-80 MV (3455.12')

Float shoe set at 5100'. Float collar set at 5059.97'. Bottom marker set at 4100.4'.

Cemented with 300 sxs Pecos Valley Lite + 3 pps D44 + .1% D65 + .4% D167 + .2% D46 (yld 1.45, wt 13).

PD at 11:30 PM 5/4/02. Bumped plug to 1630#, held OK.

Notified Jerry Guy with NMOCD of operations.

5/5/02 - Rig released at 3:30 AM.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Susan Herpin TITLE Engineering Technician DATE May 9, 2002

Type or print name Susan Herpin

Telephone No. 505-748-1471

(This space for State use)

ORIGINAL SIGNED BY TIM W. GUM  
DISTRICT II SUPERVISOR

APPROVED BY [Signature] TITLE

DATE MAY 10 2002

Conditions of approval, if any: